

Judicial Council of California · Administrative Office of the Courts

455 Golden Gate Avenue · San Francisco, California 94102-3688 www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

For business meeting on: June 28, 2013

Title Agenda Item Type
Court Facilities: Trial Court Facility Information Item

Modification Quarterly Activity Report:

Quarter 3, Fiscal Year 2012–2013 Effective Date June 28, 2013

Rules, Forms, Standards, or Statutes Affected

None Date of Report May 28, 2013

Recommended by

Trial Court Facility Modifications Contact

Advisory Committee Patrick McGrath, Facility Operations Manager

Hon. David Edwin Power, Chair 916-643-8051 phone

patrick.mcgrath@jud.ca.gov

Executive Summary

The Judicial Council's Trial Court Facility Modifications Advisory Committee (TCFMAC) has completed its facility modification funding for the third quarter of fiscal year 2012–2013. In compliance with the Trial Court Facility Modifications Policy, adopted by the Judicial Council on July 27, 2012, the TCFMAC is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2012–2013* as information for the council.

Recommendation

The Trial Court Facility Modification Advisory Committee recommends that the Judicial Council accept the *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2012–2013* as an information-only item.

Previous Council Action

On July 27, 2012, the Judicial Council adopted the Trial Court Facility Modifications Policy.

Rationale for Recommendation

The recommendation to approve this report is based on the fact that the TCFMAC has reviewed all projects in detail in accordance with the current policy.

During quarter 3, the TCFMAC reviewed and approved a total of 245 facility modifications for a total projected project cost of \$9,895,836. The Administrative Office of the Courts (AOC) share of these projects totals \$9,380,735. The projects are limited to Priority 1 emergency projects and Priority 2 critical needs projects. Please see Attachment 1 for the detailed list of approved projects.

Comments, Alternatives Considered, and Policy Implications

Because of the limited nature of the Facility Modification Budget, we anticipate continuing to limit our expenditures to Prior 1 emergency projects and Priority 2 critical need projects for the final quarter of this fiscal year.

The advisory committee met during a groundbreaking two-day session on January 31 and February 1 to begin discussion on the update charge of the advisory committee to:

- Provide ongoing oversight of policy issues, business practices, and budget monitoring
 and control for all facility-related issues in existing branch facilities. This includes all
 areas for which the Office of Real Estate and Facilities Management (REFM) is
 responsible, including operations and maintenance (O&M), facility modifications (FM),
 non-capital-related real estate transactions, energy management, and environmental
 management and sustainability.
- Authorize funding of facility modifications in accordance with the Judicial Council's policy.
- Provide recommendations to the Judicial Council on funding-related issues, including funding requirements for both O&M and FM.
- Support the Court Facilities Working Group in the development of the Judicial Branch Capital Program, including providing input to design standards, prioritization of capital projects, and methods to reduce construction cost without affecting long-term operations and maintenance cost.
- Advise on issues related to the advisory committee's charge as requested by the Chief Justice, the Judicial Council, or the Administrative Director of the Courts. These may include issues related to funding, AOC staffing support, development and oversight of contracts, and policies and procedures related to the trial court facilities.
- Provide quarterly and annual reports on the facility modification program in accordance with the Judicial Council's policy.

Discussions included presentations by the AOC Office of Real Estate and Facilities Management on the overall FM and O&M budget status and cycles, an overview of the history of the development of the facilities program, and the transition of facilities and operational maintenance responsibilities from the counties to the state. The REFM regional managers

discussed operational protocols and day-to-day decisions that are made by court, AOC, and service provider personnel. The Facility Operations Manager discussed the various reporting and contractual key performance indicators that the AOC uses to measure program success and service provider performance.

The advisory committee discussed potential strategies and approaches toward meeting the intent and overall goals approved by the Judicial Council and embodied within the charge.

At the March 10 meeting, the advisory committee met via phone conference. In addition to the standard facility modification funding discussions, the advisory committee heard reports on critical and extremely expensive emergency cleanup efforts at the Foltz Criminal Justice Center and Compton Courthouse. The Foltz facility was subject to a major flood that affected multiple floors. The flood included the abatement of asbestos containing materials and resulted in significant costs to clean this hazardous material. Additionally, a diesel fuel leak caused soil contamination. The cleanup of this environmental hazard also incurred significant expense.

Funding decisions were based on the prioritization and ranking methodologies under the aegis of the Trial Court Facility Modifications Policy. Delaying TCFMAC approval of these projects would, for Priority 1 emergencies, cause continued court closures and operational failures within the branch. Delaying approval of Priority 2 critical need projects would create undue risk to continued court operations.

We anticipate submitting the *Trial Court Facility Modification Quarterly Activity Report: Quarter 4, Fiscal Year 2012–2013* in August 2013.

Attachments

1. Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2012–2013

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	знокт тпсе	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
١.	51.1 0010100	51.5	Main St.	00.44	_				
1	FM-0010468	El Dorado	Courthouse Hall of Justice	09-A1	2	HVAC - Gas Fired Boiler - Remove and replace 34 year old non-compliant boiler due to AQMD regulations. Heating Hot Water Boiler #1, 375,000 BTU Elevator - renovate 2 elevators and controls and install monitoring system - court operations are impacted by having court staff, deputies, and the public having	\$ 30,000	\$ 30,000	100
2	FM-0022152	Santa Clara	(West)	43-A2	2	impared use of the elevators and controls and histail monitoring system - court operations are impacted by having court start, deputies, and the point having impared use of the elevators	\$474,084	\$474,084	100.00
						Grounds and Parking Lot - Restore Parking Lot - Reseal-Restripe 51,300 sq ft - Potholes, spalling-alligatoring and cracks throughout the entire lot parking lot have	7,	********	
3	FM-0028703	Amador	Begovich Building	03-C1	2	created concerns. This project has been deferred for two years and has escalated to a point to justify a P 2 priority.	\$ 145,000	\$ 145,000	100
			Kearny Mesa Traffic						
4	FM-0031641	San Diego	Court	37-C1	2	(-)	\$ 319,000	\$ 319,000	100
						Exterior Shell - Exterior Stucco- Stage scaffolding and protective equipment on the south side and front entrance of the building. Perform destructive testing to			
5	FM-0034475	Napa	Historical Courthouse	28-B1	2	determine cause of failure of stucco finish. Develop plan for the re-installation of new stucco. Prepare plans and elevations for planning and building department review. Remove and replace affected areas of damaged stucco.	\$ 200,000	\$ 187,980	93.99
- 3	FIVI-0034473	Мара	Courtilouse	20-D1		review. Remove and replace affected areas of damaged stucco.	\$ 200,000	\$ 167,960	95.99
6	FM-0040448	Los Angeles	Metropolitan Courthouse	19-T1	2	Security - Emergency exit - Remove and replace door hardware and security controls on 10 doors throughout the building, New monitoring door controls, conduits, and wiring required for this installation. Installation of conduits and wiring will be completed in an environment where ACM's are known to be present. Connect monitored doors to panel in sheriff's office. The existing doors have been breached, creating a security issue.	\$ 45,000	\$ 45,000	100
l _			South Placer Justice		_	Electrical - Phase II Lighting - Remove and replace 80 lamps with a serviceable lamp and ballast - AOC approved and authorized project (phase II of IV). 60% of			
7	FM-0044053	Placer	Center	31-H1	2	Phase II lighting is impacted at this time.	\$ 121,000	\$ 121,000	100
			Control						
8	FM-0045782	Los Angeles	Central Arraignment Court	10-111	2	HVAC - Remove and replace the failed and leaking hot water coils. This is needed to return HVAC to required operating condition.	\$ 44,000	\$ 44,000	100
- 0	FIVI-0043782	LOS Aligeles	Compton	15-01		Fire Life Safety - Replace defective non compliant fire alarm control panel, wire and devices throughout 14 story building. System fails to meet fire inspection	3 44,000	3 44,000	100
9	FM-0045786	Los Angeles	Courthouse	19-AG1	2		\$ 34,750	\$ 22,980	66.13
	1111 00 15700	2007 mgcres	Courtilouse	15 7.01	_	HVAC - Condensate Pump - Replace existing condensate pump with Bell & Gossett Domestic Series VLR Simplex Units with existing connection - Current system	\$ 3.,730	Ç 22,500	00:13
			Wakefield Taylor			has failed and no longer in operation. Causing leak on floor in mechanical room as well. May lead to HVAC system failure. This will be more of a problem as days			
10	FM-0049422	Contra Costa	Courthouse	07-A2	2	get colder.	\$ 55,198	\$ 55,198	100
			Torrance			HVAC - Failed HVAC Unit - Remove and replace AHU #9 which has failed with a 9,000 CFM unit and install outside air dampers for efficiency, connect to control			
11	FM-0049631	Los Angeles	Courthouse	19-C1	2	wiring. Old unit and new unit must be dismantled in order to gain access to the room then re-assembled.	\$ 74,508	\$ 67,378	90.43
			Pasadena			HVAC - Replace two (2) 400 Ton cooling towers including VFDs, 8" piping, four (4) isolation valves, rental towers, new steel roof mounts, engineering and permits.			
12	FM-0049850	Los Angeles	Courthouse	19-J1	2	Towers currently are leaning due to rust conditions. Requires roof replacement under towers.	\$ 658,000	\$ 658,000	100
13	FM-0049920	Los Angeles	San Fernando Courthouse	19-AC1	2	1	\$ 24,941	\$ 24,941	100
						Front Door - Install new door closer on the main door. The front entrance door does not shut all the way. Latch is not automatically latching when the door closes.			
14	FM-0049984	Amador	Begovich Building	03-C1	2	Entry Security is compromised.	\$ 2,566	\$ 2,566	100
15	FM-0049985	Contra Costa	Wakefield Taylor Courthouse	07-A2	2	Plumbing - Install 6 feet of 3/4" domestic water pipe between shut-off valves. Clean and remove containment wall. Install sheetrock wall 8' x 16' - ceiling 4' x 8' - match missing wood paneling 32' x 8' - wood chair rail 12" x 32'. Install sheetrock wall 4' x 4' Remediation work required to rebuild a corner of the courtroom that was torn down under SWO # 1256579, a P1 for water damage and mold. Electrical - Provide (1) 120 volt 20 AMP receptacle with (1) dedicated 20 AMP circuit and install a 2 inch conduit run only, from communication room just below	\$ 10,845	\$ 10,845	100
			Downey			courtroom for data cable run. Data lines and cabling will be installed by the court. This work is being performed due to the safety trip hazard electrical and data			I
16	FM-0049986	Los Angeles	Courthouse	19-AM1	2	lines crossing back to back workstations covered underneath a chair mat at the present time.	\$ 3,600	\$ 3,600	100
			Downey						
17	FM-0049989	Los Angeles	Courthouse	19-AM1	2	Holding Cell - Sally Port Entrance Gate Motor not functioning and needs to be replaced. Currently gate is in the open position and cannot close.	\$ 2,800	\$ 2,800	100
	51.4 00.55555	l	Stanley Mosk	40 1/1	_	HVAC - Disassemble the hot water (comfort heat) pump and remove and replace gaskets and seals and bring back to working condition. Pump was leaking due to			
18	FM-0049990	Los Angeles	Courthouse	19-K1	2	packing shaft seals. Work must be done to bring pump back to its original design functionality and to ensure hot water.	\$ 4,454	\$ 4,454	100
19	FM-0049992	Stanislaus	Modesto Main Courthouse	50-A1	2	Fire Protection - Install a new water flow switch on the basement riser and a new water flow bell on exterior of building - water flow bell has failed. Replacement is required by code	\$ 4,060	\$ 4,060	100
19	1 141-0045552	StarrisiaUS	Courtilouse	20-WI		Flood Damage - Courtroom D - Remove and replace the broken pipe connection at the sump pump, evacuate the water from the pit, extract flood water from the	4,060	4,060	100
			Traffic/Small Claims			carpeted areas of courtroom D, remove the baseboards from the courtroom walls, drill holes to allow for the walls to dry and set air movers and dehumidifiers to			
20	FM-0049993	San Mateo	Annex	41-A2	2	start the drying process. Emergency response.	\$ 2,748	\$ 2,748	100
						, 5,		_,, .0	

									Ą	
	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE O PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
21	FM-0049994	San Diego	County Courthouse	37-A1	2	HVAC - Remove and replace two mechanical seals from hot water heater #2. Currently the mechanical seals are leaking and we are losing chemicals. Replacement must be made to ensure proper system performance and to avoid further damage. There is no back up boiler feed pump for this boiler.	\$	2,301	\$ 2,301	100
22	FM-0049995	San Diego	County Courthouse	37-A1	2	Roof - Remove old / damaged mastic and replace with new, fill open laps & gouges in base flashings and pipe flashings. Re-tighten drain rings on every drain and re-caulk all open joints on the North tower, south tower and north annex building for the San Diego County Courthouse. Work must be performed to prevent additional leaks during rainy season and to bring roof back to original design functionality. HVAC - Replace leaking chill water pump seals, bearing, sleeve and gaskets. Water has started to slowly leak into the first floor Civil department. Plastic sheeting	\$	5,636	\$ 5,636	100
22	FN4 0040007	0	Mark leasting Courter	20.04	2	has been temporarily placed under pump to divert water to nearby drain. Ceiling has already sustained water damage and the public service window directly	,	2.000	ć 2.500	00.50
23	FM-0049997	Orange	West Justice Center Criminal Court	30-DI	2	under the leak has been closed, impacting Court operations.	Ş	3,969	\$ 3,599	90.68
24	FM-0049998	Napa	Building	28-A1	1	Exterior doors - Failed card reader system - Replace failed ACX Controller Board which controls card readers. Security access is compromised.	\$	10,000	\$ 10,000	100
25	FM-0049999	Los Angeles	San Pedro Courthouse	19-Z1	2	HVAC - Remove and replace failed pump located in the basement to increase water pressure in the building. Currently the toilets have a hard time flushing due to low water pressure. Work must be done to ensure proper pressure in the building and to avoid any further damages.	\$	4,681	\$ 4,681	100
26	FM-0050000	Lake	South Civic Center	17-B1	2	Electrical- Install 3 New Circuits - Currently all equipment within the courtroom is running off 1 circuit. Circuit is tripping causing Operational interruptions. This circuit powers the clerks desk via two separate power strips that are taped down in a path of travel. It also provide power to the break room	\$	8,188	\$ 8,188	100
27	FM-0050001	Los Angeles	Santa Monica Court Annex	19-AP3	2	Interior Finishes - Replace all damaged tile located on stairs and landings for the Annex building stairway and seal with a non-slip lacquer based sealant to prevent any further or future weather damage to the tile. Tiles are lose and cracked creating a tripping hazard to the public, tiles must be replaced and sealed to ensure no future work is required. Safety hazard.	\$	3,087	\$ 3,087	100
28	FM-0050002	Los Angeles	West Los Angeles Courthouse	19-AR1	1	Roof - Replace approximately 30ft x 30 ft of existing damaged roof rubberized membrane to stop the current leak that is traveling to Dept C Courtroom. Work must be performed under P1 to prevent further damage due to current rains and to ensure that the Courtroom is available for use.	\$	4,988	\$ 4,988	100
						Elevators - Remove and rebuild electronic drive from elevator no. 10 (Custody Elevator) to bring elevator back to working condition. Work was performed under				
		Los Angeles	North County Regional Center -		1	P1 emergency. Elevator stopped and did not operate, drive failed. Exterior Shell (Roof) - Prepare damaged roof areas and replace failing joints at the parapets, expansion joints and flashings throughout the roof. This work is	\$	4,570	\$ 4,570	100
		San Diego	Vista Center North County Regional Center - Department 36	37-F2	2	required to prevent future roof leaks. Roof - Restore areas of leaking roof - Remove all loose panel laps, apply primer to deck, apply liberal layer of white Enteramastic to seam areas extending 4" from seam onto panels, embed a layer of polyester fabric in the layer of White Enteramastic and apply final layer of white Enteramastic over polyester. Work is needed	\$	4,650	\$ 4,650	100
31	FM-0050006	San Diego	Trailer Civic Center	37-F6	2	to prevent additional roof leaks. Exterior Shell - Integrated pivot and door closer - Remove and replace the concrete embedded hinge pivot and closer on the exterior door at the loading dock. The	\$	2,741	\$ 2,741	100
32	FM-0050007	San Francisco	Courthouse Downey	38-A1	2	pivot on the man door hinge has deteriorated and the door is non-operational creating safety and security concerns.	\$	6,304	\$ 6,304	100
33	FM-0050013	Los Angeles	Courthouse	19-AM1	1	Fire Protection - Install two (2)failed Honeywell Power supplies for fire alarm panel and devices.	\$	5,030	\$ 5,030	100
34	FM-0050014	Los Angeles	Beverly Hills Courthouse	19-AQ1	1	Fire Protection - Replace (1) failed fire panel. Currently the fire panel is not outputting any alarms to the communicator creating a safety hazard. Work needs to be performed under P1 status.	\$	14,900	\$ 14,900	100
35	FM-0050015	Los Angeles	Pasadena Courthouse	19-J1	1	HVAC - Remove and replace 3 way chilled water actuator that broke off from the Air Handler. Work was performed under P1 emergency where the cooling valve snapped in half and no cool air was available to the entire first floor of the building.	\$	13,167	\$ 13,167	100
36	FM-0050017	Orange	North Justice Center	30-C1	2	Plumbing - Water Heater - Remove and replace the failed 85 Gallon Commercial Grade (Model BTL 400100), quick response, low emissions water heater and associated piping. Includes removal and disposal of the existing water heater. Phase III is without hot water impacting operations.	¢	13,407	\$ 12,108	90.31
	FM-0050017		West Justice Center		2	associated piping, includes removal and disposal or the existing water neater. Phase III is without not water impacting operations. HVAC - Cooling Tower - Replace rotting support beams with structural steel isolation beam supports. Currently, cooling tower sits 8 feet from the east edge of roo unsupported and unfastened by makeshift, rotted wooden supports. These supports do not reach the load bearing part of the foundation; it is primarily stabilized by plumbing lines in and out of the unit.		14,890	\$ 12,108	90.31
38		Riverside	Larson Justice Center	33-C1	2	Roof - Replace 57,000 Square feet of roof - Remove 57,000 Square feet of 3 ply tar and gravel roof leaving in place the 3" insulation layer below. Replace with a 50 mil. Single Ply PVC roof system over a trowel on cementious base layer, re-roof will include new parapet walls, mechanical curbs and roof jacks.	٥	630,331	\$ 509,370	80.81
39		Riverside	Indio Juvenile Court		2	Roof - Replace approximately 5,000 S.F. of roofing at the mechanical areas to stop leaking which has caused extensive damage to offices, ceiling and drywall.	\$	80,800	\$ 309,370	41.83
40	FM-0050023		Wakefield Taylor	07-A2	2	Exterior - Resurface and reseal front steps- Replace 160' of expansion material, reseal 2,500 SF of Stair Surfaces - Water leaking into file room and disrupting court	\$	14,092	\$ 14,092	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
41	FM-0050024	Kern	Delano/North Kern Court	15-D1	2	Plumbing - Remove and replace (1) hot water heater that is in deteriorated condition and past its life expectancy, there are issues with the ignition of burners, heater must be replaced as it is now a fire hazard due to the issues with the burners. Heater will be replaced with a new energy efficient tank-less system. Work to be performed to ensure system functions at its original design functionality and to prevent any further damages.	\$	3,255	\$ 3,255	100
42	FM-0050025	Los Angeles	Pasadena Courthouse	19-J1	2	Plumbing - Remove and replace (2) failed sewer pumps. Currently the sewer pumps have failed and during rainy season the pit fills up and the entire basement floods. Flooding gets close to electrical panels, this is a serious safety hazard. Work must be performed before rain begins to ensure system functions properly and to avoid any damage to electrical panels.	d \$	3,874	\$ 3,874	100
43	FM-0050026	Los Angeles	Long Beach Courthouse	19-Y1	1	Plumbing - Remove and replace failed pump #2, located in the basement, to increase the water pressure in the building. Currently the water pressure in the toilet is extremely low, causing toilets to be left un-flushed. Pump must be replaced to ensure proper water pressure to the building and to prevent any health hazards. Work to be performed in-house	s \$	3,221	\$ 3,811	100
44	FM-0050028	Orange		30-C1	2	HVAC - Air Handler #6 for Phase II- Replace supply fan bearings. Noise and vibrations currently being generated by the bad bearings are impacting courtrooms and offices.	\$	7,688	\$ 6,943	90.31
45	FM-0050030	Santa Cruz	County Administration Bldg.	44-A2	2	Electrical - Remove/relocate/replace existing electrical floor monuments (2) w/ new low profile floor outlets; replace 15' electrical wiring; install floor outlet covers where missing and replace 4 damaged carpet tiles - Electrical monuments and missing covers under carpet tiles causing trip hazards.	\$	2,400	\$ 2,400	100
46	FM-0050032	Solano	Hall of Justice	48-A1	2	Elevator - Remove existing Elevator 4 & 5 control board- install (2EA) New Non-proprietary and code-compliant GAL type car door operator and components-install (2EA)- Install (1EA) Control board for one Smart Track door operator -Install pit 9ft 6in 16 wide pit ladder-This work is the result of a Notice to Comply from California State Elevator Inspector	\$	63,851	\$ 63,851	100
47	FM-0050033	San Francisco		38-A1	2	HVAC - Replace the failed Building Automation System (BAS) with new system - The existing Alerton BAS has failed and is no longer supported by the manufacturer. Replacement parts are not being made, the failed system has cost over \$40k in stop gap measures and manual attention of controls since Feb 2012	·. \$	950,000	\$ 950,000	100
48	FM-0050035	Alameda	Fremont Hall of Justice Butte County	01-H1	2	HVAC - Chiller - Install EXVs and control boards (2), oil pressure switch (1), transformer (1), and slide valve piston (1) - Chiller is non operational	\$	8,807	\$ 8,807	100
49	FM-0050036	Butte		04-A1	2	HVAC - Replace return fan motor in Package Unit # 10 - Return fan on A/C 10 is not operating	\$	2,942	\$ 2,942	100
		Contra Costa	Center Arnason Justice	07-E3	2	HVAC - Replace failed components in AC 007 and AC 102 - Condensing units are freezing up and the units will not maintain space temperature HVAC - Replace failed components in the refrigerant monitoring system - The system is showing a constant "fault" status and might not display an alarm if there is	\$	4,976	\$ 4,976	100
		Contra Costa Los Angeles	Downey	07-E3 19-AM1	1	a refrigerant leak Elevator - Remove and rebuild (1) failed hoist motor and (1) generator from elevator no. 3. Currently the elevator will not function due to failed parts, work must be performed to ensure elevator is placed back in service and that it runs safely.	\$	14,863	\$ 4,649 \$ 14,863	100
		Los Angeles	Santa Monica	19-AP1	2	Electrical - Remove (4) ballasts and (4) lamps (from 4 exterior post lights) and replace with (4) new 277 volt ballasts with starter capacitor and (4) new 400 watt metal halide lamps. Currently the pole lights on the exterior of the building are not working properly, before the sun rises or after the sun is set, the courtyard stairs of the building are dark and can cause a tripping hazard for personnel when they are used. Proper lighting is required to ensure safety.	\$	2,339	\$ 2,339	100
5.4	FM-0050042	Los Angeles	Santa Monica Courthouse	19-AP1	2	Interior Finishes - Remove all the cracked and broken glazing around 27 windows and reseal with waterproof silicon. Cracked glazing on the 3rd floor jury assembly room windows is causing heavy leaks during rain, water is causing wet carpet. Windows must be glazed to prevent any further leaks, damage to building and mold buildup that can cause a health issue.	;	2,449	\$ 2,449	100
34	0030042	200 Angeles	Santa Monica Court	25 M I		Electrical - Remove (2) ballasts and (2) lamps (from 2 exterior post lights) and replace with (2) new 277 volt ballasts with starter capacitor and (2) new 400 watt metal halide lamps. Currently the pole lights on the exterior of the building are not working properly, before the sun rises or after the sun is set, the courtyard	Ţ	2,443	2,443	100
55	FM-0050043	Los Angeles		19-AP3	2	stairs of the building are dark and can cause a tripping hazard for personnel when they are used. Proper lighting is required to ensure safety.	\$	2,403	\$ 2,403	100
56	FM-0050044	Los Angeles		19-AQ1	1	Elevators - Remove and replace (1) failed elevator exciter motor and added shim brush for better spring tension.	\$	6,402	\$ 6,402	100
57	FM-0050045	Los Angeles		19-AX2	1	Electrical - Replace defective electrical sub-panel bucket that supplies power to the compressor unit. Replacement needed or building HVAC control could be lost. Fire Protection - Remove and replace module for the 5th floor water flow switch, remove the field wiring of the water flow and reset the system. The system	\$	5,000	\$ 5,000	100
58	FM-0050046	Los Angeles	Van Nuys Courthouse West	19-AX2	1	failed over the weekend and needed to be replaced, system kept going on alarm, module was disconnected. Work performed under emergency status to ensure prompt completion.	\$	3,038	\$ 3,038	100
59	FM-0050047		Stanley Mosk Courthouse	19-K1	2	Interior Finishes - Remove (2) concrete curbs at the abandoned plant wells in Room 102, demolish and level floor to match floor. Remove and dispose approximately 87 sq ft of mastic under vinyl covering (hazmat) before demolishing concrete curbs. Curbs have become a serious tripping hazard and must be removed to avoid any accidents to the public.	\$	9,565	\$ 9,565	100

	-M NUMBER	OCATION	-ACILITY NAME	SULDING ID	PRIORITY	нокт тисе		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
		_	El Monte			Elevators - Replace damaged switches from elevator no. 5 and bring back to working condition. Work completed under P1 emergency. Elevator brought back to				
60	FM-0050048	Los Angeles	Courthouse	19-01	1	service.	\$	6,239	\$ 6,239	100
						Plumbing - Remove and replace a 3' section of 3" copper pipe and cast iron flange that was leaking at the shut off. A new flex connector from the domestic water				
			East Los Angeles			pipe was also needed to complete the work. Work was completed under P1 emergency, replacement of pipe had to be made to ensure proper system function				
61	FM-0050049	Los Angeles	Courthouse	19-V1	1	and to avoid further damage.	\$	9,146	\$ 9,146	100
			East Los Angeles			Plumbing - Replace two (2) pressure relief valves and (1) pressure regulator that have failed and are leaking. Work performed under P1 emergency, valves were				
62	FM-0050050	Los Angeles	Courthouse	19-V1	1	broken and leaking water into the mechanical room and several offices in the 4th floor North / West secured areas.	\$	3,865	\$ 3,865	100
63	FM-0050052	Sacramento	William Ridgeway Family Relations Courthouse	34-E1	2	COUNTY MANAGED - Security - Cameras and Switcher Unit - Replace fourteen (14) failed cameras and one (1) switcher unit (with like, kind and quality equipment to restore system back to normal operating specifications. Interior - Floor leveling - Remove carpet to expose approximately 40 SF of uneven substructure, prep the area and apply a two part self leveling component to the	\$	7,000	\$ 7,000	100
			Rancho Cucamonga			floor, when self leveling component has cured, reinstall the carpet. Currently, the area has a quick drop to flooring causing major tripping hazard and floor must				
64	FM-0050053	San Bernardino	Courthouse	36-F1	2	be brought back to even levels to ensure safety of staff and public.	\$	4,276	\$ 4,276	100
						Fire Protection - Replace several obsolete smoke detectors and defective alarm bells as per vendor's fire alarm deficiencies report dated 11/27/12. Devices need			,	
65	FM-0050054	San Diego	County Courthouse	37-A1	2	replacing to pass fire alarm inspection and to maintain public safety.	\$	2,590	\$ 2,590	100
		_	Gordon Schaber							
			Sacramento			Vandalism - Remove graffiti throughout the public areas of the court - Removed graffiti from 55 areas of interior and exterior walls, doors, mirrors, public				
66	FM-0050055	Sacramento	Superior Court	34-A1	2	restroom partitions and furniture throughout the public areas. This is a consolidation of several separate incidents.	\$	7,579	\$ 7,579	100
			North County							
			Regional Center -			Roof - Restore Single Ply Roof membrane - Remove abandoned vent pipe flashings (3 ea) and cover with sheet metal and tie in roof sections, re-bond several loose	e			
67	FM-0050087	San Diego	Traffic Annex	37-F3	2	seams, tighten roof drains to assure a weather tight seal and place mounting blocks under 120 LF of electrical conduit.	\$	4,105	\$ 4,105	100
68	FM-0050090	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Fire Protection - Remove and replace failed main fire sprinkler system 6" OS&Y valve that is currently leaking. Work must be performed to avoid any further damage to this valve and to ensure proper system function. Valve is leaking and losing water, part must be replaced. HVAC - Remove and replace failed tube bundle from hot water heater, run CO analyzer and balance air gas. Currently the heating boiler is not functioning due to	\$	5,757	\$ 5,757	100
						failed tube bundle that is completely clogged and sagging, the clogged tube is not allowing proper heat transfer to the circulating water causing the tube to				
			San Fernando			overheat and weakening the tube, causing it to sag close to the burner, the fire control module is not functioning, this can cause an explosion, serious safety				
69	FM-0050091	Los Angeles	Courthouse	19-AC1	2	hazard.	\$	8,998	\$ 8,998	100
			Laura Amel I		1	HVAC - Replace Frozen 1 fan motor, 2 Dodge block bearings, 4 BX-116 Gates cog belts, 1 Browning 48-16.0 fan sheave and Hub, 1 Browning four belt fixed pitch				
70	FM-0050092	Solono	Law And Justice Center	48-A2	1	motor pulley - Matching hub-laser alignment of new sheaves, pulleys, and belts and motor. This unit is the only means of heating and cooling the entire second floor of Law and Justice building for Court exclusive space.	,	35,493	\$ 35,493	100
/0	FIVI-0050092	Solano	Clara Shortridge	40-AZ	1	nion or Law and Justice building for Court exclusive space.	ş	35,493	35,493	100
			Foltz Criminal			Security - Sally Port Rollup Gate - Remove and replace the 15' x 13' heavy-duty (In Custody Rated) rollup gate for sally port where sheriffs custody buses enter.				
71	FM-0050093	Los Angeles	Justice Center	19-L1	1	The gate is non-functional with springs having been broken and the equipment is well beyond its life expectancy. Work includes new door, shroud and brackets.	Ś	58,074	\$ 58,074	100
	2230033		George E.		Ť	Exterior Shell - Remove eroded exterior stucco wall- (200sq.ft.) - Remove disintegrated caulking from expansion joint (100.ft.) Renovate exterior stucco wall with	Ť	22,0,4	. 55,074	130
			McDonald Hall of		1	expandable UV resistant waterproof caulk Encapsulate exterior stucco wall and joint seal with elastomeric coating. This will refute rain water intrusion at the				
72	FM-0050094	Alameda	Justice	01-F1	2	court	\$	4,917	\$ 4,917	100
			Fremont Hall of			HVAC - Remove and replace eroded exterior electrical panel enclosure (1)- Install Nema 4 (water tight) electrical panel enclosure (1) and replace associated	Ť		,-	
73	FM-0050095	Alameda		01-H1	2	components and wiring-	\$	2,719	\$ 2,159	79.4
						HVAC - Remove and recover refrigerant from the system, remove and replace the fan motor, center bearings, squirrel cage blowers and end bearing, then				
					1	reassemble the evaporator coil and return back to the wall and rewire the unit, leak check, charge system and test - The Squirrel cage fan in the Mitsubishi Split				
74	FM-0050096	Amador	Begovich Building	03-C1	2	AC has failed, center spindle on the blower has broken	\$	4,400	\$ 4,400	100
			Bakersfield]		HVAC - Remove and replace (2) failed air handler bearings from Air Handler #4. Currently the HVAC unit is creating loud noise, parts must be replaced to prevent				
75	FM-0050097	Kern	Superior Court	15-A1	2	unit from failing completely.	\$	2,349	\$ 2,349	100
			Michael D. Antonovich Antelope Valley							
76	FM-0050098	Los Angeles		19-AZ1	1	Security - Replace broken roll-down gate barrel for judge's secured parking. This work is needed to maintain security.	Ś	3,450	\$ 3,450	100
			,			I and the second of the second		-, .50	. 3,130	, 100

									Ą	
	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT ТПLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
77	FM-0050099	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	HVAC - Remove and replace (1) cracked flex hose return line to the condensate tank and (2) broken brackets along the return steam line. The cracked hose caused leaking of high pressure steam and scalding hot water and the broken brackets were unable to properly support the return line. Work performed under P1 status due to leaking steam and hot water, serious safety issue. System brought back to working condition.		10,926	\$ 10,926	100
		El Dorado	Cameron Park	09-C1	2	Fire Protection - Fire-Security Panel - Replace existing proprietary fire alarm-Security Duress Panel with new non-proprietary fire alarm panel with required components and a non-proprietary security duress panel with required components per current fire code due to ADA remodel - The requirement for the fire alarm upgrade based upon County ADA upgrade.	¢	38,507	\$ 38,507	100
79		Los Angeles	Alhambra Courthouse	19-11	2	HVAC - Replace oil line for Chiller #1 which leaks oil and refrigerant in violation of state air quality code. Also, chiller is low on refrigerant; full charge of approximately 600 lbs of refrigerant is also required. Building cannot hold temperature with one chiller. Work must be done to return system to proper functionality and to prevent further damages.	¢	17,500	\$ 15,050	86
		Kern	Bakersfield	15-A1	2	Exterior Shell - Replace four (4) defective entrance doors located on east side of building. Doors have deteriorated to a point they have become a security problem. Additional adjustment and bracing is necessary to secure the doors.	\$	5,630	\$ 5,630	100
81	FM-0050111	Los Angeles	Hollywood Courthouse	19-S1	2	HVAC - Remove and replace (1) Air Compressor. Currently the compressor's piston has failed causing the backup piston to run full time, back up will fail if this compressor is not replaced. If the backup fails, there will be no control air for the thermostats in the building causing the whole building to default to FULL heat.	\$	4,810	\$ 4,810	100
82	FM-0050112	Orange	Central Justice Center	30-A1	1	Carpet and Drywall - Emergency remediation related to black water intrusion on 11.25.2012 - Isolate the cause and extract the black water to mitigate further damage. Abatement of approximately 350 SF of glue down carpeting and 120 SF of contaminated drywall. Replace 64 SY of carpet and 120 SF of drywall, finished and painted.	\$	11,771	\$ 11,771	100
83	FM-0050114	San Mateo	Central Branch	41-B1	2	HVAC - Install intake damper control and integrate w/existing BAS - The lack of damper control is causing static pressure throughout the facility to compromise the external and keep internal secure doors from closing.	\$	5,000	\$ 5,000	100
			Larson Justice			HVAC - BAS System - The project will include replacement of approximately 10,000 Lineal feet of faulty high-speed network cable. Approximately 20,000 Lineal feet of low-speed network comm. Wiring between 5 air handlers, 10 central plant boiler and chiller controllers, sand filters, and 225 VAV box controllers. Replacement of 9 two-way control valves with three-way valves with associated piping. Removal of obsolete chilled water bypass loop, inclusive of decommissioning of pumps 6 and 7. Rebalance the modified chilled water pipe system. Related BAS software programming and commissioning of all BAS devices.				
84	FM-0050115	Riverside	Center	33-C1	2	Communication within wiring is unstable causing system failure and negative impact to court.	\$	875,000	\$ 707,088	80.81
85	FM-0050116	Los Angeles	Compton Courthouse	19-AG1	2	Fire Protection - Replace two (2) leaky 2-1/2" OS&Y valves and seals. Leaky valves are causing operational failure. Also possible hazard due to leak occurring close to electric panel.	\$	5,290	\$ 5,290	100
86	FM-0050117	Los Angeles	Downey Courthouse	19-AM1	2	Electrical - Retrofit (13) existing metal halide recessed lights to (13) LED output. Currently, the existing metal lights are failing and others are not functioning, replacing these lights to LED will provide stronger lighting for the entrance and lower the electrical costs. Work required to ensure proper lighting in the entrance, safety hazard.	\$	9,688	\$ 9,688	100
87	FM-0050118	Los Angeles	Downey Courthouse	19-AM1	2	Grounds & Parking Lot - Re-lamp (18) parking lot pole light fixtures with new lamps, currently (due to age) the pole lights are out and must be replaced in order to supply appropriate lighting to the parking lot and to ensure public safety when area is dark. Public and safety issue.	\$	5,310	\$ 5,310	100
88	FM-0050119	Los Angeles	Downey Courthouse	19-AM1	2	Fire Protection - Remove and replace (4) leaky OS&Y valves from the Pre-action fire system. Currently the packing, packing glands and bolts are leaking and must be replaced in order to ensure the Pre-action fire system functions at its original design functionality and to prevent any further damage to this system.	\$	4,654	\$ 4,654	100
89	FM-0050120	Los Angeles	Santa Monica Courthouse	19-AP1	2		\$	8,356	\$ 8,356	100
90	FM-0050121	Los Angeles	Santa Monica Court Annex	19-AP3	2	Exterior Shell - Remove and set back in place all loose tiles located in the 2nd floor annex walkway, slate tiles with (2) coats of lacquer based sealant, with non slip polymer aggregate additive. Currently the tiles are damaged, slate tile is breaking apart due to rain, tiles are loose and are causing tripping hazards to the public. Work to be performed to ensure flat surface and to avoid further damage due to rain.	\$	6,034	\$ 6,034	100
91	FM-0050122	Los Angeles	Chatsworth Courthouse	19-AY1	2	Plumbing - Supply and install sheet metal secondary containment at fuel day tank #1. Code Required.	\$	3,450	\$ 3,450	100
92	FM-0050123	Los Angeles	Chatsworth Courthouse	19-AY1	2	Plumbing - Remove and replace failed and leaky actuator valve, lift up slab and cap two heads that are not in use, patch the cement sidewalk to ensure flat surface. Currently the actuator valve is leaking heavily under the sidewalk in the main entrance of the Court creating a puddle of water that has become a trip hazard for the public. Replacement of valve will stop leak.	\$	3,099	\$ 3,099	100
93	FM-0050124	Los Angeles	Torrance Courthouse	19-C1	2	Plumbing - Replace approx 15 lin. ft. of badly rusted 4" domestic water main, 4" flanged gate valve, new check valve and new elbows and test new materials. Major rust and corrosion found on lines which is susceptible to major leak causing loss of building domestic water.	\$	7,850	\$ 7,850	100
94	FM-0050125	Los Angeles	Inglewood Courthouse	19-F1	1	Elevator - Remove and replace a defective run time relay from elevator no. 5 to return to service.	\$	2,965	\$ 2,965	100

									ш	
	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	энокт тпсе		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
			Long Beach			Interior Finishes - Replace sections (first section: 8 ft x 24 in, second: 11 ft x 8 ft and third: 5 ft x 9 ft) destroyed and damaged by water intrusion plaster/drywall				
95	FM-0050126	Los Angeles	Courthouse	19-Y1	2	and replace 12 stained ceiling tiles from the Sheriff's offices room 202B.	\$	9,067	\$ 9,067	100
1	ENA 00E0400	C Di	G	27.41	_	HVAC - Remove and replace failed bearings, shaft and belts from exhaust fan AE-4. Parts must be replaced to ensure HVAC system runs at its original design	,	2 405		
96	FM-0050130	San Diego	County Courthouse	37-A1	2	functionality and to prevent any further damage to the unit.	\$	3,182	\$ 3,182	100
			Kearny Mesa Traffic			Fire Protection - Replace all failed parts listed in the Five Year Certificate Inspection deficiency list, work requires replacement of (approximately 6) fire sprinklers, adding 200 chrome 401 skirts and plugging other sprinklers to bring them back to service as well as adding (approximately 3) more sprinklers. Work is code				
97	FM-0050131	San Diego		37-C1	2	aduling 200 circume 401 skins and progging other sprinklers to bring them back to service as well as aduling (approximately 3) more sprinklers. Work is code required.	s	4,382	\$ 4,382	100
- 37	1101 0030131	Juli Diego	Court	37 61	-	Grounds - Brick Planter Boxes/Seating - Remove and replace six (6) brick planter boxes which also act as seating areas that have started to fall apart due to the	7	4,302	7 4,502	100
98	FM-0050132	San Diego	Juvenile Court	37-E1	2	trees in each planter. Bricks are loose and broken creating a safety issue.	\$	6,270	\$ 6,270	100
		-	Civic Center			HVAC - Replace failed APEX control card and reprogram system - APEX control card has failed causing loss of communication via Ethernet to the BAS computer for	1			
99	FM-0050133	San Francisco	Courthouse	38-A1	2	the facility.	\$	4,259	\$ 4,259	100
			Juvenile Branch,			Electrical - Replace existing 12 gauge electrical wire with 10 gauge - A recent electrical panel inspection found the electrical line supplying a Court closet was over-			_	
100	FM-0050134	San Mateo	Paul Scannell Drive	41-F1	2	heating due to the extremely long run (150 ft) causing a failure/fire concern.	\$	2,029	\$ 2,029	100
			Shasta County							
			Superior Court/Sheriff's			Plumbing - Water heater in attic had leaking gate valve, damaged sheet rock and ceiling tiles in hallway. Need to replace gate valve to water heater and repair				
101	FM-0050136	Shasta		45-B1	2	water damage in ceiling.	¢	2,639	\$ 1,040	39.41
101	1101 0030130	Snasta	Butte County	43 DI	-	Interior - Courtroom Audience Seating - Remove and replace 188 damaged seats and 240 SY of flooring in Courtrooms 3,4,5 and 6. Approximately 30% of the	7	2,033	7 1,040	33.41
102	FM-0050137	Butte	Courthouse	04-A1	2	chairs in the public seating area are broken and unsafe to use.	\$	112,318	\$ 112,318	100
							Ť	,	, , , , , , , , , , , , , , , , , , , ,	
			El Monte			Roof - Replace 45,000 S.F. built up roof (5 layer of coal tar pitch) - Remove and replace approximately 45,000 S.F. of 5 layer hot mop and gravel roof that has a				
103	FM-0050139	Los Angeles	Courthouse	19-01	2	history of leaks and is beyond normal life, existing roof installed in 1977. Replacement includes new metal cap on coping.	\$	380,991	\$ 380,991	100
						Roof - Renew - reseal approx 6,000 sq ft of rolled roofing: approx 4,000 on "Saw tooth" style roof over Annex and approx 2,000 sq ft (3 roofs) over Jury Room,			_	
104	FM-0050140	Sutter	Courthouse West	51-A1	2	Break area. All roofs are well beyond their expected life expectancy.	\$	68,403	\$ 68,403	100
105	FN4 00F0443	Alexande	Berkeley	01.61	2	HVAC- Remove failed heating hot water boiler (50 psi) pressure relief valve (1)-Remove failed heating hot water boiler circulation pump flow switch (1) Install new	۱ ,	2 472	ć 2.472	100
105	FM-0050142	Alameda	Courthouse Downey	01-G1	2	heating hot water boiler circulation pump flow switch - and heating hot water boiler (50 PSI) pressure relief valve.	\$	2,472	\$ 2,472	100
106	FM-0050143	Los Angeles	Courthouse	19-AM1	1	Elevators - Remove and replace pre-opening controller with 1 second timer to eliminate latency issues with pre-opening of elevator no. 2.	s	2,949	\$ 2,949	100
200	0030173		Parking Structure		Ė		,	-,543	- 2,545	130
			Lot 59- Whittier			Plumbing - Replace 1 1/2" inch water supply pipe that has been stolen from the Parking Structure, replacement must be made to ensure water is being supplied to	5			
107	FM-0050144	Los Angeles	Admin CTR	19-AO2	2	the office restroom, pre-action fire sprinkler system and hose bibs throughout the parking.	\$	2,822	\$ 2,822	100
1			Van Nuys	l	_	Fire Protection - Fire Sprinkler Restoration - Remove and replace ten (10) non-compliant sprinkler heads, two (2) pressure gauges and install four (4) regulatory				
108	FM-0050145	Los Angeles	Courthouse East	19-AX1	2	signs. This work is in response to the 5 year fire sprinkler inspection report. Work is code required and is needed for building fire protection.	\$	4,860	\$ 4,860	100
1			Van Nuys			Interior Finishes - Restore flood damaged areas in DA's office, Hallway to judge's lounge, Judge's Restroom & Room B125 back to original design by applying primer to new drywall as well as two coats paint & base coving. Judge's Restroom & Room B125 also require installation & paint of chair rail molding. Restoration				
109	FM-0050146	Los Angeles		19-AX2	2	also requires the installation of approximately 100 sq ft of damaged shag carpet tile.	Ś	4,032	\$ 4,032	100
103	0030140	203 MIBCICS	Michael D.	13 MAL		together are material of approximately 200 of 15 of damaged angle (inc.	۰	7,032	7,032	100
1			Antonovich			Interior Finishes - Remove and replace failed chain and fusible link kits on five (5) roll up fire doors. Currently the back up battery device operator failed, two of				
1			Antelope Valley			the five doors roll down on alarm. Parts must be replaced to ensure that the doors function properly, doors are located by the clerks' window causing				
110	FM-0050147	Los Angeles	Courthouse	19-AZ1	2	disturbance.	\$	2,778	\$ 2,778	100
			Torrance			HVAC - Install electrical strip heater to discharge section of existing fan coil unit and modify ductwork as needed. This is required to supply adequate heat for Rm#				
111	FM-0050148	Los Angeles	Courthouse	19-C1	2	165.	\$	9,250	\$ 9,250	100
			Burbank			HVAC - Remove and rebuild failing hot water pump that is currently leaking water all over the chiller room. Part must be removed and rebuilt to ensure proper	1.			
112	FM-0050149	Los Angeles	Courthouse	19-G1	1	system performance and to ensure hot water is provided to entire building.	\$	3,247	\$ 3,247	100
112	ENA 00E01EC	Orongo	North Justice	30-C1	2	HVAC - Return Air Fan for Phase III - Replace return fan bearings. Return Air Fan is currently making a very loud vibration noise. You can see the entire assembly	_ ا	6 404	ć 5005	90.31
		Orange Solano	Center Hall of Justice	48-A1	2	vibrating and failure is imminent. HVAC- Remove Frozen fan motor drive bearings (2)- Install new fan motor drive bearings- and align motor	¢	6,494 3,100	\$ 5,865 \$ 2,257	72.82
114	1.141-0020129	Joiallo	East County	40-WI		Elevators - Remove and replace bearings from elevator no.2's generator. Currently the generator has failed and parts must be replaced to ensure elevator	۶	3,100	۷,257	12.02
115	FM-0050159	San Diego		37-I1	2	functionality.	s	8,015	\$ 8.015	100
113	0050133	JULI DICEU		13, 11		Paraconards	٧	0,013	0,013	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
116	FM-0050160	San Diego	County Courthouse	37-A1	2	HVAC - Replace 75 lin. ft. of condensate pipe for AHU #5 plus steam trap and 4 isolation valves. This system continues to leak and cause damage to the building.	\$	14,997	\$ 14,997	100
117	FM-0050161	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	HVAC - Install exhaust duct extensions on top of Chiller unit. Currently hot air exhaust is recycling back into condenser coil causing compressor to short cycle and raise head pressure. This will shorten life of equipment and increases operational costs. HVAC - Remove failed Variable Frequency Drive Supply Fan communication board (1) Install VFD communication board- Actuate VFD utilizing the Building	\$	2,845	\$ 2,845	100
			Wiley W. Manuel			Automated system to confirm operational control for the VFD Supply Fan - Building static pressure must be maintained to ensure Court does not experience	١.			
118	FM-0050163	Alameda	Courthouse Wiley W. Manuel	01-B3	2	negative pressure that would cause concern. Plumbing - install 3 drain line fittings and 5 feet of pipe inside of a tile wall with no existing access - create access to install plumbing fittings - drain lines are	\$	3,347	\$ 3,347	100
119	FM-0050164	Alameda		01-B3	2	leaking and causing damage to the walls and flooring	\$	5,038	\$ 5,038	100
		Alameda	George E. McDonald Hall of Justice	01-F1	2		\$	2,560	\$ 2,560	100
			Wakefield Taylor			HVAC - Replace (1) Failed Control Contactor for the Chiller - There is currently a high potential for complete failure of the all contactors which will result in damage				
		Contra Costa	Courthouse Wakefield Taylor Courthouse	07-A2 07-A2	2	to the chiller controls and motor. Security - Replace 20 Faulty Glass Break Sensors - False Alarms due to sensor failure is creating disruption of Court Operations	\$	4,812	\$ 4,812 \$ 4,934	100
			Van Nuys			HVAC - Removed and replaced failed upper coupler between motor and pump shaft, removed and replaced column pump #1 motor. Without a sump pump a				
123	FM-0050168	Los Angeles		19-AX2	1	flood will occur in the basement.	\$	6,113	\$ 6,113	100
124	FM-0050169	Los Angeles	Glendale Courthouse	19-H1	2	Fire Protection - Remove and replace (31) failed sprinkler heads and (2) water gauges, bring water motor gong back to working condition by rebuilding. Work required and must be performed to comply with Fire codes.	\$	2,967	\$ 2,967	100
		<u> </u>	Civic Center			Interior - Door Controller - Remove and replace one (1) failed Courtroom automatic door controller, includes new motor operator and gear box, track arm	Ť	,	, , , , ,	
125	FM-0050170	San Francisco		38-A1	2	package, power supply and 80" dark Bronze header trim piece. Current ADA assembly has failed/non repairable	\$	5,175	\$ 5,175	100
126	FM-0050172	Santa Clara	Hall of Justice (West)	43-A2	1	Public Elevator - Replace wiring to Generator Motor that has burnt out and is not functioning	\$	28,485	\$ 28,485	100
127	FM-0050173	Santa Cruz	Main Courthouse	44-A1	2	Holding Cell - Sally port door (1) - Replace non operational door - The electronic eye on the door closer failed and the door struck a vehicle and is unable to be	,	14,009	ć 14.000	100
127	FIVI-0030173	Santa Cruz	Main Courthouse Hayward Hall of	44-A1		repaired. Removed and replaced the roll-up door which included a new electronic eye and safety.	ې	14,003	\$ 14,009	100
128	FM-0050175	Alameda		01-D1	2	Interior Finishes - Replace flood damaged carpet tiles (100) -and molding (90 feet)	\$	4,708	\$ 4,708	100
120	ENA 00E0476	Contra C+-	Danville District	07.64	,	Interior Finishes - Replace (1) non-operational automatic door closer to the holding cells corridor - The door is not closing all the way and latching shut creating a	,	10.530	6 40.500	400
129	FM-0050176	Contra Costa	Courthouse Betty Lou	07-C1	2	safety and security issue.	Ş	10,536	\$ 10,536	100
130	ENA 00E0477	Orango	Lamoreaux Justice	20 P4	,	Floridizal Panlago gapayatay the thermostat gaplate scale Originated	,	4.984	6 3.005	70.05
130	FM-0050177	Orange	Center	30-B1		Electrical - Replace generator the thermostat, gaskets, seals, O rings and leaking hoses. HVAC - Remove and replace (1) hot water valve that is in an ACM environment and has failed. Currently the failed control valve is frozen in "OFF" position and	\$	4,984	\$ 3,985	79.95
						there is no control of heating, half of the Child Care Center is really cold. Work must be done to ensure proper temperature in this area & that the HVAC system				
131	FM-0050178	San Diego	County Courthouse	37-A1	2	works.	\$	5,760	\$ 5,760	100
			Visalia Superior			COUNTY MANAGED - Elevators - Install new car operating panel with new key switch in elevator #3 and five new hall call stations at each of five landings - Existing				
132	FM-0050179	Tulare	Court	54-A1	2	panel is broken and un-repairable, allowing any type of key device to operate elevator and access the building interior.	\$	4,099	\$ 4,099	100
133	FM-0050184	Merced	New Downtown Merced Courthouse	24-A8	2	Holding Cell - Bullet Proof Glass - Remove and replace a piece of bullet proof glass in a holding cell, the glass is 21 1/2" X 37 1/2".	¢	3,000	\$ 3,000	100
133	1 141 0030104	I FICT CEU	Criminal Court	24-A0		proving cen solice 1100 0100 nemove and replace a piece of bullet proof glass in a nothing cen, the glass is 21 1/2 x 37 1/2 .	ڔ	3,000	3,000	100
134	FM-0050185	Napa	Building	28-A1	1	HVAC - Supply fan VFD (1) - Remove and replace Failed VFD, unable to operate system as designed, fan noise and vibration is impacting court operations.	\$	8,000	\$ 8,000	100
135	FM-0050186	San Francisco	Civic Center Courthouse	38-A1	2	HVAC - Replace evaporator pressure relief valve inlet on the Chiller #1.	Ś	3,119	\$ 3,119	100
133	0030100		Civic Center	50 MI		The replace croporator pressure rener raise inter-on-the crimer risk	ڔ	3,113	5,119	100
136	FM-0050187	San Francisco	Courthouse	38-A1	2	Chiller - Replace Victaulic fittings on chiller # 2.	\$	5,358	\$ 5,358	100
137	FM-0050188	Santa Barbara	Santa Maria Courts Building G	42-F5	2	Electrical - Replace defective relay for cove lighting. The cove lighting is not functioning making lobby area dark which creates a security and tripping hazard in the evening.	¢	5,585	\$ 5,585	100

									, o	
	FM NUMBER	LOCATION	FACILITY NAIME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM BUDGET % OF COST
139	FM-0050189	Fresno	Fresno County Courthouse.	10-A1	2	HVAC - Cooling Towers - Remove and replace deteriorating media and stainless steel media supports, and also new mechanical fan, fan motor, sheaves, bushings, fan shaft bearings, and belts that are beyond repair.	¢	217,674		100
130	1101-0030183	1163110	courtilouse.	10-A1		Interior Finishes - Fire Rated Courtroom doors and hardware - Remove and dispose of six pairs of non-standard double doors and failed hardware. These doors	٧	217,074	3 217,074	100
139	FM-0050192	Napa	Criminal Court Building	28-A1	2	(12 EA.) are 3' x 12' x 2 3/4" thick fire rated doors, which requires a Firelite cementious panel. The new door hardware will comply with Fire/Life/Safety requirements and consist of new Post rails, extra long throw rods, head rail latches and Von Duprin Panic Bars. Court room entrance doors latching mechanisms are inoperable.	Ś	112,424	\$ 112,424	100
100	1111 0030132		Arnason Justice	20 / 12	_	HVAC - Install new HVAC supply on employee side of customer service window. Work to include installation of additional ducting and 24" diffuser. Repairs to	Ť	112,121	Ţ 112,121	100
140	FM-0050194		Center	07-E3	2	Ecophan ceiling grid as required.	\$	12,113	\$ 12,113	100
						HVAC - Replace 3 ton package unit #4 - Remove and replace the non-functional 3 ton package unit, the unit is blowing cold air and the flame out switch continues				
141	FM-0050195	Glenn	Historic Courthouse	11-A1	2	to trip causing the burners to keep cycling on and off.	\$	4,070	\$ 4,070	100
						Fire/Life/Safety - Audio Control Module - Remove and replace (1) defective audio control module (ACM-1) in the fire alarm panel. Currently when the fire panel	١.			
142	FM-0050196		Airport Courthouse	19-AU1	2	alarm sounds, the speakers in strobe / enunciator boxes are not functioning.	\$	4,641	\$ 3,581	77.17
143	FM-0050198		Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Plumbing - Remove and replace (2) failed boiler circulation pumps with new. Pumps are to be replaced to ensure hot water access in entire building and to ensure that the plumbing system functions properly.	Ś	3,539	\$ 3,539	100
			Alhambra			HVAC - Remove and replace leaky 3-way hot water valve from Air Handler Unit #1. Valve was leaking hot water and had to be replaced to prevent major water	Ť	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
144	FM-0050199	Los Angeles	Courthouse	19-I1	2	leak.	\$	2,933	\$ 2,522	86
145	FM-0050200	Los Angeles	Clara Shortridge Foltz Criminal Justice Center Clara Shortridge	19-L1	2	Plumbing - Domestic Water Pumps (2 ea) - Remove and replace one failed and one failing 15 HP domestic water pumps. Water pressure to the building at this time is not high enough to allow the toilets to flush properly or the drinking fountains to work. Electrical - Remove and replace (16) exchange fuel injectors, (32) long short fuel jumper lines, (4) new rocker cover gaskets from the emergency generator.	\$	3,578	\$ 3,578	100
			Foltz Criminal			Currently the generator block heater is not working properly, which causes the start up of the generator to fail and not function properly, also the unit does not				
146	FM-0050201		Justice Center	19-L1	2	reeve down, and starts to heat up.	\$	4,152	\$ 4,152	100
			San Pedro			Security - Replace defective gate operator (motor) and adjust operational settings to return gate to normal operation. Gate is currently non-operational and	Ť	,	,	
147	FM-0050202	Los Angeles	Courthouse	19-Z1	2	requires manual labor to open and close.	\$	5,035	\$ 5,035	100
148	FM-0050203	Mono	New Mammoth Lakes Courthouse	26-B2	2	Grounds and Parking Lot - Monument Sign - Remove four (4) cornet steel plates off the Monument Sign and install four (4) 16 gauge stainless steel back panels as per the detail drawings then re-install the four (4) cornet plates - It is hard to read the sign from a distance due to no contrast Fire Alarm Panel - Replace Fire Alarm Panel and System - Install new non-proprietary addressable fire alarm control panel with dialer, replace necessary fire alarm	\$	3,275	\$ 3,275	100
			Portola/Loyalton			devices to be compatible with new fire alarm control panel, program system, and test - Battery backup charging system is an integral part of the existing fire alarm	,			
149	FM-0050206		Court	32-B2	2	control panel, it has failed requiring the panel to need to be replaced.	\$	7,560	\$ 7,560	100
			Barstow			HVAC - replace failed server room 2.5 Ton split system supporting critical IT Court function. Project requires crane access to remove old and place new rooftop				
150	FM-0050209	San Bernardino	Courthouse	36-J1	2	part of the system.	\$	14,980	\$ 14,980	100
151	FM-0050213	San Diego	Juvenile Court	37-E1	2	Roof - Roof Restoration - Cut out blistered seams and replace with new roofing, Adjust roof drains and seal to roof deck, remove old sealant and reseal pipe penetrations, Install missing counter flashing at AC-1, Add PVC walk pads below all safety rail base plates and raise AC unit at lower deck & install two wood sleepers on walk pads.	\$	5,562	\$ 5,562	100
		_		48-A1	2	Exterior Shell - Sliding Doors - Install New Sliding Door Guides, Hinge Springs and Components - Unable to secure doors	\$	3,421	\$ 2,491	72.82
			Traffic Court -			HVAC - Replaced the compressor, condenser fan motor, main contactor for the compressor, and Bard heat strip - Heat pump #2 has failed, the compressor has a				
153	FM-0050215	Yolo	Modular	57-A8	2	dead short and the rotor is frozen, the condenser fan has also failed along with the compressor contactor.	\$	3,082	\$ 3,082	100
154	FM-0050219		Van Nuys Courthouse West	19-AX2	1	Plumbing - Black water restoration (hazardous waste) - Extract waste water over an approximately 7,600 SF area, spray biocide and place air movers and dehumidifiers to dry the floors and walls. Remove and replace the failed sum pump which was the source of the flood and remove and replace approximately 500 SF of damaged drywall.	\$	28,536	\$ 28,536	100
		_	Torrance			HVAC - Gas Fired Boiler - Remove and replace two each 22 year old non-compliant boilers 3,000,000 BTU EA. due to AQMD regulations Vent stacks have	Ė		,,,,,	
155	FM-0050220	Los Angeles	Courthouse	19-C1	2	deteriorated and need replacement as well.	\$	120,000	\$ 120,000	100
			Pasadena			HVAC - Gas Fired Boiler - Remove and replace three 60 year old 2,000,000 BTU EA. non-compliant boilers due to AQMD regulations, Vent stacks have deteriorated				
156	FM-0050221	_	Courthouse	19-J1	2	and need replacement as well.	\$	180,000	\$ 180,000	100
157	FM-0050222	Riverside	Riverside Hall of Justice	33-A3	2	HVAC - Gas Fired Boiler - Remove and replace the 21 year old 4,750,000 BTU non-compliant boiler due to AQMD regulations.	\$	110,000	\$ 110,000	100
158	FM-0050223	Riverside	Larson Justice Center	33-C1	2	HVAC - Gas Fired Boiler - Remove and replace two each 15 year old 4,500,000 BTU EA. non-compliant boilers due to AQMD regulations.	\$	180,000	\$ 145,458	80.81

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
159	FM-0050224	Monterey	Salinas Courthouse- North Wing	27-A1	2	HVAC - Gas Fired Boiler - Remove and replace the 45 year old 4,500,000 BTU EA. non-compliant boiler due to AQMD regulations.	\$ 85,000	\$ 85,000	100
160	FM-0050225	Alameda	Hayward Hall of Justice	01-D1	2	HVAC - Gas Fired Boiler - Remove and replace two each 34 year old non-compliant 2,900,000 BTU boilers due to AQMD regulations, ACM removal required, Vent stacks have deteriorated and need replacement as well.	\$ 467,000	\$ 412,361	88.3
161	FM-0050226	Kern	Bakersfield Superior Court	15-A1		Fire Sprinklers - Remove and replace all (550)sprinkler heads in building and install heads in areas not currently served to meet certification.	\$ 48,316		100
162	FM 00F0227	Alamada	Hayward Hall of	01 D1	٠	Discribing Demons failed Dates out a spinor (1). Demons availed nice space (1015) leaded Dates out a spinor (1) leaded space (1015)	¢ 4.444	6 4444	100
	FM-0050227	Alameda	Justice	01-D1		Plumbing - Remove failed P-trap auto primer (1) - Remove eroded pipe waste line pipe (10LF) - Install P-trap auto primer (1) Install waste line pipe (10LF) Grounds & Parking Lot - Parking Lot Lights - Restore eight (8) non functioning parking lot lights. Remove the light fixtures from 14' poles, remove and replace 8 ballasts, light bulbs and rewire from fixture head to junction box at the pole base. Currently the degraded pole lights leave the parking lot dark and creates a	\$ 4,444	\$ 4,444	100
163	FM-0050229	Los Angeles	Courthouse Michael D.	19-AY1	2	safety issue, especially on every first Thursday of the month when there is night court. Work must be performed to ensure proper lighting.	\$ 5,295	\$ 5,295	100
164	FM-0050230	Los Angeles	Antonovich Antelope Valley Courthouse	19-AZ1	2	, , , , , , ,	\$ 4,051	\$ 4,051	100
165	FM-0050231	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Interior Finishes - Water Damaged Plaster - Remove and replace water damaged metal lath and plaster ceiling, approximately 500 SF. Currently the damaged ceiling plaster is falling in large sections.	\$ 4,991	\$ 4,991	100
166	FM-0050232	Los Angeles	El Monte Courthouse	19-01	1	Plumbing - Chiller Pump - Extract water that leaked from the failed chiller pump into cells 1 and 2. Remove and replace the failed chiller pump.	\$ 2,541	\$ 2,541	100
167	FM-0050233	Los Angeles	El Monte Courthouse	19-01	2	Interior Finishes - Remove and rebuild (1) Swing Operator assembly motor for the West entrance ADA door, that is burned out and has stopped working.	\$ 3,341	\$ 3,341	100
168	FM-0050235	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	HYAC - Install low ambient control kit on Chiller# 1. Work needed to prevent chiller unit from shutting down when chillers are still needed and outside temperatures get colder.	\$ 3,950	\$ 3,950	100
160	FM-0050236	Santa Clara	Hall of Justice (West)	43-A2	٠	Diumbing Daniage (1) failed course lift num #1	\$ 12.840	ć 13.840	100
109	FIVI-0050236	Santa Ciara	Law And Justice	43-AZ	2	Plumbing - Replace (1) failed sewage lift pump #2. HVAC - Failing Fan Assembly - Provide new and install two (2) Dodge Block Bearings, Provide and replace four (4) Cog Belts, Provide and replace one (1) 16.0" Fan Sheave and matching Hub, Provide and replace one (1) 8.6" Fixed Pitch Motor Pulley and matching Hub, laser alignment of new sheaves, pulleys, and belts and			100
170	FM-0050237	Solano	Center Betty Lou	48-A2	2	balance the fan.	\$ 9,324	\$ 9,324	100
171	FM-0050238	Orange	Lamoreaux Justice Center	30-B1	2	Elevator - Passenger Elevator # 5 - Replace worn shaft seal, spider seal, oil seal, o-rings, inspection cover gasket, thrust bearings, inner bearings, spider roller bearing, pedestal bearing. Elevator is making grinding sounds.	\$ 13,957	\$ 11,159	79.95
172	FM-0050243	Alameda	Wiley W. Manuel Courthouse	01-B3	2	Security - Remove failed electronic lock (2 pair) - Install electronic lock (2 pair) - Judges hardwired panic lock is required to ensure chambers security.	\$ 3,391	\$ 3,391	100
173	FM-0050244	Contra Costa	George D. Carroll Courthouse	07-F1	2	Elevator - Replace failed safety relief valve - Replacement of this valve is required to have the Preliminary Order Signed off by the State.	\$ 6,700	\$ 5,024	74.99
174	FM-0050245	Fromo	Fresno County	10.41	2	HVAC - Air Handler Return blower Shaft - Breakdown the Air Handler to access the drive shaft and bearings, remove and replace the worn drive shaft, bearings	\$ 14,665	¢ 14.005	100
1/4	rivi-0030245	Fresno	Courthouse. Compton	10-A1		and fan sheaves - Return blower not operational due to drive shaft failure. HVAC - Chiller restoration - Restore condenser barrel tubes that contain blockage which is causing the chiller to run above 85 degrees. The chiller running at high	۶ 14,065 ۶	\$ 14,665	100
175	FM-0050246	Los Angeles	Courthouse	19-AG1	1	heat is causing the chiller to trip often.	\$ 3,235	\$ 3,235	100
176	FM-0050247	Los Angeles	Compton Courthouse Michael D.	19-AG1	1	Fire/Life/Safety - Smoke Detectors - Remove and replace smoke detector fuse and wiring short at the 4th floor smoke detector. Elevators 1 & 2, Both elevators were recalled to the basement level due to alarm of the elevator smoke detector. Elevators and smoke detectors back to working condition.	\$ 2,839	\$ 2,839	100
177	FM-0050249	Los Angelos	Antonovich Antelope Valley Courthouse	19-AZ1	2	Plumbing - Domestic Water Pumps - Remove and replace two (2) pressure valves and two (2) new bolt and gasket kits for each pump located at two separate domestic water pumps in the Southwest area of the building. Currently the valves are not functioning and there is little to no water pressure available.	\$ 6,409	\$ 6,409	100
	FM-0050249	Los Angeles Merced	Old Court	24-A1		Electrical - Outlets and switch - Remove failed existing electrical connections in the bench and install two (2) new four gang outlets and a single switch.	\$ 6,409		100

197 MARGOUST Serio Drug Serio Countries of Part 1982											
Dec. 000000000000000000000000000000000000		FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY					FACILITY MODIFICATION PROGRAM BUDGET % OF COST
150 Pro-0000252 Santa latarbax Building G	179	M-0050251	_		37-A1	1	Plumbing - Replace broken Sloan valve in men's restroom. Remediate flood damage and associated Asbestos Containing Materials.	\$	10,000	\$ 10,000	
181 Pht-0000255 Stansibulus Courthouse So.A.2 2 HVAZ - 2nd floor office are cold and not warming up - replace failed actuator valve controlling the reheat valve, install and calibrate 2 floor office hermostatis. S. 3,840 S.	180 I	M-0050252			42-F5	2	HVAC - Replace defective inducer motor and wheel for A/C #7 and replace defective heat exchanger.	\$	3,010	\$ 3,010	100
22 Ph-0000225 Stamislass Half of Records 50-22 2 HVAC - 2nd froor offices are cotal and not warming up - replace failed actuator valve controlling the reheat valve, install and calibrate 2 floor offices thermostats. 5 3,600 5 3,600 185 Ph-0000255 San isosquin 500 5,400 5 1,400 5							Exterior Shell - Replace Exterior Door, frame and mullion and door hardware on south stairwell - This door is beyond repair and the mullions have rusted and				
28 FM 0000255 San Joaquin Sal C. Main Street 39-A3 2 Interior Finishes - Counter Screen - Countertop mount a 24 square foot 3/8" Pleasighs protective screen between staff and public at pro-per clinic station. \$ 1,400 \$ 1,400	181 I	M-0050253	Stanislaus	Courthouse	50-A1	2	deteriorated.	\$	3,188	\$ 3,188	100
COUNTY MANASED PROJECT - Parking Lot Restoration - A section of the Courts parking lot pavement has structurally failed. This requires excavation and replacement of the subgracies of 6,000 s.g. T. This will also include restring and coming into compliance with ADA 7,91,835. Section 13-11 2 2 2 2 2 2 2 2 2	182	M-0050254	Stanislaus	Hall of Records	50-A2	2	HVAC - 2nd floor offices are cold and not warming up - replace failed actuator valve controlling the reheat valve, install and calibrate 2 floor office thermostats.	\$	3,640	\$ 3,640	100
COUNTY MANAGED PROJECT - Parking Lot Restoration - A section of the Courts parking lot pavement has structurally failed. This requires excavation and replacement of the subgracies and approximate area of 6,000 s.p. 17. in suit also include restrings and coming into compliance with ADA 7 spatisty 3-11 2 regularements. This provide has been offerend for some time and the suffer thresh degradation of the sub structure of the subgracies and the subgracies and thresh degradation of the substructure of the subgracies and thresh degradation of the substructure of the	102		Con Incomin	E40 E Main Street	20.42	,		ć	1 400	ć 1,400	100
Ref Mr-0005025 El Dorado Ohinson Bidg O9-E1 1 Fire Protection - Fire Sprinkler - Remove and replace a broken section of fire sprinkler pipe, cast iron fitting and sprinkler head that were damaged after freezing. S 5,000 S 5,			·	Mojave-Main Court		2	COUNTY MANAGED PROJECT - Parking Lot Restoration - A section of the Courts parking lot pavement has structurally failed. This requires excavation and replacement of the sub grade and asphalt of an approximate area of 66,000 sq ft. This will also include restriping and coming into compliance with ADA	\$			
186 M-0050258 El Dorado Johnson Bidg. O9-E1 1 Fire Protection - Fire Sprinkler - Remove and replace a broken section of fire sprinkler pipe, cast iron fitting and sprinkler head that were damaged after freezing. S 5,000 S 5,000	195	:M-0050257			01-C1	1		¢	10.000	\$ 10,000	100
Airport Courthouse 19-AUT 1 Plumbing - Replace (1) backflow device - 10° Ames 5000 RPDA with a new 10° Wilkins 375ADAR with 05&V valves. \$ 14,980 \$	103	101-0030237	Alameda	r sychiatric r avillon	01-01		paringed caused by in-custody variations in the suppression system.	٧	10,000	5 10,000	100
Betty Lou Lamoreaux Justice Center 30-81 2 Plumbing - Back Flow Device - Rebuild the two (2)domestic water backflow prevention devices. Both Backflow devices failed the annual test. Work required the 5 2,866 5 2,291 5 4,904 5 4,90	186 I	M-0050258	El Dorado	Johnson Bldg.	09-E1	1	Fire Protection - Fire Sprinkler - Remove and replace a broken section of fire sprinkler pipe, cast iron fitting and sprinkler head that were damaged after freezing.	\$	5,000	\$ 5,000	100
Betty Lou Lamoreaux Justice Center 30-81 2 Plumbing - Back Flow Device - Rebuild the two (2)domestic water backflow prevention devices. Both Backflow devices failed the annual test. Work required the 5 2,866 5 2,291 5 4,904 5 4,90	187	M-0050259	Los Angeles	Airport Courthouse	19-Δ111	1	Diumbing - Renlace (1) backflow device - 10" Ames 5000 RPDA with a new 10" Wilkins 375ADAR with OS&V valves	¢	14 980	\$ 14 980	100
Rancho Cucamonga 36-F1 2 Security - Remove failed sally port door operator and replace with (1) new Gear Head Motor Operator. Currently the West Sally port door operator has failed and is not allowing the door to close. 190 FM-050262 Solano Hall of Justice 48-A1 2 County has bandoned it in place. Plumbing - Mising valve - Remove and replace 40-SF of tile and one (1) failed Hot water Mising valve. Water is leaking inside wall causing damage to the Court Solano Sola				Betty Lou Lamoreaux Justice			Plumbing - Back Flow Device - Rebuild the two (2)domestic water backflow prevention devices. Both Backflow devices failed the annual test. Work required the	Ţ	,	,	
Electrical - Emergency Lighting - Remove emergency lighting circuit from County UPS (Licrouti, 15lights) Install new emergency lighting circuit to existing emergency generator panel (Licrouti 15lights). The existing UPS system at the Fairfield hall of Justice that supports the emergency lighting was damaged and the windows will be allistic glazing. 191 FM-0050265 Alameda				Rancho Cucamonga			Security - Remove failed sally port door operator and replace with (1) new Gear Head Motor Operator. Currently the West Sally port door operator has failed and	Ś			79.95
FM-0050262 Solano Hall of Justice 48-A1 2 County has abandoned it in place. S 3,429 \$ 3,420 \$ \$ 3,420 \$ 3,420 \$ 3,420 \$ 3,420 \$ 3,420 \$ 3,420											
Wiley W. Manuel 191 FM-0050266 Alameda Courthouse 01-83 2 Surrounding area. Plumbing - Trap Primer - Remove and replace 40 SF of tile and one (1) failed Trap Primer, Snake approximately 100 LF of drain line and extract water from the holding cells. A Plumbing - Trap Primer - Remove and replace one (1) failed Trap Primer, Snake approximately 100 LF of drain line and extract water from the holding cells. A Plumbing - Trap Primer - Remove and replace one (1) failed Trap Primer, Snake approximately 100 LF of drain line and extract water from the holding cells. A Source of the Monald Hall of London Hall of Lond	400		6.1		40.44	_		_	2 420		400
FM-0050266 Alameda Courthouse O1-B3 2 Surrounding area. \$ 3,826 \$ 3,82	190	·M-0050262			48-A1	2	, ,	\$	3,429	\$ 3,429	100
FM-0050267 Alameda Justice 01-D1 1 combination of a partial clog in the drain line and the failed trap primer was the cause of flooding in the holding cells. Sa,942 Sa,943 Sa,942 Sa,9	191 I	M-0050266			01-B3	2		\$	3,826	\$ 3,826	100
George E. McDonald Hall of Justice O1-F1 2 required to remove and reset four (4) water closets. Floors are delaminating from moisture. Del Norte County Superior Court Superior Court O8-A1 2 Exterior Shell - Exterior door card access control board (1) - Replaced failed control board FM-0050270 FM-0050270 Kern Taft Courts Bldg. 15-F1 2 Exterior shell - Replace broken windows - Remove and replace two (2) 3'x4' windows in the Judges chambers, new windows will be Ballistic glazing. Van Nuys Van Nuys Van Nuys FM-0050272 Los Angeles Metropolitan Metropolitan Metropolitan Metropolitan Metropolitan Metropolitan Metropolitan Metropolitan Justice O1-F1 2 Interior Finish - Bathroom Floors - Remove and replace approximately 100 SF of floor tile, laminate flooring and underlayment in four (4) Jury Restrooms, plumber y 4,997 4,997	400				04.54			,	2.042		400
FM-0050268 Alameda Justice 01-F1 2 required to remove and reset four (4) water closets. Floors are delaminating from moisture. \$ 4,997 \$ 4,999 \$ 4,997 \$ 4,999 \$ 4,997 \$ 4,999 \$ 4,997 \$ 4,999 \$ 4,997 \$ 4,999 \$ 4,997 \$ 4,999 \$ 4,997 \$ 4,999	192	·M-0050267		George E.	01-01	1			3,942	\$ 3,942	100
FM-0050269 Del Norte Superior Court 08-A1 2 Exterior Shell - Exterior door card access control board (1) - Replaced failed control board (2) - Replaced failed control board (3) - Replaced failed control board (3) - Replaced failed control board (4) - Replaced failed control board (5) - Replaced failed control board (5) - Replaced failed control board (6) - Replaced failed control board (6) - Replaced failed control board (7) - Replaced failed control board (7) - Replaced failed control board (7) - Replaced failed control board (8) - Replaced failed control board (9) - Replaced failed control pipe, (approximately 2') to stop leak. Backfill, compact and pour back (9) - Replaced failed control pipe, (approximately 2') to stop leak. Backfill, compact and pour back (9) - Replaced failed control pipe, (approximately 2') to stop leak. Backfill, compact and pour back (9) - Replaced failed control pipe, (approximately 2') to	193 I	M-0050268			01-F1	2		\$	4,997	\$ 4,997	100
Plumbing - Saw cut asphalt area to expose leaky pipe, remove and replace section of pipe, (approximately 2') to stop leak. Backfill, compact area and pour back Taft Courts Bldg. 15-F1 2 concrete. Currently the main water line feeding Sheriff Dept and Court is leaking and causing a trip hazard. \$ 6,052 \$ 6,052 196 FM-0050271 Lake South Civic Center 17-B1 2 Exterior shell - Replace broken windows - Remove and replace two (2) 3'x4' windows in the Judges chambers, new windows will be Ballistic glazing. \$ 4,439 \$ 4,439 Elevator - Remove and replace (8) phones with (8) ADA compliant, vandal resistant autodial elevator phones complete with a flush mount stainless steel plate. Currently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company Yan Nuys South Civic Center 17-B1 2 Exterior shell - Remove and replace (8) phones with (8) ADA compliant, vandal resistant autodial elevator phones complete with a flush mount stainless steel plate. Currently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company South Civic Center 17-B1 2 Exterior shell - Remove and replace 1,100 LF of severely worn/rusted rope/cable, Twelve (12) wedged shackles and new banding on the judge's Helevator - Elevator Cable - Remove and replace 1,100 LF of severely worn/rusted rope/cable, Twelve (12) wedged shackles and new banding on the judge's Elevator - Elevator Cable - Remove and replace 1,100 LF of severely worn/rusted rope/cable, Twelve (12) wedged shackles and new banding on the judge's Elevator - Elevator Cable - Remove and replace 1,100 LF of severely worn/rusted rope/cable, Twelve (12) wedged shackles and new banding on the judge's Elevator - Elevator Cable - Remove and replace 1,100 LF of severely worn/rusted rope/cable, Twelve (12) wedged shackles and new banding on the judge's Elevator - Elevator Cable - Remove and replace 1,100 LF of severely w				-							
FM-0050270 Kern Taft Courts Bldg. 15-F1 2 concrete. Currently the main water line feeding Sheriff Dept and Court is leaking and causing a trip hazard. \$ 6,052	194 I	M-0050269	Del Norte	Superior Court	08-A1	2		\$	4,177	\$ 2,559	61.27
196 FM-0050271 Lake South Civic Center 17-B1 2 Exterior shell - Replace broken windows - Remove and replace two (2) 3'x4' windows in the Judges chambers, new windows will be Ballistic glazing. \$ 4,439 \$ 4,4	195	M-0050270	Kern	Taft Courts Bldg.	15-F1	2		\$	6,052	\$ 6,052	100
Elevator - Remove and replace (8) phones with (8) ADA compliant, vandal resistant autodial elevator phones complete with a flush mount stainless steel plate. Currently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company Solution of the provided of the p				ÿ				T.			
Van Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phones are not ADA compliant and do not have the capability to program them to provide location to elevator monitoring company year Nuys Urrently 8 out of 9 elevator phon	196 I	M-0050271	Lake	South Civic Center	17-B1	2		\$	4,439	\$ 4,439	100
197 FM-0050272 Los Angeles Courthouse West 19-AX2 2 in case of an emergency. 7,730 \$ 7				Van Nuys							
198 FM-0050273 Los Angeles Courthouse 19-T1 1 elevator. Metal shavings from deteriorating cable are falling into generator set. \$ 14,999 \$ 14,999	197 I	M-0050272			19-AX2	2	in case of an emergency.	\$	7,730	\$ 7,730	100
	198 I	M-0050273			19-T1	1		\$	14,999	\$ 14,999	100
199 FM-0050276 Alameda Courthouse 01-B3 2 paint as required - Work required to replace faulty plumbing within walls and reopen restroom \$ 6,980 \$ 6,980	199	M-0050276			01-B3	2		\$	6,980	\$ 6.980	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	Interior Finished - Adjust Bench to address ADA and access deficiencies - Cut and lower Judge's desk from 33" to 29" (standard Height) and lower wall		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
			Lakeport Court			accordingly, Notch the counter approximately 18" to allow for clerks access to the Judges desk, replace laminate countertop and replace desk support legs with				
200 FM	л-0050277	Lake	Facility	17-A3	2	angle Iron supports to allow for full access by the Judge.	\$	6,513	\$ 6,513	100
201 EN	л-0050278	Los Angolos	Metropolitan Courthouse	19-T1	2	Elevators - Governor Rope - Remove and replace failed governor/communication cable on Public Elevator #1, which is extremely stretched and elevator is	ė	4,982	\$ 4,982	100
201 FIVE	/1-0030278	Los Angeles	Palo Alto	19-11		inoperable until replacement can be completed.	Ş	4,962	\$ 4,962	100
202 FIV	л-0050279	Santa Clara	Courthouse	43-D1	2	HVAC - Replace failed and plugged heating hot water pipe, (2) failed motor bearings, drive belts and (1) supply fan.	\$	6,119	\$ 4,041	66.04
			Santa Clara			HVAC - Replace 20' of plugged 1/2" heating water line to reheat coil, (1) isolation valve, new copper piping and insulation. Flush and Refill system and set				
203 FM	л-0050280	Santa Clara	Courthouse	43-G1	2	pressures.	\$	5,445	\$ 5,445	100
			Wiley W. Manuel			Fire Protection - Remove Fire Pump and Motor (skids 2) - Install (2 EA 750 GPM) Fire pumps and motors, install 30 LF of 8" flow 1100 gpm test pipe and two (2)		ŀ		
204 FM	Л-0050281	Alameda	Courthouse	01-B3	2	isolation valves.	\$	204,687	\$ 171,528	83.8
205 5	4.0050303	Nama	Criminal Court	20.44		NAC Cook Develop Advisor Develop design (20) in each left and the development	,	22.666	¢ 22.000	100
205 FIVE	л-0050282	Napa	Building	28-A1	2	HVAC - Smoke Dampers Actuators - Remove and replace (30) inoperable fire smoke damper actuators Security - Door controller and controller faceplate - Remove and replace one (1) failed door controller and faceplate, the doors controlled by this controller will	Ş	33,666	\$ 33,666	100
206 EN	л-0050283	Kings	Hanford Building B	16-Δ2	2	Security - Door controller and controller acceptate - Kentove and replace one (1) failed door controller and faceptate, the doors controller by this controller will not lock.	Ġ	3,847	\$ 3,847	100
200 1101	7 0030203	Kings	Beverly Hills	10 AZ	1	Elevators - Remove (4) elevator phones and replace with (4) ADA compliant box emergency elevator phones and run separate phone lines for each. Currently the	7	3,047	3,047	100
207 FM	л-0050284	Los Angeles	Courthouse	19-AQ1	2	existing phones are NOT ADA compliant and can't be identified when calling for an emergency response.	\$	7,421	\$ 7,421	100
						Security - Replace (1) damaged 14' x 13' Lawrence door model HD, 22 gauge steel slats, 24 gauge steel hood, steel guides, 1/2 hp motor operator, electric sensing				
			Alhambra			edge, edge kit, take up reel & emergency hand chain operation. Currently the door has twisted end locks which make it shift causing the door to get stuck off		ŀ		
208 FM	Л-0050285	Los Angeles	Courthouse	19-I1	1	level.	\$	7,864	\$ 7,864	100
						Plumbing - Replace drain located on South Patio Deck. The current drain is 1/2" above deck grade. Water is pooling and seeping into W4 Chambers. Roofing	_			
209 FM	л-0050286	Orange	West Justice Center	30-D1	2	material will need to be replaced along with the drain to correct problem.	Ş	4,582	\$ 4,155	90.68
210 FM	л-0050287	San Diego	South County Regional Center	37-H1	2	Electrical - Replace defective fire door control box. Currently door does not open 100%. Partial open door blocks access to service window E.	Ġ	5,020	\$ 5,020	100
210 110	71-0030287	Jan Diego	Municipal Court	37-111		Electrical - Replace defective fire door control box. Currently door does not open 100%. Fartial open door blocks access to service willhow E.	٧	3,020	3,020	100
			Building - Northern			Fire Protection - Water-motor alarm bell - Remove and replace the existing failed fire water flow switch with a new electronic bell alarm, work will include 50 LF of	f	ŀ		
211 FW	л-0050288	San Mateo	Branch	41-C1	2	conduit and a single dedicated circuit for the new bell.	\$	7,220	\$ 7,220	100
								1		
			Barclay Justice			HVAC - Replace four (4) 20+ year old inefficient propane furnaces with high efficient units and provide and install R-38 insulation in the existing attic space The		ŀ		
212 FM	Л-0050291	Modoc	Center	25-A1	2	existing four (4) furnaces that are 20 years old are failing and are inefficient and unable to provide adequate heating.	\$	26,095	\$ 26,095	100
			Humboldt County							
			Courthouse			HVAC - Replace Drive Motor & Motor Control Board – Remove and replace one (1) failed Drive Motor and Control Board on Trane AHU #3, test system and return		ŀ		
213 FN	л-0050292	Humboldt	(Eureka)	12-A1	2	into operation.	\$	7,760	\$ 7,760	100
	-		Clara Shortridge		1		Ť		,,,,,	
			Foltz Criminal			HVAC - Remove failed air handler supply valve and replace with new, clear water from flood created from failed part, which flooded the 4th, 3rd, 2nd and 1st				
214 FM	л-0050293	Los Angeles	Justice Center	19-L1	1	Floor as well as the service level parking area. There is extensive damage to all floors, specially the 2nd floor.	\$	416,000	\$ 416,000	100
			Clara Shortridge					ļ		
215 5	4.0050304	Los Angolos	Foltz Criminal	10.11		Interior Finishes - Remove and replace (1) historic glass door that has been shattered and broken by a person running into it, door will need to be re-		2.640	6 3.640	100
215 FIVI	л-0050294	Los Angeles	Justice Center Metropolitan	19-L1	2	manufactured and the memorial silhouette will be recreated. Elevators - Governor Rope - Remove and replace failed governor/communication cable on Public Elevator #2, which is extremely stretched and elevator is shut	Ş	3,619	\$ 3,619	100
216 FM	л-0050295	Los Angeles	Courthouse	19-T1	2	down until replacement is completed.	Ś	5,301	\$ 5,301	100
			North Justice	1	T	HVAC - Variable Frequency Drive (VFD) - Replace existing defective 25 hp VFD with new ABB 25 hp VFD. Existing VFD has ceased to function properly. It	Ť	-,	. 2,301	
	л-0050296	Orange		30-C1	2		\$	9,889	\$ 8,931	90.31
217 FM			Harbor Justice							
217 FM						1	1			1
			Center-Newport		_		١.	i		[
	л-0050297	Orange	Beach Facility	30-E1	2	Grounds and Parking Lot - Tree Removal - Large Ash tree in interior patio is causing damage to building and sidewalk.	\$	2,595	\$ 2,188	84.32
	л-0050297	Orange	,	30-E1	2	Grounds and Parking Lot - Tree Removal - Large Ash tree in interior patio is causing damage to building and sidewalk. Security - Door Security Hardware - Remove and replace the failed maglock, panic, keypad station and relay from the secured area door between dept 10 and 11.	\$	2,595	\$ 2,188	84.32

	FM NUMBER	LOCATION	FACILITY NAIME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
220	FM-0050302	Alameda	Hayward Hall of Justice	01-D1	1	Interior - Repair holding cell flood due to blockage in drain. Remove & Dispose Contaminated Carpet Squares (500sqft)-Install Blowers and Dehumidification units for moisture Extraction-of Follow EPA protocol to ensure indoor air quality for flood remediation Court Room 507&508.	\$	14,000	\$ 14,000	100
221	FM-0050304	Los Angeles	San Fernando Courthouse	19-AC1	2	Parking Lot / Installation of (4) 4" steel bollards with heavy duty chains to secure the entrance of the public and jury parking areas.	\$	5,409	\$ 5,409	100
222	FM-0050305	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Locate and replace broken and leaky main irrigation line from the landscape area to repair a major irrigation water leak into the main electrical room, there was approximately 3 inches of standing water. Irrigation line was replaced and system was brought back to working condition, leak stopped.	\$	8,821	\$ 8,821	100
222	ENA 0050306		Pomona	10 14/1	_	Fig. Destroition Dealers fire anniable deliver and other property of the Fire annual control of the second con	ć	4.530	ć 4.520	100
223	FM-0050306	Los Angeles	Courthouse South	19-W1	2	Fire Protection - Replace fire sprinkler deluge pre-action components to comply with Fire marshal notice.	\$	4,520	\$ 4,520	100
224	FM-0050307	Glenn	Historic Courthouse	11-A1	2	Exterior Shell - Roofing - Remove and replace approximately 11,000 SF of roofing. New roof to be a 3-tab, composition shingle with a 30 year warranty.	\$	66,076	\$ 66,076	100
225	FM-0050308	Los Angeles	Long Beach Courthouse	19-Y1	1	Plumbing - Clogged Storm Drain - Hydrojet 6" storm line too clogged to clear by snaking the line. Cap the line at the line to perform the hydrojetting and replace a 90 degree coupling damaged by the removal of tree roots, concrete and dirt.	Ś	5,045	\$ 5,045	100
223	- W 0030300	2007 Higeres	Historical	13 .1	_	So degree coupling duringed by the removal of thee roots) conserve and and	Ý	3,013	5,015	100
226	FM-0050309	Napa	Courthouse	28-B1	2	Security - Install wall rack to accommodate CCTV equipment - Remove damaged wiring and terminate to rack	\$	9,141	\$ 9,141	100
227	FM-0050311	Placer	South Placer Justice Center	31-H1	2	Electrical – flag pole lights out– lights required to hang flags, identified failed buried cable, replace buried cable with conduit, pull wire, restore and return to operation.	\$	2,600	\$ 2,600	100
		Placer	South Placer Justice Center	31-H1	2	Security – Security system / access control not operating correctly, Identified issue is failed control module, control module replaced to restore Central Security Control to normal operation.	\$	3,000	\$ 3,000	
229	FM-0050313	San Diego	Kearny Mesa Traffic Court	37-C1	2	Fire/Life/Safety - Door Hardware - Replace current hardware with NFPA/ADA approved panic hardware on two (2) sets of double doors from rooms 206 to 207 and Claims Rm. Currently this is a fire life safety hazard, as the West and East Egress Corridors are being locked with slide bolts, this is out of compliance.	\$	3,660	\$ 3,660	100
230	FM-0050314	Santa Barbara	Lompoc Municipal Court	42-D1	2	Interior Finish - Courtroom Flood Restoration - Work with county to restore Lobby Area and Courtroom 1 back to original condition by replacing damaged drywall and baseboards, painting of walls, and installation of rubber base.	\$	4,220	\$ 4,220	100
231	FM-0050315	Alameda	Hayward Hall of Justice	01-D1	2	Plumbing - Isolation Gate Valve - Remove and replace two (2) Isolation gate valves and dielectric fittings. After hours work due to the need of shutting off the buildings water supply. This is required to stop active Potable water leak at the court.	\$	2,770	\$ 2,770	100
222	FM-0050316	Kern	Bakersfield Superior Court	15-A1	1	Plumbing - Remove water and sanitize areas that were contaminated by sewage water that traveled down Judicial hallway contaminating common area terrazzo flooring with sewage water.	¢	4,023	\$ 4,023	100
232	1101-0030310	Kem	Downey	13-A1		Electrical - Remove and replace (15) existing surface mounted HPS fixtures on the Sally Port canopy with (15) new 38 watt LED canopy fixtures, utilizing a scissor	7	4,023	7 4,023	100
233	FM-0050317	Los Angeles	Courthouse	19-AM1	2	lift. Currently the canopy lighting is non-functional.	\$	4,685	\$ 4,685	100
234	FM-0050318	Los Angeles	Airport Courthouse	19-AU1	1	HVAC - Remove and replace failed valves, clear the air lines, replace the centrifugal air separator air vent on the return heating hot water heater. Regulated the negative air pressure reading on the 1st floor air handler unit.	\$	7,616	\$ 7,616	100
235	FM-0050319	Los Angeles	Pasadena Courthouse	19-J1	2	Electrical - Diesel Generator - Restore diesel generator to perform per original engineered specifications. Work required is to remove and replace the battery charging regulator assembly, fuel separator bowl, gasket & seals, battery charging assembly and exchange the water pump assembly.	\$	7,285	\$ 7,285	100
236	FM-0050320	Santa Barbara	Lompoc Municipal Court	42-D1	1	Interior Finish - Install, level, and sanitize drywall and install 4 x 4 wall tile straight set, 4 x 4 cove base, toilets, and sinks. This is the follow up work that was a result of the hot water heater flood.	\$	9,930	\$ 9,930	100
237	FM-0050321	Solano	Hall of Justice	48-A1	2	Interior Door Hardware - Replace 11 failing door locksets with ADA compliant handle sets. Current units do not operate correctly and prevent access.	Ś	10,070	\$ 7,333	72.82
			Hayward Hall of		_	Interior finishes - Flood Remediation - Install carpet tile (600 SQ YD) - Replace Carpet tiles (600 SQ YD) (1200 SQ YD total) - Replace laminate covering (80 SQ FT) or judicial bench and bar - Remediation FM due to flooding caused by in-custodies - Carpet partially removed (600 SQ FT) remaining carpet curling and not adhering	1	_5,0.0	,,,,,,,	, 2.52
238	FM-0050322	Alameda	Justice	01-D1	2	to the floor (trip hazard) - Laminate is buckling pulling away from the bench	\$	184,866	\$ 184,866	100
239	FM-0050323	Alameda	Hayward Hall of Justice	01-D1	2	Plumbing - Auto trap primers (18) -Remove and replace with manual primers (18)- Isolation valves (60)-Building has been flooded by inmate vandalism which has required full building shutdown which negatively impacted court operations.	\$	193,224	\$ 193,224	100
			Compton				1.			
	FM-0050328 FM-0050330	Los Angeles Merced	Courthouse Old Court	19-AG1 24-A1	2	Elevator, Escalators & Hoists - Elevator #11 - Rebuild failing hydraulic pump and install new muffler HVAC - Air Ducting Control - Furnish and install a Zone Control system to serve the judges chambers and juror room by installing (1) zone controller, (2) programmable thermostats, (2) zone dampers, (1) bypass damper, bypass duct, insulate bypass duct, run new thermostat wire from HVAC unit to the zone controller, run new thermostat wire to new thermostat in the judges chamber, seal new duct connections, and test system	\$	6,654	\$ 11,502 \$ 6,654	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT ТПLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
242	FM-0050331	San Diego	North County Regional Center - Vista Center	37-F2	2	Holding Cell - Equipment - Replace failed parts of one (1) touch screen viewing monitor in the Sheriff's control room at the Court's Main Holding Area.	\$ 3,666	\$ 3,666	100
243	FM-0050340	Los Angeles	Pasadena	19-J1	2	Exterior Shell - Walk Up Windows. Install one (1) new Walk-up window and required casework, demolition, framing and electrical.	\$98,784	\$ 98,784	100
244	FM-0050341	Los Angeles	Santa Monica Courthouse	19-AP1	2	Exterior Shell - Walk Up Windows. Install three (3) new Walk-up windows and required casework, demolition, framing and electrical.	\$101,908	\$ 101,908	100
245	FM-0050342	Los Angeles	Metropolitan Courthouse	19-T1	2	Exterior Shell - Walk Up Windows. Install four (4) new Walk-up windows and required casework, demolition, framing and electrical.	\$210,000 s \$ 9,895,836		100