

#### Judicial Council of California

455 Golden Gate Avenue · San Francisco, California 94102-3688 www.courts.ca.gov

# REPORT TO THE JUDICIAL COUNCIL

For business meeting on April 16-17, 2015

Title

Court Facilities: Trial Court Facility Modification Quarterly Activity Report for Quarter 2 of Fiscal Year 2014–2015

Quarter 2 of Fiscar Tear 2014–2013

Submitted by

Trial Court Facility Modification Advisory Committee

Hon. David Edwin Power, Chair

Agenda Item Type Information Only

Date of Report March 4, 2015

Contact

Patrick McGrath, 916-643-8051 patrick.mcgrath@jud.ca.gov

#### **Executive Summary**

The Trial Court Facility Modification Advisory Committee has completed its facility modification funding for the second quarter of fiscal year 2014–2015. In compliance with the *Trial Court Facility Modifications Policy*, adopted by the Judicial Council on July 27, 2012, the advisory body is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 2, Fiscal Year 2014–2015* as information for the council. This report summarizes the activities of the Trial Court Facility Modification Advisory Committee from October 1, 2014 to December 31, 2014.

#### **Previous Council Action**

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*, <sup>1</sup> adopted by the Judicial Council in 2005 and revised on December 12, 2014. The working group's primary oversight responsibilities included reviewing statewide facility modification requests and approving facility modification funding.

<sup>&</sup>lt;sup>1</sup> As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See <a href="www.courts.ca.gov/documents/jc-20120727-itemG.pdf">www.courts.ca.gov/documents/jc-20120727-itemG.pdf</a>.

The working group's charge was formalized by the Judicial Council on December 14, 2012, and the working group was assigned additional oversight responsibility for the operations and maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability. On April 25, 2013, the working group's status was elevated to that of advisory committee.

An updated Court-Funded Facilities Request approval process was submitted and approved by the Judicial Council on August 23, 2013, requiring all Court-Funded Facilities Requests to be reviewed and approved by the Trial Court Facility Modification Advisory Committee (TCFMAC). These submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at <a href="https://www.courts.ca.gov/2567.htm">www.courts.ca.gov/2567.htm</a> under Research and Reports: Conditions in Our Courts.

#### **Methodology and Process**

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, But Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, But Serviceable; and Priority 6–Hazardous Materials, Managed But Not Abated. These categories are based on methods commonly used by private-sector facility management firms. Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC primarily limits approvals of facility modification projects to Priority 1 and Priority 2 projects. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

### **Policy and Cost Implications**

During the second quarter of fiscal year 2014–2015, the TCFMAC reviewed and approved a total of 386 facility modifications for a total projected cost of \$27,066,997. The Facility Modification Program's share of these projects totals \$23,396,856. These approved projects are limited to Priority 1 emergency projects and Priority 2 critical needs projects. Please see Attachment A for a detailed list of all approved projects.

During this quarter, eight projects required additional funds in excess of \$50,000 over their original estimates. The Facility Modification Program's share of these cost increases totals

\$1,128,963. Projects that require excess costs of this magnitude are typically Priority 1 emergency projects that do not have a full scope and cost estimate developed at the onset of the project and for which significantly more work or testing is discovered after commencement.

During this quarter, three Court-Funded Facilities Requests (CFRs) were reviewed and approved by the TCFMAC, including requests from Glenn, Los Angeles, and San Joaquin courts. As stated above, CFR submittals may include lease-related costs, allowable court operations expenditures under rule 10.810 of the California Rules of Court, and other facility improvement costs that are not allowable under rule 10.810. See Attachment B for a detailed list of CFRs approved by the TCFMAC during the second quarter of fiscal year 2014–2015.

#### Implementation Efforts

The TCFMAC conducted an in-person meeting on November 3, 2014, at the Sacramento office, and a teleconference on December 15, 2014, to review facility modification funding requests and to discuss the following topics:

- Regular review of facility modification projects lists: A (Emergency and Priority 1), B (FMs Under \$50K), C (Cost Increases Over \$50K), D (FMs Over \$50K Eligible for Funding), and F (Court-Funded Facilities Requests);
- Discussion and review of facility modification requests for Priority 3 projects received from courts;
- Status updates on the Department of Finance (DOF) denial response to the FY 2015–2016 budget change proposals;
- Informational presentation from Judicial Council staff to review expenditures from FY 2013–2014 relative to the operational budget;
- Review and approval of a utility cost outreach letter that was sent to all presiding judges;
- Informational presentation from Judicial Council staff to review the process involved in obtaining a solar power purchase agreement;
- Discussion and review of the DOF deferred maintenance report;
- Informational presentation from Judicial Council staff to review current staffing status and constraints;
- Discussion of comments received from the Superior Courts of Merced, Nevada, Placer, Santa Barbara, Solano, and Tulare Counties;
- Discussion and review of proposed California Rule of Court 10.65 (Trial Court Facility Modification Advisory Committee; adopted effective January 1, 2015);
- Discussion and review of the *Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2013–2014*;
- Judge David Edwin Power's visit to the Napa County Historic Courthouse and Napa County Criminal Courthouse to examine the earthquake damage and the ongoing repairs at both facilities; and
- Site visit conducted by Ms. Christina Volkers, court executive officer of the Superior Court of San Bernardino County, at both the Superior Court of Placer County's Auburn jail arraignment courtroom and the shelled facility at the new Placer jail.

## **Next Steps**

The *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2014–2015* will be submitted to the Judicial Council in June 2015.

#### **Attachments**

- 1. Attachment A: TCFMAC Funded Project List: Quarter 2, Fiscal Year 2014–2015
- 2. Attachment B: Court-Funded Facilities Requests (CFRs): Quarter 2, Fiscal Year 2014–2015

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Exterior Grounds - Flood prevention - Storm Drains (20) - Restore the storm drains to the original engineered design capacity, remove mud, vegetation and debris within the basins and					
			Fremont Hall of			pipes, pressure flush drain pipes and install carbon filters - Storm water drains are clogged and					
1	FM-0023333	Alameda	Justice	01-H1	2	prone to flooding.	\$	26,530	\$	21,065	79.40
						Fire Protection - Fire Alarm System - Correct deficiencies found while performing a level IV PM -	•	· · ·		•	
			Wiley W. Manuel			Replace failed water flow device located on the 3rd floor stairway #1 and Fireman's phone jack					
2	FM-0052860	Alameda	Courthouse	01-B3	2	on the 1st floor.	\$	2,114	\$	1,772	83.80
			Fremont Hall of			HVAC - Replace the failed slide valve piston and lip seal bypass kit on compressor #1 on Chiller					
3	FM-0052881	Alameda	Justice	01-H1	2	#1.	\$	6,746	\$	5,356	79.40
			Berkeley			Exterior window flashing - Replace two missing window head flashings on the front and rear		2 225	_	2 225	100.00
4	FM-0052952	Alameda	Courthouse	01-G1	2	second floor windows for wet weather proofing to match existing.	\$	3,225	\$	3,225	100.00
						Fire Sprinkler - Replace leaking fire sprinkler system weld-o-let on the second floor, welding required. Isolate fire sprinkler system riser on the south stairwell to allow all sprinklers to be					
			Wiley W. Manuel			feed from the north side riser. (Full building coverage overnight) Drain and fill system checking					
5	FM-0053024	Alameda	Courthouse	01-B3	2	all floors and floor isolation valves for leaks.	¢	8,569	¢	7,181	83.80
	1101-0033024	Alaineda	Courtiflouse	01-03		all floors and floor isolation valves for leaks.	7	6,303	7	7,101	83.80
						HVAC - Remove and dispose of existing cooling tower; Re-slope and re-roof 800 sq ft of roofing;					
						Install one (1) new 227 ton cooling tower. Provide and install 40 LF of 8 steel piping and 20 LF of					
						1 copper piping including fittings, valves and supports; Provide a new VFD; Connect cooling					
			Wakefield Taylor			tower to the existing BAS. Work requires a crane and is to be done off hours - Existing Cooling					
6	FM-0053469	Alameda	Courthouse	07-A2	2	tower is rotting and leaking. The water pools on the roof due to slope problems.	\$	429,416	\$	429,416	100.00
			Fremont Hall of			Remove and replace failed twenty five horsepower motor for the pneumatic tube transport					
7	FM-0054040	Alameda	Justice	01-H1	2	system blower - Work to be performed after hours.	\$	14,845	\$	11,787	79.40
						Exterior Shell - Replace the failed outdoor steel staircase, guardrails, and hand rails, with an					
			Hayward Hall of			industrial aluminum staircase, guardrails, and hand rails, located outside of the basement					
8	FM-0054046	Alameda	Justice	01-D1	2	mechanical room - Rusted to a point of being unsafe.	\$	52,822	\$	46,642	88.30
			Dutte County			HVAC - Replace 2 Condenser Fan Motors, Fan Blades and Motor Speed Controls - The 2 motors					
	ENA 0052049	Dutto	Butte County	04.41	2	have quit working and the Chiller runs high pressures on warm days. Putting heavy load on	۲	6 F21	ے	6 F21	100.00
9	FM-0052948	Butte	Courthouse  New San Andreas	04-A1	2	compressors.	<b>&gt;</b>	6,521	<b>&gt;</b>	6,521	100.00
10	FM-0054066	Calaveras	Courthouse	05-C1	2	Elevator - Elevator #4 stuck in basement with entrapment, replace failed vane behind rotor.	¢	2,812	ς .	2,812	100.00
10	1 191-0034000	Calavelas	Courtilouse	100-CI		COUNTY MANAGED - HVAC - Replace 22 year old, 60 ton HVAC unit that has completely failed.	۲	۷,01۷	٧	۷,01۷	100.00
11	FM-0053025	Colusa	Courthouse Annex	06-A2	1	Repair is not economically prudent. Crane will be utilized to replace the unit.	\$	80,000	\$	80,000	100.00
- <del>-</del>				· · · <del>-</del>	† <u> </u>	The state of the s	, r	,		,	
						HVAC - Restore AHU-11 to manufacturers specifications, work includes the installation of one					
		Contra	George D. Carroll			new high efficiency motor with a VFD. This unit serves public areas that are presently not getting					
12	FM-0052942	Costa	Courthouse	07-F1	2	air. The VFD is required to lower air flow because the unit originally served a much a larger area.		14,841	\$	11,129	74.99

						Vandalism - Graffiti removal in six restrooms - Replace 2 - 5 x 3 etched restroom mirrors;					
		Contra	George D. Carroll			Remove multiple instances of graffiti in clerks area and public spaces; Replace 24 defaced ceiling					
13	FM-0052943	Costa	Courthouse	07-F1	2	tiles.	\$	9,073	\$	6,804	74.99
						Fire Protection - Install 80 ft 1-1/2 steel pipe; Install 7 new sprinkler heads with escutcheon; Re-					
						plaster 36 sq ft ceiling plaster; Install straps (8), fittings (20), Replace 3 pre-action gauges; Drain					
		Contra				and recharge 3 floors 3 times; Perform fire watch; off hours work - Deficiencies found during					
14	FM-0052992	Costa	Bray Courts	07-A3	2	annual Fire Inspections by the SFM.	\$	57,155	\$	48,879	85.52
						HVAC - Remove and dispose of (4) failing rooftop AHUs; Install (4) new units, (1) 7.5 ton, and (3)					
						12.5 ton; Install 4 new roof curbs; Install (4) economizers and (4) smoke detectors; Install and					
		Contra	Danville District			wire (4) new thermostats (200 ft of wire); Modify 240 sq ft of ductwork to fit new units; Requires					
15	FM-0053468	Costa	Courthouse	07-C1	2	a crane and off hours installation.	\$	294,518	\$	294,518	100.00
						Fire Protection - Provide and install one (1) upgraded fire beam detector in the atrium; Provide					
						Start-up, testing, and verification of operation; Work to be performed by a specialty fire alarm					
						company; Work to be done off hour and requires a lift to access the detector location - Present					
		Contra	Arnason Justice			beam detector creates false alarm conditions. System adjustments completed since construction					
16	FM-0053473	Costa	Center	07-E3	2	have not resolved initial design deficiency.	\$	14,238	\$	14,238	100.00
						HVAC - Remove and replace one (1) 40 Ton roof top condenser, (1) 40 Ton indoor condenser,					
						and (4) 10 ton scrolls and heat exchanger; removal and replacement of (16) seismic spring					
						isolators, (2) water pumps, (2) 3 triple duty valves and suction diffusers and (6) 3 flex					
						connections, (2) thermometers and pressure gauge valve kits, (2) 1 1/4 and 1 3/8 flex					
		Contra	George D. Carroll			connections, (1) Pot Feeder, (100) LF of 3 chilled water piping and (100) LF of refrigerant piping;					
17	FM-0053477	Costa	Courthouse	07-F1	2	New refrigerant Leak detection system.	\$	567,603	\$	425,645	74.99
		Contra	George D. Carroll								
18	FM-0054085	Costa	Courthouse	07-F1	2	HVAC - Replace Qty 1 failing burning on boiler #2 - The burner is a safety issue.	\$	4,616	\$	3,462	74.99
						HVAC - Install new stainless steel outside air and return air dampers, linkages, and actuators for					
						nine (9) economizers (AH-1, AH-2, AH-3, AH-4, AH-5, AH-6, AH-8, AH-9, AH-11). Remove existing					
			Del Norte County			ductwork and install new dampers, insulation, and sheet metal. Reinstall existing ductwork and					
10	FM-0053412	Del Norte	Superior Court	08-A1	2	seal new dampers. Remove and dispose of existing dampers, linkages, and actuators.	خ	75,881	خ	66,775	88.00
19	1101-0055412	Der Norte	Superior Court	08-A1		sear new dampers. Remove and dispose of existing dampers, linkages, and actuators.	٦	73,861	٦	00,773	88.00
						Exterior Shell - Replace 5 single glazed window & 2 door panes with opaque dual glazed units					
						and install 2 dual glazed doors/fame. Current conditions leave room too cold even after					
20	FM-0053450	El Dorado	Johnson Bldg.	09-E1	2	repeated HVAC adjustments that cannot overcome thermal loss from the exterior conditions.	Ś	11,000	Ś	11,000	100.00
	1111 0033 130	2. 20.440	B.F. Sisk Federal	03 22	<u> </u>	Grounds and Parking Lot - Replace slat, bottom rail and adjust - Judges' parking lot gate was hit	<u>Υ</u>	11,000	Υ	11,000	100.00
21	FM-0052876	Fresno	Courthouse	10-01	2	with a vehicle and damaged, requiring parts replacement to operate properly.	Ś	4,070	Ś	4,070	100.00
						Fire Protection - Replace 2 stolen post indicator valve heads and secure as necessary them to	,	.,	,	1,010	
						prevent them from being removed in the future. Order 4 new Knox covers and install them on					
						the 4 fire department connections. Paint the new valves fire red and secure them with new					
			Fresno County			padlocks - Fire Protection equipment must be maintained properly to insure it is ready when					
22	FM-0053039	Fresno	Courthouse.	10-A1	1	required for life safety.	\$	4,758	\$	4,563	95.91
						Security - (1) Install Windows 8.1 software on the two existing security camera system	İ	,	Ė	,	
						workstations, replacing Windows XP; (2) Upgrade existing ViconNet software to v. 6.7SP1;					
						update software, drivers or firmware as necessary for existing Nucleus, 167 cameras, NVRs,					
						storage; (3) Replace one failed encoder Windows XP is no longer a supported operating					
			B.F. Sisk Federal			system, and is a security risk on the Courts network. The ViconNet software needs to be					
23	FM-0053461	Fresno	Courthouse	10-01	2	upgraded to support Windows 8.1.	\$	8,253	\$	8,253	100.00
	1	_1	L			1	<u> </u>	•	<u> </u>	, L	

						Energy Efficiency - HVAC - Install 30 smart room sensors, add building pressure controls to AHU-6 along with transfer duct in Jury Assembly Room; reconfigure BAS software to maximize					
			B.F. Sisk Federal			operational and program efficiencies relative to set points, temperature dead bands, fan control					
24	FM-0053522	Fresno	Courthouse	10-01	3	functions and temperature dead bands.	\$	61,604	ς	61,604	100.00
27	1101 0033322	1103110	Courtilouse	10 01	<u> </u>	runctions and temperature dead bands.	٧	01,004	7	01,004	100.00
						Interior Finishes - Remove approximately 270 sq. ft. of lead-based and non-lead-based paint at					
						areas of efflorescence and wall damage in Library and DCSS office. Perform clearance test of					
						abated areas to ensure no lead paint left behind. Patch and paint approximately 350 sq. ft. of					
						wall space - Moisture intrusion through outside wall from sprinkler system has caused					
25	FM-0054064	Fresno	Firebaugh Court	10-K1	2	efflorescence and wall damage. Environmental tests have been conducted and are attached.	Ś	6,575	\$	3,815	58.02
			JJC Delinquency			Security - Replace power supply and one hard drive in Multiplexer #1 - Multiplexer #1 has failed		- , -	'	-,	
26	FM-0054073	Fresno	Court	10-P1	2	and is inoperable.	Ś	2,675	Ś	1,565	58.50
						HVAC - Remove pump and pump motor for heating water system. Install new viton pump seal,	1		7	_,	
			Fresno County			sleeve the seal race and remove grease from the motor. Reinstall pump and pump motor -					
27	FM-0054093	Fresno	Courthouse.	10-A1	2	Pump had failed and was badly leaking.	Ś	2,895	\$	2,777	95.91
			Historic			The state of the s	1		7	_,:::	
28	FM-0052947	Glenn	Courthouse	11-A1	1	HVAC - Replace condensing unit - Unit has dumped all refrigerant and will need to be replaced.	Ś	3,500	\$	1,715	49.00
					_	and the second s	1	- 7,5 5 5	,		
			Humboldt County			Interior - Remediate Sound Issue - Supply and install forty-eight (48) sound emitters to mask the					
			Courthouse			noise transfer issues in family law mediators office, safety issues when family members can hear					
29	FM-0052859	Humboldt	(Eureka)	12-A1	2	conversations with mediators outside in waiting rooms. Set up and training included.	Ś	13,105	Ś	13,105	100.00
			()			HVAC - Install Mini Split Unit - Install 1 recessed ceiling mounted Mini Split heat pump in Court	1		,		
						IT, the house system cannot control air temperature in this room due to heat load from					
						Computers, it is connected to Court Finance so we either keep one group hot or the other group					
			Humboldt County			cold. Including core drilling and roof penetrations, roofing patching at roof top compressor					
			Courthouse			location, modification to T-bar ceiling in IT room to allow recess unit to be installed, all electrical					
30	FM-0052861	Humboldt	(Eureka)	12-A1	2	connection and wireless.	Ś	52,322	\$	52,322	100.00
			()			HVAC - Install two new 5 ton rooftop high efficiency gas electric package units: AC Units PKU #8	7	,	7		
						and PKU #9 including new Seismic Vibration Isolation Roof Curbs. A 90 ton crane will be used to					
						remove the (2) package units from the roof and lift the new units into place. Two rooftop HVAC					
						units (5 ton each) no longer provide sufficient cooling to Judge's Chambers and the Deliberation					
			Delano/North			room. Both units have had multiple parts replaced to no avail and units are operating at less					
31	FM-0052741	Kern	Kern Court	15-D1	2	than 60% capacity.	\$	39,293	\$	39,293	100.00
						HVAC - Compressors were replaced returning cooling to Court exclusive (critical) areas. Replace	'	,	'	,	
			Delano/North			faulty compressors (2) that are both grounded and not providing cooling to Courtroom - failed					
32	FM-0052831	Kern	Kern Court	15-D1	1	compressors have rendered unit servicing Courtroom inoperable.	\$	8,656	\$	8,656	100.00
						COUNTY MANAGED - Electrical - P2/PHASE 2 of P1 Electrical Work - Replace 50yr old		,		,	
			Bakersfield			cabling/conductors/breakers/disconnects. The existing electrical panel has been in service for					
33	FM-0052841	Kern	Superior Court	15-A1	2	fifty years and parts can no longer be replaced, this is a 12000 volt system.	\$	485,210	\$	485,210	100.00
			Bakersfield			HVAC - Replace failed Compressor #2 on Chiller #1. Chiller working below capacity due to failed		,	'	,	
34	FM-0052904	Kern	Juvenile Center	15-C1	1	Compressor #2 on Chiller #1.	\$	42,791	\$	28,567	66.76
	-		Bakersfield			Plumbing - Replace approximately 5' of leaking 3" chilled water pipe and multiple fittings.	<u> </u>	,	•	,	· ·
35	FM-0052907	Kern	Juvenile Center	15-C1	2	Chilled water line has small leak and must be replaced.	\$	3,304	\$	2,206	66.76
-			1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			Plumbing - Restore leaking pipe in Men's public restroom: Area scrubbed and dried out, drywall	<u> </u>	,	•	,	
			Shafter/Wasco			removed and replaced in lobby and men's public restroom. Patch and paint to match existing.					
36	FM-0052985	Kern	Courts Bldg.	15-E1	1	Court staff reported wet wall and floor tile in restroom.	\$	31,918	\$	28,710	89.95

37	FM-0053037		Bakersfield Superior Court Modular	15-A2	2	HVAC - HVAC Bard unit compressor has failed. Installation of replacement (Energy Efficient) HVAC unit to service Superior Court Modular.	\$ 5,328	\$ 3,337	62.64
38	FM-0053453	Kern	Bakersfield Superior Court	15-A1	1	Plumbing - Water line restored, judge's chambers and clerk's offices scrubbed/dried out over 48 hour period. Small paint touch up to Clerk's office wall. In custody in Holding Cell #2 damaged water line to toilet (clean water) causing water intrusion to judge's chambers and clerk's offices.	3,047	\$ 1,909	62.64
			Bakersfield			HVAC - Replace burnt out supply fan motor, pulley w/hub and 2 new belts. Reconnect wiring to			
39	FM-0053487	Kern	Superior Court	15-A1	2	new motor. Burnt out supply fan motor not providing cooling to AHU 04.	\$ 2,699	\$ 1,691	62.64
			Arvin/ Lamont			Fire Protection - Fire curtain door at window 5 tension wheel assembly replaced and installed			
40	FM-0053951	Kern	Branch	15-H1	2	onto shutter. Fire curtain at window # 5 in clerk's office will not open.	\$ 2,731	\$ 1,663	60.91
41	FM-0047471	Lake	South Civic Center	17-B1	2	Exterior Grounds - Asphalt - Remove and replace approximately 13 Cubic Yards of damaged asphalt, fill 800 LF of cracks and seal the parking lot (approx 38000 SF). Work includes the installation of 20 lf concrete curb, 16 sf truncated domes, 1 bollard and striping.	\$ 55,421	\$ 55,421	100.00
42	FM-0052963	Lassen	New Susanville Courthouse	18-C1	2	Safety - Bullet Resistant Glazing - Remove and replace one (1) 4' x 2' Cracked Bullet Resistant Glass window in Judges Conference Room - A Bullet Resistant glass window is cracked and has lost its structural integrity, therefore can no longer perform its design function.	\$ 3,873	\$ 3,873	100.00
43	FM-0054087	Lassen	New Susanville Courthouse	18-C1	1	HVAC - Boiler 1 & 2 will not stay online, control boards have failed and the building cannot be heated. Replace control boards and add heat tape and windshield to unit housing to protect and help prevent reoccurrence.	\$ 2,000	\$ 2,000	100
44	FM-0054111	Lassen	New Susanville Courthouse	18-C1	1	Grounds and Parking Lot - Potential Hazardous Material Leak- contain and mitigate environmental hazard. Saw cut and hand demo 8'x8' area of concrete where the Glycol is seeping through concrete fissures and determine the source of the leak. Replace the leaking PVC couplers with Shark Bite brass couplers. Retrieve and properly dispose of ponded Glycol. Restore concrete to existing conditions.	10,000	\$ 10,000	100
			Pasadena Superior			Elevator - Elevator Renovation - Complete renovation of five (5) traction and two (2) hydraulic elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoist way entrance frames, doors and pit equipt., new AC gearless machines, microprocessor control systems, regenerative VVVF AC drives, fly ball governors, closed loop heavy duty high speed operators, current code required wiring, interior and lobby control panels, counterweights and roller guides, hoist and governor ropes, cab ceilings with LED down lights, rope compensation, new submersible pump units and underground cylinders encased in PVC for			
45	FM-0035537	Los Angeles	Court	19-J1	2	hydraulic elevators, and seismic provisions. Provide new air conditioning to the machine rooms.	\$ 3,893,560	\$ 3,163,518	81.25
						Plumbing - Replace Leaking 250 Gallon Water Heater in Rm. B27 - Needed to maintain the			
			El Monte			buildings potable hot water supply to all restrooms and entire facility for the comfort and			
46	FM-0036206	Los Angeles	Courthouse	19-01	2	cleanliness of the court.	\$ 40,828	\$ 23,729	58.12
			Torrance			Grounds-Replace broken curb (35 lf) and concrete (350 sf) causing trip hazard in parking lot,			
47	FM-0047040	Los Angeles	Courthouse	19-C1	2	caused by tree roots which need to be addressed during construction.	\$ 9,264	\$ 7,887	85.14

	<u> </u>	1	1	<u> </u>			1		1		1
						Elevator - Elevator Renovation - Complete renovation of eight (8) gearless traction elevators, six					
						3,000 lb capacity and two 8,000 lb capacity. Work will include but not be limited to, car frames					
						and platforms, buffers and safeties, hoist way entrance frames, doors and pit equipt., new AC					
						gearless machines, micro-processor control systems, regenerative VVVF AC drives, fly ball					
						governors, closed loop heavy duty high speed operators, current code required wiring, interior					
			Stanloy Mack								
40	ENA 004010C		Stanley Mosk	10 1/1	2	and lobby control panels, counterweights and roller guides, hoist and governor ropes, cab		2.054.000	ے ا	2 745 402	07.26
48	FM-0049106	Los Angeles	Courtnouse	19-K1		ceilings with LED down lights, rope compensation and seismic provisions.	\$	3,851,000	\$	3,745,483	97.26
						Interior Finish - Grind chipped and irregular floor and apply elastomeric filler to recessed areas					
		l	Airport			to bring floor to flush condition (Approximately 80 SF)Work is needed to prevent possible					
49	FM-0050722	Los Angeles	Courthouse	19-AU1	2	tripping hazard and maintain clean floor surface.	\$	8,810	\$	6,799	77.17
						Fire Protection - Replace 1,811 sprinkler heads throughout the 736,000 SF. facility that are					
			Stanley Mosk			painted over, some are more than 50 yrs old and found deficient during latest Fire Marshals					
50	FM-0052807	Los Angeles	Courthouse	19-K1	2	inspection. The sprinkler heads have failed U/L testing.	\$	215,621	\$	209,713	97.26
			Chatsworth			Electrical - Replace 120 UPS Batteries for Alarm System. Batteries failed and put system into					
51	FM-0052811	Los Angeles	Courthouse	19-AY1	1	alarm status.	\$	66,495	\$	55,723	83.80
						Interior Finishes - Frame and install a secured door to the back hallway to Judge's chambers					
			Stanley Mosk			#421. Currently the hallway is not secured to the public and the public waits by the chamber					
52	FM-0052813	Los Angeles	Courthouse	19-K1	2	doors while in line for the restroom, creating a safety situation.	\$	3,561	\$	3,561	100.00
			Clara Shortridge			Plumbing - Clear out main line to stop overflow onto cells, remove all debris from floor and					
			Foltz Criminal			disinfect entire area due to sewage water. 8th Floor main line back up causing sewage water to					
53	FM-0052817	Los Angeles	Justice Center	19-L1	1	come out floor drains on 4-cells.	\$	2,740	\$	1,885	68.79
						Plumbing - Replace cracked porcelain sink with stainless steel sink that complies with public and					
			Alhambra			safety standards. The porcelain sink in the holding cell is cracked presenting safety hazard for					
54	FM-0052818	Los Angeles	Courthouse	19-I1	2	the inmates and sheriff deputies if it breaks.	\$	4,795	\$	4,795	100.00
						Grounds - Cut and remove concrete that is causing the uneven surface. Pour new concrete and	<u> </u>	,		,	
			Compton			smooth out walkway area. Currently the concrete walkway and expansion joint is uneven					
55	FM-0052819	Los Angeles	•	19-AG1	2	causing a safety and trip hazard.	Ś	5,281	Ś	3,492	66.13
	1111 0002020	200711186165	Courtinouse	13 7.01			7	3,201	<u> </u>	3,132	00.13
			Clara Shortridge			Plumbing - Replace failed and angle stop to cell. Leaking down to 3rd floor public hallway.					
			Foltz Criminal			Secure water supply, contain area. Installed Add-a-valve to secure water supply and changed					
56	FM-0052823	Los Angeles	Justice Center	19-L1	1	out damage angle stop, seal pipe chase floor to prevent future leaks to lower floor.	ڔ	6,809	¢	4,684	68.79
30	1 101-0032823	LOS Aligeles	Justice Ceriter	19-61		Elevators, Escalators, & Hoists - Obstruction in Comteeth - Isolate the cause of the loud grinding	۲	0,803	٦	4,004	08.73
			Man Nunc								
	EN4 0053035		Van Nuys	10 472	2	sound at the 1st to 2nd floor escalator, found and removed a metal object wedged in the	۲ ا	2.024	ے ا	2 450	00.40
57	FM-0052825	Los Angeles	Courthouse West	19-AX2		comteeth, put the escalator back into operation.	\$	3,924	>	3,158	80.48
						Flouretone Faceletone 9 Hoiste Found 511 and 512 force and a devictor tribulation for a second state.					
			) / N			Elevators, Escalators, & Hoists - Found F11 and F12 fuses open, elevator trips loop overloaded					
	<b>5.4</b> 007007		Van Nuys	40.435		due to brake pick failure. Renovate 2TR relay, adjusted 2TR timer, tested operation and returned	۸ ا	0.405	_ ا	2 - 2 - 1	
58	FM-0052827	Los Angeles	Courthouse West	19-AX2	1	elevators to normal service. Public Elevator 1 & 2 not responding, sitting on main ground floor.	\$	3,182	\$	2,561	80.48
			Hall of Records-			COUNTY MANAGED - ELEVATOR - Replace Hydraulic elevator pump motor and starters Y and					
			County Records			Delta at Archives 222 N. Hill St., Los Angeles 90012. This is the Freight Elevator (1of 1). Non-			<b>.</b>		
59	FM-0052828	Los Angeles	Center	19-AV3	1	operating elevator is impacting Archive operations.	\$	6,500	\$	6,500	100.00
						Interior Finishes - Frame and install a secured door to the back hallway to Judge's chambers					
			Stanley Mosk			#321. Currently the hallway is not secured to the public and the public waits by the chamber					
60	FM-0052834	Los Angeles	Courthouse	19-K1	2	doors while in line for the restroom, creating a safety situation.	\$	5,433	\$	5,433	100.00

		1	T						1		
						Elevator - Furnish and install new fire rated door with laminate wood grain to match existing					
			Compton			doors and test for proper operation. Currently the elevator lobby is damaged and needs to be					
61	FM-0052836	Los Angeles	Courthouse	19-AG1	2	replaced due to the current condition does not present any fire rating.	\$	2,886	\$	1,909	66.13
			., .,			Interior Finishes - Install safety straps tight around columns to prevent from falling. Columns will					
			Van Nuys	1.0		be strapped every 5-8 feet. 50 ft columns have panels falling and some ready to fall causing a	_	10 -00			
62	FM-0052839	Los Angeles	Courthouse West	19-AX2	1	huge safety issue.	\$	12,762	\$	10,271	80.48
						Elevators, Escalators, & Hoists - Restore default memory, reset microprocessor and re-sync					
			Beverly Hills		_	position system by driving elevator to its lowest level to regain its default memory. Elevator #2	_				
63	FM-0052852	Los Angeles		19-AQ1	2	has lost its memory and the hoist way door keeps on cycling at the 4th floor.	\$	3,197	\$	2,542	79.52
			Parking Lot-San			Parking Lot / Resurface Jury parking lot. Currently the pavement/concrete throughout the					
			Fernando			parking lot is damaged, with numerous cracks and potholes scattered throughout the parking					
64	FM-0052854	Los Angeles	Courthouse Jury-	19-AC6	2	lot, creating tripping hazards along with tire damage to the cars.	\$	5,225	\$	4,358	83.41
						Elevators, Escalators, & Hoists - Clean contacts on selector, overload and dashpot oil low.					
			Van Nuys			Refilled oil and tested car and returned to service. Judges elevator #6 is stuck on 2nd floor not					
65	FM-0052855	Los Angeles	Courthouse East	19-AX1	1	responding, no entrapment.	\$	2,634	\$	2,634	100.00
						Elevators, Escalators, & Hoists - Shorten the hoist ropes and test operation under seismic or					
			Pomona			emergency conditions. The elevator did not pass the annual inspection and a preliminary order					
66	FM-0052856	Los Angeles	Courthouse South	19-W1	2	was written.	\$	4,578	\$	4,172	91.14
						Plumbing - Drained and isolated water pipe system, removed a 2" and 1-1/2" water valve that					
			_			were rusted/corroded. Installed new valves and re-filled system, checked for any leaks. Two					
			Bellflower			water valves were leaking water constantly in lock up pipe chases, water was penetrating to the					
67	FM-0052864	Los Angeles	Courthouse	19-AL1	1	floor below. Water was accumulating in pipe chases creating slipping and safety hazard.	\$	3,795	\$	2,958	77.94
						Electrical - Remove existing batteries and install lead acid batteries 8D. Install 24v charger in the					
			Metropolitan			generator and replace existing cable. Currently the batteries and cable are originals and need to					
68	FM-0052865	Los Angeles		19-T1	2	be replaced.	\$	4,938	\$	4,668	94.54
			Burbank			Fire Protection - Replace fire-fly IV (dropping device) on the fire door. Currently the fire door has					
69	FM-0052866	Los Angeles		19-G1	2	failed to drop when the fire alarm is on, creating a safety situation.	\$	4,834	\$	4,387	90.76
			Clara Shortridge								
			Foltz Criminal			Exterior Finishes - Remove and replace one (1) 4'x4' damaged piece of glass. High reach					
70	FM-0052868	Los Angeles	Justice Center	19-L1	2	equipment will be required to complete this work.	\$	2,360	\$	1,623	68.79
			Metropolitan			Elevators - Relays - Isolate the failures identified during the Reg 4 test on elevators 1-9, found					
71	FM-0052875	Los Angeles	Courthouse	19-T1	2	that multiple relays were failing and were replaced.	\$	3,724	\$	3,521	94.54
						HVAC - Failing Return Fan Motor - Remove and replace return blower motor and bearings, AHU					
			Pasadena			#6 is not operating due to the faulty return fan motor affecting the air flow on the 5th and 6th					
72	FM-0052880	Los Angeles	Courthouse	19-J1	2	floors.	\$	4,345	\$	3,013	69.35
			Metropolitan			HVAC - Bypass water on the chilled water system for the drinking fountains and recover					
73	FM-0052882	Los Angeles	Courthouse	19-T1	2	refrigerant. Floor#2, 3, 5, and 7. Currently there is no way to by-pass the failed chillers.	\$	5,616	\$	5,309	94.54
						Electrical - Replace the single wall day tank with a double wall tank and anchor it down to the					
						roof, install a monitoring device to insure no over flow or loss of fuel, replace all piping with new					
						stainless steel flex lines to bring the system up to code. Currently the day tank is a single wall					
			Metropolitan			tank with no alarm for high or low fuel and no leak detector. If the tank cracks it will leak fuel on					
74	FM-0052891	Los Angeles	Courthouse	19-T1	2	the roof creating a safety situation.	\$	10,585	\$	10,007	94.54
			Torrance			Vandalism - Strip doors and frames, sand and remove graffiti off doors, stain to match existing					
75	FM-0052893	Los Angeles	Courthouse	19-C1	2	and apply clear finish coat. Total of 25 doors and 5 frames.	\$	7,753	\$	6,601	85.14

						Fire Protection - Fire Alarm Wiring - Isolate and remove multiple shorts and ground faults in the					
7.6	514 0052004		Long Beach	40.74	•	wiring for the fire alarm panel. Currently there is intermittent trouble alarms due to the faulty		4044	,	2 727	75.50
/6	FM-0052894	Los Angeles	Courthouse	19-Y1	2	wiring. Interior Finishes - Water remediation, set up containments, installed new waterproof panel in	\$	4,944	\$	3,737	75.59
			Edmund D.			the janitorial mop sink area, install new drywall and repaint area. Water leaking through the 5th					
			Edelman			floor ceiling in the secure hallway between the restrooms, water coming from the 6th floor					
77	FM-0052896	Los Angeles	Children's Court	19-Q1	1	janitorial mop sink.	\$	5,858	Ś	4,100	69.99
	333233	2007				Plumbing - Replace faulty water valve under the women's jury restroom sink. Water	+	3,000	T	.,	05.55
			Torrance			remediation, set up ACM containment. Water impacted 2nd floor and down to Dept. H and					
78	FM-0052897	Los Angeles	Courthouse	19-C1	1	judges chamber.	\$	6,616	\$	6,616	100.00
						Electrical - Drain coolant from Generator, re-core radiator, replace, all hoses and connectors to		·			
						generator, and refill with new coolant. Currently the generator radiator is leaking coolant which					
			Metropolitan			is causing a safety situation when the generator were to be used in an emergency and it over					
79	FM-0052899	Los Angeles	Courthouse	19-T1	2	heats due to the coolant being low.	\$	31,711	\$	29,980	94.54
						Elevator - Remove and replace defective solid state starter. Currently the broken solid state					
			Santa Monica			starter is disabling the elevator, leaving the court with no working elevators for the public					
80	FM-0052900	Los Angeles	Court Annex	19-AP3	1	causing a ADA compliance issue.	\$	2,565	\$	2,013	78.49
						Plumbing - Replace failed piping and remediate ACM contamination. Replace 5 ft of 3 inch cast					
						iron waste pipe and coupling and 2 ft of 2 inch waste pipe, comby and coupling. Water					
						remediation, set up containments, HEPA vacuum, disinfect. Dehumidifiers and fans were placed					
04	ENA 0053006	l oo Amerika	Pasadena	10.11	4	to remove moisture in the leak affected areas. 3rd floor men's restroom drain line leaked into	۲,	46 702	۸	22.442	CO 25
81	FM-0052906	Los Angeles	Courtnouse	19-J1	1	2nd floor.  Plumbing - Replace punctured backflow to Cooling Tower #1. Currently the backflow has a hole	\$	46,782	\$	32,443	69.35
			Chatsworth			in the body and could leak at anytime, which would affect the water flow to the cooling tower					
82	FM-0052908	Los Angeles		19-AY1	2	effecting major operation of cooling.	¢	4,944	¢	4,143	83.80
02	1101-0032308	LOS Aligeles	Courtifouse	IJ-AII		HVAC - Remove and replace (2) leaking 4" gate valves in the AHU room. This work was	7	4,344	7	4,143	03.00
			Bellflower			completed as a P1 emergency due to the floor being constantly wet with pool water, creating a					
83	FM-0052917	Los Angeles		19-AL1	1	slipping and safety hazard.	Ś	3,371	Ś	2,627	77.94
							T		7	_,=:	77.0
l						HVAC - Replace leaking pipes and valves on Cooling Towers #1 and #2. Return and supply lines					
			Downey			have rust spots on the pipes which could spring a leak at any moment. Valves need to be					
84	FM-0052918	Los Angeles	Courthouse	19-AM1	2	replaced, they are almost frozen, very hard to turn, safety concern, possible flooding.	\$	21,598	\$	18,078	83.70
			Parking Structure-								
			Lot 53 Pasadena			Grounds and Parking Lot - Replace leaking 3" dry control valve. Dry standpipe control valve is					
85	FM-0052920	Los Angeles	Court-	19-J3	2	leaking, not holding pressure.	\$	5,146	\$	3,569	69.35
			Edmund D.								
			Edelman			Parking Lot / Replace broken cables and straighten bent panels on the Sheriff's sally port gate.					
86	FM-0052924	Los Angeles	Children's Court	19-Q1	2	One of the cables broke causing one side of the door to fall, damaging the panels.	\$	3,933	\$	2,753	69.99
						HVAC - Remove and replace damages parts (bearings, blower wheels, shaft, & B85 belts) from					
			"			Air Handler Unit. Currently the basement exhaust fan has a broken drive shaft and is non-					
	EN 4 0053036	1.55 4	Norwalk	10 414	_	operational. Air in the basement is not being exhausted properly and this is a safety and health	_	0.200	_	7.000	05.00
87	FM-0052926	Los Angeles		19-AK1	2	hazard.  Plumbing Penlace malfunctioning floats and remove the debris from the sewage injector	<b>\</b>	9,399	\$	7,992	85.03
			Parking Structure-			Plumbing - Replace malfunctioning floats and remove the debris from the sewage injector					
00	EM 0052027	Loc Angoloc	El Monte	10.03	า	pumps. The sewage injector pumps were operating continuously due to malfunctioning floats	۲	<i>1</i> E70	۲	2 661	E0 12
88	FM-0052937	Los Angeles	Courthouse- Chatsworth	19-02		and high amount of debris in the sewage pit.  HVAC - Replace Worn Gear Reducing Transmission. Gear Reducing Transmission causing	\$	4,579	۶ ا	2,661	58.12
QΩ	FM-0052940	Los Angeles		  10_AV1	2	vibration, might break down and fail, effecting cooling system.	ر	/12 17/	ć	26 1 <u>9</u> 0	02 0N
69	rivi-0052940	Lus Angeles	Courtilouse	19-AY1		Initiation, might break down and fail, effecting cooling system.	P	43,174	Ą	36,180	83.80

			Pasadena			Elevators, Escalators, & Hoists - Remove worn out bearings and install new bearings sheave.					
90	FM-0052953	Los Angeles		19-J1	1	Judge's elevator #5 was out of service, bearing sheave worn out need to be replace/repair.	\$	14,960	Ś	14,960	100.00
		8.0	Burbank			Plumbing - Install water heater. Currently there is no hot water in over 50 percent of the	•	,	'	,	
91	FM-0052954	Los Angeles		19-G1	1	courthouse which is a safety and health concern.	\$	6,181	\$	5,610	90.76
		8 2 2				Electrical - Door detector edge on elevator #1 - Remove and replace the failed door detector	•	-, -	'		
						edge, damaged cable and transformer in the control monitor mother board. Currently the					
			Inglewood			elevator is not working due to the cable for the door edge snapped causing the door edge to fail					
92	FM-0052955	Los Angeles		19-F1	1	and the mother board to short out.	\$	5,618	\$	4,189	74.56
							T		Т	,,	
			Van Nuys			Plumbing - Set up containment, repair 2' cast-iron drain line that is cracked and leaking into the					
93	FM-0052956	Los Angeles	Courthouse West	19-AX2	1	10th floor D.A.'s secure hallway (southeast corner), which is creating a slip hazard.	\$	8,000	\$	6,438	80.48
		J	Parking Structure					,	'	,	
			Lot 94 Airport			Elevators, Escalators, & Hoists - Replace failed seal and pressure test the system. Elevator has a					
94	FM-0052958	Los Angeles	Courthouse	19-AU2	1	bad packing seal to piston.	\$	6,904	\$	5,328	77.17
			Clara Shortridge				•	,	'	,	
			Foltz Criminal			Plumbing - Set up containment, test, and secure water supply with add-a-valve and replace					
95	FM-0052960	Los Angeles	Justice Center	19-L1	1	damaged plumbing. Water leaking through the Dept 33 ceiling.	\$	7,978	\$	5,488	68.79
		J						,		,	
			Metropolitan			HVAC - Replace two existing pneumatic valves and associated piping on the 3rd and 8th floor.					
96	FM-0052961	Los Angeles	Courthouse	19-T1	2	Currently the existing valves are leaking water in the AHU rooms, creating a slip hazard.	\$	7,119	\$	6,730	94.54
						Elevator - Remove and replace with new elevator entry doors. Currently the stainless steel door	<u> </u>	,		,	
			Airport			skin is failing and its delaminating causes the doors to get hung up on the hoist way and will					
97	FM-0052964	Los Angeles	·	19-AU1	2	cause entrapments.	\$	8,231	\$	6,352	77.17
			Torrance			HVAC - Replace exhaust fan motor on kitchen hood. Currently the kitchen is very hot due to the		·		·	
98	FM-0052987	Los Angeles	Courthouse	19-C1	1	kitchen exhaust is not functioning properly.	\$	5,000	\$	4,257	85.14
						HVAC - Replaced failed VAV controls in Dept K. Currently the supply air is a 77 degrees for the		·		·	
			Pasadena			4th floor and not dropping to a cooler temperature which is creating a uncomfortable work					
99	FM-0052989	Los Angeles	Courthouse	19-J1	1	environment for the court employees.	\$	5,000	\$	5,000	100.00
			Clara Shortridge			Plumbing - Replace failed hardware for hot water supply to Air Handing Unit 14-3. Currently					
			Foltz Criminal			there is water dripping from the pneumatic actuator valve. Set up containment, abatement of					
100	FM-0052990	Los Angeles	Justice Center	19-L1	1	ACM insulation and wrapping.	\$	20,000	\$	13,758	68.79
						Plumbing - Replace failed drain line. Contain ACM area and repair water damaged areas					
			Van Nuys			required for court access. Currently water is dripping into the 10th floor District Attorney					
101	FM-0052991	Los Angeles	Courthouse West	19-AX2	1	hallway.	\$	10,000	\$	8,048	80.48
			Airport			Elevators - Replace bad S1O Board and Bad Power Supply. Elevator #1 is not function without a					
102	FM-0052993	Los Angeles	Courthouse	19-AU1	2	new S10 board and power supply.	\$	7,467	\$	5,762	77.17
			Van Nuys			HVAC - Replace fan motor on Cooling Tower #1. Currently cooling tower is not functioning which					
103	FM-0052997	Los Angeles	Courthouse West	19-AX2	1	is making the courthouse temperatures rise.	\$	10,000	\$	8,048	80.48
						HVAC - Replace Variable Frequency Drive (VFD) for Air Handler Unit #1. Currently the circuit					
			Bellflower			board for the supply VFD is faulty and the drive will not ramp up or down causing high air flow					
104	FM-0052998	Los Angeles	Courthouse	19-AL1	1	from the air duct.	\$	10,000	\$	7,794	77.94
			Stanley Mosk			HVAC - Replace a failing seam on the ductwork insulation. Contain and abate ACM					
105	FM-0052999	Los Angeles	Courthouse	19-K1	1	contaminants. Condensation was leaking above the ceiling tile on the 4th floor in room 425C.	\$	10,000	\$	9,726	97.26



HVAC - Replace condenser pump for the split system in the communication room. Currently the split system is not functioning causing the server room to become hot which could affect the comptons.  Inglewood	100.00 74.56 66.13 97.26
FM-0053000   Los Angeles   Courthouse   19-AK1   1   computer equipment for the courthouse.   \$ 5,000 \$ 5,000	74.56 66.13 97.26
HVAC - Replace the motor and motor starter on Air Compressor #1. Currently the motor contactor and motor grounded out on the pneumatic air compressor. The dampers on all AHUS are closed and no cooling can be provided to the courthouse.    107 FM-0053001   Los Angeles   Courthouse   19-F1   1   are closed and no cooling can be provided to the courthouse.   \$ 10,000 \$ 7,456	74.56 66.13 97.26
Inglewood Los Angeles Courthouse 19-F1 1 are closed and no cooling can be provided to the courthouse. \$ 10,000 \$ 7,456  Plumbing - Replace 7 feet of 4" cracked drain pipe inside pipe chase of Department O lock-up on the 12th floor, ACM and bacterial clean up of floors 7-12, and build back affected areas. Water dripping from the 12 floor all the way down to the 7th floor. \$ 17,723 \$ 11,720  Plumbing - Replace 2 failed toilets, replace damaged ceiling tiles, set up and maintain ACM containment on the 9th - 12th floors. System failure on the 12th floor caused leaking all the way down to the 9th floor causing a health and safety hazard throughout the courthouse. \$ 19,091 \$ 12,625  Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  105 FM-0053016 Los Angeles Courthouse 19-K1 1 has coolant leaking into head assembly and in oil sump, governor not regulating speed. \$ 42,226 \$ 41,069  Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	66.13 66.13
107 FM-0053001 Los Angeles Courthouse 19-F1 1 are closed and no cooling can be provided to the courthouse. \$ 10,000 \$ 7,456    Plumbing - Replace 7 feet of 4" cracked drain pipe inside pipe chase of Department O lock-up on the 12th floor, ACM and bacterial clean up of floors 7-12, and build back affected areas. Water dripping from the 12 floor all the way down to the 7th floor. \$ 17,723 \$ 11,720    Plumbing - Replace 2 failed toilets, replace damaged ceiling tiles, set up and maintain ACM containment on the 9th - 12th floors. System failure on the 12th floor caused leaking all the way down to the 9th floor causing a health and safety hazard throughout the courthouse. \$ 19,091 \$ 12,625    Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  110 FM-0053016 Los Angeles Courthouse 19-K1 1 has coolant leaking into head assembly and in oil sump, governor not regulating speed. \$ 42,226 \$ 41,069    Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	66.13 66.13
Plumbing - Replace 7 feet of 4" cracked drain pipe inside pipe chase of Department O lock-up on the 12th floor, ACM and bacterial clean up of floors 7-12, and build back affected areas. Water dripping from the 12 floor all the way down to the 7th floor.  Plumbing - Replace 2 failed toilets, replace damaged ceiling tiles, set up and maintain ACM containment on the 9th - 12th floors. System failure on the 12th floor caused leaking all the way down to the 9th floor causing a health and safety hazard throughout the courthouse.  Plumbing - Replace 2 failed toilets, replace damaged ceiling tiles, set up and maintain ACM containment on the 9th - 12th floors. System failure on the 12th floor caused leaking all the way down to the 9th floor causing a health and safety hazard throughout the courthouse.  Flectrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  has coolant leaking into head assembly and in oil sump, governor not regulating speed.  FM-0053016 Los Angeles Courthouse 19-K1 1 has coolant leaking into head assembly port entrance gate. The sally port gate was struck by a police	66.13 66.13
the 12th floor, ACM and bacterial clean up of floors 7-12, and build back affected areas. Water    108 FM-0053014	66.13 97.26
108 FM-0053014   Los Angeles   Courthouse   19-AG1   1   dripping from the 12 floor all the way down to the 7th floor.   \$   17,723   \$   11,720	66.13 97.26
Plumbing - Replace 2 failed toilets, replace damaged ceiling tiles, set up and maintain ACM compton  Compton  Compton  Courthouse  19-AG1  1 down to the 9th - 12th floors. System failure on the 12th floor caused leaking all the way down to the 9th floor causing a health and safety hazard throughout the courthouse.  Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  Los Angeles  Courthouse  19-K1  1 has coolant leaking into head assembly and in oil sump, governor not regulating speed.  Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	66.13 97.26
Compton Courthouse  109 FM-0053015 Los Angeles  Courthouse  19-AG1  1 down to the 9th - 12th floors. System failure on the 12th floor caused leaking all the way down to the 9th floor causing a health and safety hazard throughout the courthouse.  Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  10 FM-0053016 Los Angeles  Courthouse  19-K1  1 has coolant leaking into head assembly and in oil sump, governor not regulating speed.  Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	97.26
Compton Courthouse  109 FM-0053015 Los Angeles  Courthouse  19-AG1  1 down to the 9th - 12th floors. System failure on the 12th floor caused leaking all the way down to the 9th floor causing a health and safety hazard throughout the courthouse.  Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  10 FM-0053016 Los Angeles  Courthouse  19-K1  1 has coolant leaking into head assembly and in oil sump, governor not regulating speed.  Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	97.26
109 FM-0053015 Los Angeles Courthouse 19-AG1 1 down to the 9th floor causing a health and safety hazard throughout the courthouse. \$ 19,091 \$ 12,625    Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  110 FM-0053016 Los Angeles Courthouse 19-K1 1 has coolant leaking into head assembly and in oil sump, governor not regulating speed. \$ 42,226 \$ 41,069    Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	97.26
Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2  110 FM-0053016 Los Angeles Courthouse 19-K1 1 has coolant leaking into head assembly and in oil sump, governor not regulating speed. \$ 42,226 \$ 41,069  Pasadena Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	97.26
Stanley Mosk 110 FM-0053016 Los Angeles Courthouse Pasadena Stanley Mosk 120 Pasadena Stanley Mosk 130 Pasadena Stanley Mosk 140 Pasadena Stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2 150 Pasadena Stanley Mosk 150 Pasadena Stanley Mosk 160 Pasadena Stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2 150 Pasadena Stanley Mosk 160 Pasadena Stanley Mosk 170 Pasadena Stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2 150 Pasadena Stanley Mosk 160 Pasadena Stanley Mosk 160 Pasadena Stanley Mosk 160 Pasadena Stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2 160 Pasadena Stanley Mosk 160 Pasadena Stanley Mosk 170 Pasadena St	
Stanley Mosk 110 FM-0053016 Los Angeles Courthouse Pasadena Stanley Mosk 120 Pasadena Stanley Mosk 130 FM-0053016 Los Angeles Courthouse Pasadena Stanley Mosk 140 Stanley Mosk 150 Stanley Mosk 160 Stanley Mosk 160 Stanley Mosk 170 Stanley Mosk 180 Stanley Mosk 190 Stanley Mosk	
110 FM-0053016 Los Angeles Courthouse 19-K1 1 has coolant leaking into head assembly and in oil sump, governor not regulating speed. \$ 42,226 \$ 41,069 Pasadena Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	
Pasadena Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	
	100 00
111 FM-0053023   Los Angeles   Courthouse   19-J1   1   vehicle and is badly damaged. The gate will not secure which a security issue.   \$ 10,000   \$ 10,000	
Interior Finishes Departure count alors etations in departure and 100 Count IT about a	100.00
Interior Finishes - Renovate court clerk stations in departments 101 and 102. Court IT changes	1
require work station renovation to facilitate additional hardware for court clerk. Work will also	1
Van Nuys eliminate existing ergonomic issues related to document transfer between the judges and	
112   FM-0053027   Los Angeles   Courthouse West   19-AX2   2   clerks.   \$ 4,719   \$ 3,798	80.48
HVAC - Chiller #1 is shutting down on high head pressure - Descaled all corroded chiller tubes,	1
Compton replaced the head gaskets and returned chiller into service. The non operating chiller has caused	1
113 FM-0053028 Los Angeles Courthouse 19-AG1 1 temperatures in the courthouse rise. \$ 6,000 \$ 3,968	66.13
HVAC / Replace failed and leaking pressure relief valves to comfort heating boilers. ACM	1
East Los Angeles containment and disposal. Currently water is dripping from the 5th floor mechanical room down	1
114 FM-0053029 Los Angeles Courthouse 19-V1 1 to the 4th floor Judge's chamber 418C and Deputies Gym room 417. \$ 10,000 \$ 7,772	77.72
Clara Shortridge	1
Foltz Criminal Plumbing / replace cracked 2" waste line utilizing lift, includes ACM containment and	1
115 FM-0053423 Los Angeles   Justice Center   19-L1   1   environmental testing.         \$ 20,000   \$ 13,758	68.79
Electrical - Emergency Generator Fuel Leak - Replaced a defective gaskets and tightened all fuel	1
Compton lines. Diesel fuel was discovered inside the generator engine block and oil pan during the	1
116 FM-0053424 Los Angeles   Courthouse   19-AG1   1   emergency generator PM.         \$ 10,000   \$ 6,613	66.13
Michael D.	
Antonovich	1
Antelope Valley Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from	1
117 FM-0053426 Los Angeles Courthouse 19-AZ1 1 the floor drains and causing slip hazard to the kitchen workers. \$ 10,000 \$ 7,351	73.51
Glendale HVAC - Replace Shaft Seals, Head Gaskets and O-Rings on compressor. Remove and replace	
118 FM-0053432 Los Angeles Courthouse 19-H1 1 Motor Control Center (MCC). AHU #3 has refrigerant leak, no signal from MCC, not cooling. \$ 79,300 \$ 71,798	90.54
Stanley Mosk Elevators, escalators, & hoist - Public elevator #3 - Remove and replace bad bearings on the	
119 FM-0053436 Los Angeles Courthouse 19-K1 2 generator set, the elevator is out of service due to leveling issues. \$ 35,651 \$ 34,674	97.26

	T										
						Electrical - Replace 2500 amp breaker - Currently a 2500 amp breaker at the main panel is not					
			Edmund D.			resetting properly, this breaker controls the power to the penthouse on the roof where the					
			Edelman			chiller plant and boiler plants are located. If the breaker trips there is high probability that it will					
120	FM-0053445	Los Angeles	Children's Court	19-Q1	2	not reset and the court will lose the cooling and heating to the building.	\$	18,285	Ś	12,798	69.99
			Edmund D.			Fire Protection - Replace one set of fire doors with new 45 min rated fire doors to meet code.	7		7	,	
			Edelman			Currently the fire doors have a crack on the side of the doors and they do not meet the fire					
121	FM-0053446	Los Angeles	Children's Court	19-Q1	2	code.	\$	5,301	\$	3,710	69.99
								· · · · · · · · · · · · · · · · · · ·			
			Pomona			HVAC - Disassemble Chiller #1 and replace seals, gaskets, and O-rings. Chiller #1 leaks thru					
122	FM-0053454	Los Angeles	Courthouse South	19-W1	2	deteriorated seals, gaskets, and O-rings. Chiller #1 is not operational due to the refrigerant leaks.	\$	25,031	\$	22,813	91.14
						HVAC - Replacement of the (2) existing chillers at the Pasadena Court. Includes: new VFD drives,					
						design/engineering, plan check, permits, inspections, new Refrigerant Monitoring System,					
			Pasadena			exhaust fans, ACM abatement, interim P1 chiller maintenance, and engineering is being					
123	FM-0053465	Los Angeles	Courthouse	19-J1	2	completed.	\$	899,772	\$	623,992	69.35
						Plumbing - Repair leaking hot water domestic pipe (3/4" Copper Pipe) includes ACM					
			Downey			containment and environmental testing. Currently there is water leaking from the ceiling into					
124	FM-0053466	Los Angeles		19-AM1	1	the 1st floor clerk's area.	\$	10,000	\$	8,370	83.7
			Edmund D.								
			Edelman		_	Plumbing / Cracked water pipe. Currently water is dripping from the ceiling into the 2nd floor					
125	FM-0053467	Los Angeles	Children's Court	19-Q1	1	secured hallway causing a hazard the employees.	\$	10,000	\$	6,999	69.99
			La alaccia a d			LINAC Banks a vetum sheft and from touch back bearings on ALILL #2 and balance not me for					
126	ENA 0052474		Inglewood	10.51	4	HVAC - Replace return shaft and front and back bearings on AHU #2 and balance return fan.	۸	10.000	۲ ا	7.456	74.56
126	FM-0053471	Los Angeles	Courthouse	19-F1		Currently the 3rd floor has no return air and it is affecting the temperature on the entire floor.	Ş	10,000	\$	7,456	74.56
			West Covina			County Managed - HVAC - Install four ductless air-conditioning systems in hallway to ensure the					
127	FM-0053472	Los Angeles		19-X1	2	court with adequate cooling in a consistent warm part of the building throughout the year.	ċ	84,255	¢	84,255	100.00
127	1101-0055472	LOS Aligeles	Courtifouse	IJ-XI		court with adequate cooling in a consistent warm part of the ballaing throughout the year.	7	04,233	7	04,233	100.00
			Compton			HVAC - Replace defective VFDs to the return fans on the 10th and 12th floors. Currently both of					
128	FM-0053478	Los Angeles	<u>'</u>	19-AG1	2	the return fans are running at 100% causing air flow to be unbalanced and wasting energy.	Ś	5,883	Ś	3,890	66.13
	3333 173	200780.00				HVAC - Remove and Replace (1) 15 HP VFD. Currently the VFD drive is tripping on common lose	7	3,000	<u> </u>	3,030	33.23
			Chatsworth			and DC over load, effecting major operation of cooling for all floors in the southeast side of the					
129	FM-0053479	Los Angeles	Courthouse	19-AY1	2	building.	\$	5,460	\$	4,575	83.80
			Michael D.					· · · · · · · · · · · · · · · · · · ·			
			Antonovich			Plumbing - Failing Sewage Pump - Replace discharge piping on Pump #1 & #2 and replace floats.					
			Antelope Valley			Sewage ejector pump went into high level alarm; Sewage pit pumps not working and sewage is					
130	FM-0053480	Los Angeles	Courthouse	19-AZ1	1	building up in the pit.	\$	14,392	\$	10,580	73.51
						Plumbing - Shut off and drain entire building, replace dual backflow preventers and isolation					
			Clara Shortridge			valves, restore water service to the building and restart buster pumps. The dual domestic water					
			Foltz Criminal			backflow preventers did not pass annual inspection and the isolation valves are bypassing water					
131	FM-0053481	Los Angeles	Justice Center	19-L1	2	when in the close position.	\$	24,032	\$	16,532	68.79
						Plumbing - Demo and build back of wall after replacing cracked pipe, includes ACM containment					
			Van Nuys			and environmental testing. Currently water is dripping from the angle-stop in the wall of the		_			
132	FM-0053483	Los Angeles	Courthouse East	19-AX1	1	woman's restroom onto the floor under the sink in the restroom creating a slip hazard.	\$	12,000	<b>Ş</b>	10,769	89.74

						HVAC - Replace failed piping on condensate for the AHU includes ACM containment, leak					
			Pasadena			remediation equipment and environmental testing. Currently there is condensate water leaking					
133	FM-0053484	Los Angeles	Courthouse	19-J1	1	through the roof into room 209.	\$	10,000	\$	6,935	69.35
			Compton			Exterior Shell - Repair concrete and sure railing. Currently the exterior ledge railing located on		·	-		
134	FM-0053486	Los Angeles	Courthouse	19-AG1	2	the Westside of the building has broken concrete causing a safety hazard.	\$	4,944	\$	3,269	66.13
						Plumbing - Remove and replace all defective wye strainer and pressure reducer valves.					
			Chatsworth			Currently the water pressure is not regulated throughout the building and could cause the main					
135	FM-0053488	Los Angeles	Courthouse	19-AY1	2	pipes to break down, causing a flood.	\$	7,763	\$	6,505	83.80
						Interior Finishes - Replace defective vinyl floor tiles approx. 60 sq ft. Currently the vinyl tile					
			Compton			flooring is breaking and coming up off the floor. It is causing a trip and safety hazard on					
136	FM-0053489	Los Angeles		19-AG1	2	occupants.	\$	3,017	\$	1,995	66.13
			Edmund D.			Exterior Shell - Replace (2) 9' 11" x 9'7" heavy duty steel rolling doors with double angle foot					
			Edelman			piece and new motor operators with eclectic miller safety edges. Currently the rolling doors			١.		
137	FM-0053490	Los Angeles	Children's Court	19-Q1	2	have broken spring and are not working properly.	\$	13,239	\$	9,266	69.99
			Clara Shortridge			Fire Protection - Repair (35) pull stations that failed to activate alarm during annual test and (1)					
1.00			Foltz Criminal		_	fire bell that sounded poorly. This repairs must be completed before the annual fire alarm test					22 -2
138	FM-0053491	Los Angeles	Justice Center	19-L1	2	can be completed due to it being a safety issue.	\$	16,375	\$	11,264	68.79
			C 1			Plumbing - Replace defective sump pump and test for proper operation. Currently one of the					
420	EN 4 00E 2 400		Compton	10.464	2	sump pumps for storm water has failed and must be replaced. Heavy rain or any other form of	<u> </u>	44.624	_ ا	0.677	66.42
139	FM-0053498	Los Angeles		19-AG1		heavy water going into basement area could cause flooding in Basement.	\$	14,634	\$	9,677	66.13
			Clara Shortridge			Elevator - Install generator start up controls to all 23 elevators. This installation must be					
440	EN 4 00E 2 400		Foltz Criminal	10.14	2	completed to make sure the generator transfers power to the elevators in case of an emergency	<u> </u>	6 572	_ ا	4.522	60.70
140	FM-0053499	Los Angeles	Justice Center	19-L1		as per the State Inspector and Fire Marshall. (Compliance Issue)	\$	6,573	\$	4,522	68.79
1 1 1	EN4 0052500		Compton	10 461	2	Parking Lot - Install up to 50 feet of new 6" no hub piping. Currently the storm drain is cracked	۲	F F70	۲ ا	2 602	CC 12
141	FM-0053500	Los Angeles	Courtnouse	19-AG1		and the water drips on the cars parked in the parking garage.	<b>&gt;</b>	5,570	\$	3,683	66.13
						HVAC - Replace shaft and bearing on Air Handler Unit #9. Currently the Air Handler is being					
			Metropolitan			controlled manually and the motor had to be ramped down so no further damage would take					
1/12	FM-0053501	Los Angeles	•	19-T1	2	place. This repair is necessary due to this air handler provides air to the entire 8th floor.	ر	11,845	ر	11,198	94.54
142	1 101-0033301	LOS Aligeles	Courtilouse	19-11		Elevators - Replace chicken legs for elevator #2 at the 2nd & 3rd floors and elevator #3 at the	٦	11,043	٦	11,196	34.34
			Santa Monica			3rd floor. This repair must be completed to ensure the doors close as intended per DIR					
143	FM-0053504	Los Angeles		19-AP1	2	preliminary orders.	\$	4,581	ς .	3,596	78.49
143	1101 0033304	LO3 Angeles	Courtiflouse	13 Al I		HVAC - Install new bearings and sleeve on the blower shaft, remove deteriorated piping and	7	7,301	7	3,330	70.43
						replace with new copper piping. Remove frozen isolation valves and replace with new butterfly					
			Clara Shortridge			valves. Replace Chilled Water line and insulation on the Chilled Water line. AHU 14-2 Vibrating					
			Foltz Criminal			due to worn shaft and bearings on the blower, vibration caused water leak on Chilled Water					
144	FM-0053506	l os Angeles	Justice Center	19-L1	1	piping, 2 isolation valves found seized and replaced.	Ś	35,500	Ś	24,420	68.79
	0033300	2007.1186.60	Justice Center	13 11		Plumbing - Replace failed and corroded flush valve assembly & pipe from above ceiling area.	7	33,300	7	2 1, 120	00.73
						Water remediation, set up containments, disinfect area. Dehumidifiers and fans were placed to					
			Clara Shortridge			remove moisture in the leak affected area. Install new 1-1/2" Pneumatic Flush Valve Assembly,					
			Foltz Criminal			new pipe with fittings. Remove damage ceiling and build back. Water Leak/Flood on 3rd fl Dept.					
145	FM-0053507	Los Angeles	Justice Center	19-L1	1	41.	\$	21,987	\$	15,125	68.79
5			Clara Shortridge		<del>-</del>	Plumbing - Install (3) VFDs, Pump Repairs, Pressure Sensors. Hot water pumps are leaking,		,_,		,	
			Foltz Criminal			pumps run 100% due to no VFD's. If pumps not repaired there will be no hot water to entire					
146	FM-0053508	Los Angeles	Justice Center	19-L1	1	building.	\$	47,144	\$	32,430	68.79
			Compton			HVAC - Clean tubes on Chiller #2, repair leaks, install new purge pump. Chiller is not working,	-	•	<u> </u>	,	
147	FM-0053509	Los Angeles	<u> </u>	19-AG1	1	building is hot.	\$	58,602	\$	38,754	66.13
l	1	_,				-				·	

						HVAC - Replace leaking valve on reheat coil above ceiling includes ACM containment and					
1			Bellflower			environmental testing. Demo and rebuild failing ceiling areas . Water was dripping through the					
148 FI	M-0053510	Los Angeles		19-AL1	1	ceiling into the Woman's public restroom creating a slip hazard.	Ś	10,000	Ś	7,794	77.94
						Same and the same	1		т	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
1						HVAC / Rebuild leaking chilled water pump #23 includes ACM containment and environmental					
1			Stanley Mosk			testing and abatement. Currently water is leaking through the seals and this is the second of the					
149 FI	M-0053511		Courthouse	19-K1	1	three pumps available to circulate chilled water through the cooling loop for the HVAC.	Ś	10,000	Ś	9,726	97.26
	0000011	200780.00				HVAC - Replace leaking valve on reheat coil above ceiling includes ACM containment and	+		7	3,7.20	37.20
1			Bellflower			environmental testing and abatement. Water was dripping through the ceiling into the court					
150 FI	M-0053512	Los Angeles		19-AL1	1	reporters office creating a safety hazard.	Ś	10,000	ς	10,000	100
130 11	101 0033312	2037 tilgeres	Courtifouse	IJ / LI		Plumbing / Set-up containment, drying equipment, and conduct environmental testing.	+	10,000	7	10,000	100
1			Van Nuys			Currently water is dripping from the ceiling into the secure hallway on the 10 floor creating a					
151 EI	M-0053513	Los Angeles	Courthouse West	19-AX2		safety hazard.	١	10,000	¢	8,048	80.48
131 11	141-0033313	LO3 Aligeles	Courtifouse West	1J-AAZ		Plumbing / Replace failed 90 degree elbow behind the wall of the sink includes ACM	+	10,000	7	8,048	00.40
1			Stanley Mosk			containment and environmental testing. Currently water is dripping down from the 7th floor to					
152 5	M-0053514	Los Angeles	•	19-K1	1	the 5th floor, room 546 court counsel room, damaging the ceiling tiles.	ċ	10,000	ر	10,000	100
132 [7]	101-0033314	LOS Aligeles	Courtilouse	19-11		Plumbing - Replace failed seal on janitors sink area on the second floor and replace	+	10,000	ې	10,000	100
1						damaged/fallen ceiling tiles includes ACM containment and environmental testing. Water					
1			Inglowood								
152 5	N4 00F2F4F	Los Angolos	Inglewood	10.51	1	spilled from Janitor's sink and the water leaked through to the 1st floor ceiling causing ceiling	ے ا	10 000	۲	7.456	74.56
133 F	M-0053515	Los Angeles	Courthouse	19-F1		tiles to fall on the lobby floor.  Plumbing - Replace cracked drain pipe includes ACM containment and environmental testing.	<del>                                     </del>	10,000	Ş.	7,456	74.56
1			Nomicalle								
1454 51	NA 005254 <i>C</i>		Norwalk	10 41/4		Janitor closet on the 4th floor has cracked drain pipe, leaking water into 3rd floor secured	<u>_</u>	40.000	ے ا	0.503	05.03
154   FI	M-0053516	Los Angeles		19-AK1	1	hallway.	\$	10,000	\$	8,503	85.03
1			Clara Shortridge			Plumbing - Set up sump pumps in tunnel to drain water, set up containment in lower gym, test					
1   - (			Foltz Criminal	40.14	4	for ACM, repairs were completed by County ISD. Steam leak (Flex line) in tunnel causing leak in		4.006		2 227	60.70
155 F	M-0053524	Los Angeles	Justice Center	19-L1	1	lower gym room B-302.	\$	4,836	\$	3,327	68.79
1											
1						Plumbing / Set-up containment & drying equipment, conduct environmental testing, and					
			Stanley Mosk		_	insulate vent duct that is sweating causing a leak in the ceiling. This work was completed as a P1					07.00
156 FN	M-0053526	Los Angeles	Courthouse	19-K1	1	emergency due to water leaking through the ceiling tiles above the entrance of room 258.	\$	8,937	\$	8,692	97.26
1						Plumbing / Replace failed Sloan valve assembly includes ACM containment and environmental					
1			Clara Shortridge			testing, vacuum all water in Dept.121 and sanitize carpet dry. Toilet continuously flushing					
1			Foltz Criminal			causing water to flood the jury room, courtroom, and water to leak down to the 12 floor					
157 FN	M-0053527	Los Angeles	Justice Center	19-L1	1	hallway.	<u></u> \$	10,087	\$	6,939	68.79
1						Fire Protection - Replace fire pump motor, batteries, wiring, battery cables, and auto relays 3D5					
1						& 4D2. This work was completed as a P1 emergency due to the motor starter failing (burning					
1			Compton			up) causing the batteries and battery cables to fail as well as other wiring inside fire pump					
158 FI	M-0053530	Los Angeles	Courthouse	19-AG1	1	control cabinet.	\$	14,994	\$	9,916	66.13
1						Holding Cell - Set-up containment and drying equipment, conduct environmental testing, secure					
1			Clara Shortridge			water to cell #8, and auger/clear clogged toilet to stop water from overflowing. This work was					
1			Foltz Criminal			completed as a P1 due to an inmate clogging his cell toilet causing water to overflow and leak					
159 FI	M-0053531	Los Angeles	Justice Center	19-L1	1	down to the 13th floor public hallway.	\$	10,225	\$	7,034	68.79
1						Grounds and Parking Lot - Isolated control valve and replaced valve, pumped area to prevent					
1			Stanley Mosk			water from entering the building. Landscaping control valve stuck open over the weekend					
160 FI	M-0053532	Los Angeles	Courthouse	19-K1	1	flooding area, causing water to enter the building rm-119.	\$	3,900	\$	3,793	97.26

	1										
						Plumbing - Flood Remediation - Set-up containment and drying equipment, conduct					
			Compton			environmental testing, and replaced 40' of 4" cast iron sewer drain pipe, no-hub couplings, and					
161	FM-0053533	Los Angeles	•	19-AG1	1	miscellaneous fittings. Water is leaking into the basement from the cracked pipe.	Ś	16,765	Ś	11,087	66.13
101	1101 0033333	Los / trigeres	Courtificase	13 7.01		miscenarieous rittings. Water is leaking into the basement from the cracked pipe.	7	10,703	7	11,007	00.13
			Clara Shortridge			Interior Finishes / Set-up containment and drying equipment, perform environmental testing,					
			Foltz Criminal			remove ceiling tiles, and check for leak above cubicle. This work was completed as a P1					
162	FM-0053534	Los Angeles	Justice Center	19-L1	1	emergency due to an employee stating a leak was coming from the ceiling above her.	\$	5,406	\$	3,719	68.79
			Clara Shortridge			HVAC - 3 HP Exhaust Fan - Remove and replace the failing kitchen exhaust fan, the new fan will	т		,	37. =5	
			Foltz Criminal			include a timer, for more efficient operation. The kitchen exhaust fan has a high vibration					
163	FM-0053535	Los Angeles	Justice Center	19-L1	1	causing the exhaust fan to not work properly.	\$	14,998	Ś	10,317	68.79
		8: 8:				g · · · · · · · · · · · · · · · · · · ·	'	,	<u>'</u>	-,-	
						Plumbing - Drain building cold water to 5th floor to stop leak, once secure Cut out section 2-1/2					
						copper that was leaking, installed ball valve with new 2-1/2 copper line and pro press secure					
			Clara Shortridge			Re-fill entire building and check all toilets, urinals for proper operation and repair as needed.					
			Foltz Criminal			Checked new plumbing for leaks, once cold water was filled. 5th Floor Women's public restroom					
164	FM-0053536	Los Angeles	Justice Center	19-L1	1	had leak in ceiling, located source leaking coming from 2-1/2 copper pipe cold water supply.	\$	19,350	\$	13,311	68.79
						Interior Finishes - Water remediation, set up containments, dry areas with proper drying	•	<u> </u>	<u> </u>	,	
						equipment. Build back, replace ceiling tiles, floor tiles, drywall ceiling. Remove all debris					
			Inglewood			associated within scope of work. Water leak from roof to 2nd flr court room # 241, 2nd flr men's					
165	FM-0053537	Los Angeles	Juvenile Court	19-E1	1	public restroom and the 1st flr court room # 240.	\$	29,051	\$	23,467	80.78
						Interior Finishes - Water remediation, set up containments, disinfect areas. Dehumidifiers/fans	•	<u> </u>			
						were placed to remove moisture in the leak affected areas. Remove drywall for access to drain					
						pipe, remove and replace damaged drain pipe. Install drywall after pipe installation and					
						complete finish work (painting and cove base). Tear out wet ceiling tile and replace ceiling tile					
			Van Nuys			(108 pcs). Cracked 2" black steel pipe leaking through walls on 10th floor down to the 9th floor					
166	FM-0053539	Los Angeles	Courthouse West	19-AX2	1	ceiling.	\$	36,811	\$	29,625	80.48
						Interior Finishes - Set-up containment and drying equipment due to water leaking into Room					
			Santa Monica			202B file storage room, conduct environmental testing, replaced 2 ft of 1 1/2" piping and fitting,					
167	FM-0053541	Los Angeles	Courthouse	19-AP1	2	replaced one 90 and coupling, repaired hangers and supports, and installed new ceiling tiles.	\$	18,356	\$	14,408	78.49
						Interior Finishes - Removal and disposal of loose and flaky paint and plaster from the 12th floor					
			Compton			N/E stairwell, replaster approximately 30 sq ft. and color match paint. This is a slip hazard at the					
168	FM-0053543	Los Angeles	Courthouse	19-AG1	2	stairway.	\$	2,889	\$	1,910	66.13
						Interior Finishes - Build containment 11X6 feet and removed and replace VCT floor tiles 12x12.					
						Repair a piece of concrete on the 9th floor 4x4 feet. Currently there are floor tiles missing and					
			Compton			some that are ready to break causing a trip hazard. Also, a small piece of concrete has broken off					
169	FM-0053544	Los Angeles	Courthouse	19-AG1	2	causing a trip hazard.	\$	2,774	\$	1,834	66.13
						Plumbing / Set-up containment, conducted environmental testing, create larger access panel in					
						restroom wall, and replaced the hot & cold isolation valve. This work was completed as a P1					
			Compton			emergency due to the valves breaking in the off position and the restroom having no access to					
170	FM-0053553	Los Angeles	Courthouse	19-AG1	1	water.	\$	9,249	\$	6,116	66.13
						HVAC - Removed the old, faulty External Float Switch and installed a New External Float Switch.					
						Checked the Cooling Towers, Chillers, and Condenser Water Pumps to ensure the system is in					
						normal working conditions. Building was very hot due to a faulty External Float Switch on the					
			Bellflower			Cooling Towers. Chillers #1 and #2 were tripped due to restricted condenser water flow. This					
171	FM-0053556	Los Angeles	Courthouse	19-AL1	1	was a health and safety issue.	\$	2,348	\$	1,830	77.94

						HVAC - Replace Chilled Water Valve and piping, new insulation was wrapped on the new sections of piping. The chilled water valve for AHU # 4 seized up and would stroke properly. This			
			East Los Angeles			caused the AHU to not cool properly. The chilled water piping adjacent to the unit was			
172 FM-00	0053557	Los Angeles	Courthouse	19-V1	1	deteriorated and leaked water.	\$ 10,961	\$ 8,519	77.72
						Plumbing - Drain building cold water to 5th floor to stop leak, once secure Cut out a 3' section of			
						2-1/2" copper line that was leaking, installed ball valve with new 2-1/2" copper line and pro			
						press secure. Re-fill entire building and check all toilets, urinals for proper operation and repair			
						as needed. Checked new plumbing for leaks, once cold water was filled. 5th Floor Women's			
						public restroom had leak at the ceiling, isolated the leak coming from a 2-1/2" copper cold			
			Van Nuys			water supply pipe. Extract water from bathroom floor, remove and replace approximately 16SF			
173 FM-00	0053560	Los Angeles	Courthouse West	19-AX2	1	of damaged drywall and seal and paint approximately 80 SF of the ceiling.	\$ 19,588	\$ 15,764	80.48
						Plumbing - Water remediation, set up containments, abated insulation from the pipes. Replaced			
						deteriorated sections of pipe. New fiberglass insulation was wrapped on the new sections of			
						pipes. Water supply and return water lines from buildings boiler system have multiple leaks,			
			Pomona			leaking is from deterioration of lines. This caused safety issues with electrical panels and slippery			
174 FM-00	0053562	Los Angeles	Courthouse South	19-W1	1	floor surfaces.	\$ 66,361	\$ 60,481	91.14
			Clara Shortridge			Plumbing - Set-up Containment, drying equipment, and conduct environmental testing.			
			Foltz Criminal			Currently water is dripping from the ceiling into the public hallway in front of the entrance Dept			
175 FM-00	0053565	Los Angeles	Justice Center	19-L1	1	32 courtroom causing a slip hazard.	\$ 10,000	\$ 6,879	68.79
						Parking Structure - Replacement and installation of 20 gate drains in the upper parking			
						structure. The homeless have stolen the floor drain covers for the upper levels of the parking			
			Whittier			area. This leaves a 10 inch by 24 inch gap for each one that is missing on the floor. This is a			
176 FM-00	0053566	Los Angeles	Courthouse	19-AO1	2	safety hazard.	\$ 4,745	\$ 4,101	86.43
						HVAC - Failing AHU #7 - Replace supply fan motor, variable frequency drive, pulleys, and fan			
						belts. AHU #7 had a faulty bearing and the variable frequency drive is tripping on the ground			
			Norwalk			fault protection. If the unit had failed completely, there would have been no air conditioning to			
177 FM-00	0053573	Los Angeles	Courthouse	19-AK1	1	the entire seventh floor, impacting the courts operations.	\$ 14,071	\$ 11,965	85.03
						HVAC / Replace Pneumatic Air Compressor #3. Currently the air compressor has a seized which			
			Stanley Mosk			supplies air to the HVAC system and the building will not be able to control the air to the air			
178 FM-00	0053577	Los Angeles	Courthouse	19-K1	2	handlers used to maintain comfort throughout the building.	\$ 18,870	\$ 18,353	97.26
						Grounds and parking lot - Restored operation to (1) Hy-Security HRG swing riser gate operators.			
						Removed and installed new hydraulic hoses, bled the system, removed and installed the new			
						flow control valves, furnished and installed (2) new Reno AX-3 safety loop detectors, adjusted &			
			Downey			checked for proper operation. The Sally port gates would not swing open and the custody bus			
179 FM-00	0053578	Los Angeles	Courthouse	19-AM1	1	could not leave the sally port.	\$ 7,595	\$ 7,595	100
						Plumbing - Ran fiber optic camera through the drain line in order to locate the stoppage and			
						clear the drain line. Removed all debris and pumped water from sump pits to prevent water			
						from backing up and causing a flood in the basement. The floor drain line in the basement got			
			Norwalk			clogged not allowing water to drain properly. Water is pooling in the basement presenting a			
180 FM-00	0053579	Los Angeles	Courthouse	19-AK1	1	safety hazard to damage our electrical panels and a slipping hazard to ABM personnel.	\$ 6,162	\$ 5,240	85.03
						Elevators, Escalators, & Hoists - Control Panel - Replaced bad circuit that had a short and			
						restored elevators 1-4 back to normal working conditions. Call Stations for Elevators 1-4 were			
			Norwalk			not responding. The public as well as court employees were overcrowding and congesting public			
181 FM-00	0053580	Los Angeles	Courthouse	19-AK1	1	elevator lobbies on all floors. This was a safety and security hazard.	\$ 2,239	\$ 1,904	85.03

Secretary Description   Secr							HVAC - Remove, rebuild, then re-install fuel injector pump and reseal oil return line. The					
182 FM-0053945   Los Angeles   Courthouse   19-01   1   Hazards include possible fire due to the fuel igniting.   S   11,801   S   6,859   58.1				El Monte								
Name	182	FM-0053581	Los Angeles		19-01	1		\$	11 801	Ś	6 859	58.12
183 FM-0053945   Los Angeles   Courthouse West   19-AX2   1   the 2nd floor Clerk's area creating uncomfortable work conditions for the employees   5   15,000   5   12,072   80.4	102	1101 0033301	Los / tilgeres	Courtificase	13 01		Tidzards include possible me due to the faci igniting.	<del>                                     </del>	11,001	7	0,033	30.12
188   FM-0053945   Los Angeles   Courthouse West   19-AX2   1   the 2nd floor Clerk's area creating uncomfortable work conditions for the employees   5   15,000   5   12,072   80.4				Van Nuvs			   HVAC / Repair supply trunk lines and install new VFDs to AHU #21. Currently there is no A/C to					
Rod - Perform a minor renovation to the buildings roof which will include repairing the following components. Membrane, Bullster & Drain Repairs - Main Deck, Bilster & Penetration Repairs - Perthouse. Pitch Pocket & Drain Repairs - Lower Decks, Membrane Repair, Condensate Drain Repairs - Drain Rear Lower Decks. Clear Lowers - Lower Cangor. 2, 859 S04FT of repairs.   S 19,010 \$ 17,212 90.5 min Repairs - Drain Rear Lower Decks. Clear Lower Decks. Approx. 2,859 S04FT of repairs.   S 19,010 \$ 17,212 90.5 min Rear Lower Decks. Drain Repairs - Lower Decks. Drain Rear Lower Decks. Drain Re	183	FM-0053945	I os Angeles	<i>'</i>	19-ΔΧ2	1		\$	15 000	\$	12 072	80.48
following components. Membrane, Bilster & Drain Repairs & Penhouse Places, Membrane Repairs, Cendrosate Drain Repairs Decelos. Membrane Blanket - Special Repairs, Cendrosate Repairs, Caulk Metal Laps, Caulk Studer, Three Course Ceramic Roof Drain, Resert Ladders, Lower Decks, Lower Decks, Caulk Metal Laps, Caulk Studer, Three Course Roof Drain Repairs Ladders Repairs, Caulk Repairs,	103	1101 0033343	LOS Angeles	Courtificase West	13 AAZ		· ,	7	13,000	7	12,072	00.40
Repairs -Penthouse. Pitch Pocket & Drain Repairs -Lower Cancey. Membrane Repair, Condensate Drain Repairs - Penthouse. Pitch Pocket & Drain Repairs - Lower Cancey. Decks. American Repairs - Course Pock. Cancer Pock. Approx. 2,850 SQ/TT of repairs.  Roof - A minor roof removation will be done to the following areas (Main Deck & Lower Deck). Main Deck Code Area of Repairs, Coulk Metal Laugust States. Course Carmin Roof Drain, Reset Ladders. Lower Decks. Three-Course Hole in Membrane, Re-Caulk Peremeter Edge Metal, Re-Caulk Counter-Flashing. Approx. 2,300 SQ/TT of repairs.  Roof - A minor roof removation will be done to the following areas (Main Deck & Lower Deck). Main Deck Code Area of Repairs, Caulk Metal Laugust States. Course Carmin Roof Drain, Reset Ladders. Lower Decks. Three-Course Hole in Membrane, Re-Caulk Peremeter Edge Metal, Re-Caulk Counter-Flashing. Approx. 2,300 SQ/TT of repairs.  Roof - A minor roof removation will be done to the following areas (Main Deck & Lower Deck). Main Deck Code Area of Repairs. Caulk Metal Laugust States. Course Carmin Roof Drain, Reset Ladders. Lower Decks. Three-Course Hole in Membrane, Re-Caulk Perimeter Edge Metal, Re-Caulk Reminder Edge Metal,												
Drain Reser Lower Deck. Clear Leaves - Lower Congory. Insert Membrane Blanket -   2 Penthouse/Rear Lower Deck. Approx. 2,850 SQ/FT of repairs.   5 19,010   5 17,212   90.5												
184   FM-0053946   Los Angeles   Courthouse   19-H1   2   Penthouse/Rear Lower Deck. Approx. 2,850 SQ/FT of repairs.   \$ 19,010   \$ 17,212   90.5				Glendale								
Roof - A minor roof renovation will be done to the following areas (Main Deck & Lower Deck). Main Deck Coated Area of Repair, Caulik Media Laps, Caulik Surco, Three-Course ceramic Roof Drain, Reset Ladders. Lower Decks- Three-Course Hole in Membrane, Re-Caulik Perimeter Edge Metal, Re-Caulik Counter-Flashing. Approx. 2,300 SQ/ET of Fepairs. Elevators, Escalators, & Holsts: Remove and properly disposed off oil oil/fill system with fresh lybrace worn out packing, install new hydraulic packing on the jack and make sure that all leaks are addressed properly. Replace and properly disposed off oil oil/fill system with fresh lybrace worn out packing, install new hydraulic packing on the jack and make sure that all leaks are addressed properly. Replace and properly disposed off oil oil/fill system with fresh lybrace worn to packing, install new hydraulic packing on the jack and make sure that all leaks are addressed properly. Replace and properly disposed off oil oil/fill system with fresh lybrace worn to packing. Install new hydraulic packing on the jack and make sure that all leaks are addressed properly. Replace and properly disposed off oil oil/fill system with fresh lybrace worn that shall new hydraulic packing on the jack and make sure that all leaks are addressed properly. Replace and properly disposed off oil oil/fill system with fresh lybrace worn that all leaks are addressed properly. Replace and properly disposed off oil oil/fill system with fresh lybrace with fresh lybrace and properly. Replace selection and replace damaged sally port off or proper oil system fresh sall make sure that all leaks are addressed properly. Replace selection and replace damaged sally port off proper on the pack sall proper disposed and sall properly disposed off proper off propers of proper sall proper disposed and sall proper disposed proper sall proper disposed and sall proper disposed proper sall proper disposed prop	18/	EM-0053946	I os Angeles		19-H1			¢	19 010	ς .	17 212	90 54
Main Deck-Coated Area of Repair, Caulk Metal Laps, Caulk Stucco, Three Course Ceramic Roof Drain, Reset Ladders. Lower Decks- Three-Course Lower Decks- Three-Course Course (Premieter Edge Drain, Reset Ladders. Lower Decks- Three-Course Lower Decks Lower Deck	104	1101-0033340	LO3 Aligeles	Courtifouse	13-111			7	13,010	7	17,212	50.54
Torrance Courthouse 19-C1 2 Metal, Re-Caulk Counter-Flashing. Approx. 2,300 SQ/FT of repairs 5 15,145 5 12,894 85.1    Doalin, Reset Ladders. Lower Decks- Three-Course Hole in Membrane, Re-Caulk Perimeter Edge 5 Metal, Re-Caulk Counter-Flashing. Approx. 2,300 SQ/FT of repairs 5 15,145 5 12,894 85.1    Elevators, Escalators, & Holsts - Remove and replace worn out packing. Install new hydraulic packing on the floor and will burn out the motor if leak is not controlled by the proper discharge pressure. Stanley Mosk 187 FM-0054037 Los Angeles Courthouse 19-AP1 2 Corrected. Stanley Mosk 187 FM-0054037 Los Angeles Courthouse 19-AP1 1 Proper discharge pressure. Stanley Mosk 187 FM-0054038 Los Angeles Los Angeles Los Angeles Los Angeles Courthouse 19-F1 1 Proper discharge pressure. Stanley Mosk 189 FM-0054039 Los Angeles Courthouse 19-F1 1 Proper discharge pressure. Stanley Mosk 199 FM-0054047 Los Angeles Courthouse 19-F1 2 Los Angeles Courthouse 19-F1 2 Los Angeles Courthouse 19-F1 2 Los Angeles Courthouse 19-F1 3 rid floor of renovation will be done to the following areas Pitch Pan Repairs, Roof Drain Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at affected area. How Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at affected area. How Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at affected area. How Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at affected area. How Loose Granules and Fals aware pumps on the east side of the building. Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC. Restore Chiller operation is into. As a result of loss of power the injector pumps system that the current cooling tower drains into. As a result of loss of power the injector pumps system that the current cooling tower drains into. As a result of l												
185   FM-0053947   Los Angeles   Courthouse   19-C1   2   Metal, Re-Caulk Counter-Flashing. Approx. 2,300 SO/FT of repairs.   5   15,145   5   12,894   85.1				Torranco								
Elevators, Escalators, & Hoists - Remove and replace worn out packing, Install new hydraulic packing on the jack and make sure that all leaks are addressed properly. Replace and properly disposed off old oil/illl system with fresh hydraulic oil. Elevator #3 has a worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not controls as worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley Mosk and replace. All packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley Mosk and replace. All packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley Mosk and replace. All packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley. It is a worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley. It is a worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley. It is a worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley. It is a worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not stanley. It is a worn out/leaking hydraulic jack packing. Oil is leaking on the floor out the motor if leak is not stanley. It is a worn out/leaking hydraulic jack packing. Oil is leaking on the floor out the motor if leak is not stanley. It is a worn out/leaking hydraulic jack packing. Oil is leaking on the floor of the packing on the floor of the floor of the floor of the stanley and review control of the floor of the pack of proper date. All packing the floor of the packing of the	100	EN4 00E2047	Los Angolos		10.61	2		۲	1	۲	12.004	OF 1.4
packing on the jack and make sure that all leaks are addressed properly. Replace and properly disposed off old oil/fill system with fresh hydraulic oil. Elevator #3 has a worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not corrected.    186 FM-0053949   Los Angeles   Los Angele	192	FIVI-0053947	Los Angeles	Courthouse	19-C1			۶	15,145	Ş	12,894	85.14
disposed off old oil/fill system with fresh hydraulic oil. Elevator #3 has a worn out/leaking hydraulic jack packing, Oil is leaking on the floor and will burn out the motor if leak is not \$ 6,921 \$ 5,432 78.4    186 FM-0053949 Los Angeles Courthouse 19-AP1 2 corrected.												
Santa Monica   19-API   2   hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not   5   6,921   5   5,432   78.4												
186 FM-0053949 Los Angeles Courthouse 19-AP1 2 corrected.  187 FM-0054037 Los Angeles Courthouse 19-K1 1 proper discharge pressure.  188 FM-0054038 Los Angeles Courthouse 19-K1 1 proper discharge pressure.  189 FM-0054038 Los Angeles Courthouse 19-K1 1 3rd floor with the doors closed and is not functioning.  189 FM-0054040 Los Angeles Courthouse 19-K1 2 best.  190 FM-0054040 Los Angeles Courthouse 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-L1 1 ander and around the building, creating contamination insks on the east side of the building.  190 FM-0054040 Los Angeles Dustice Center 19-L1 1 proper discharge pressure.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 3rd floor with the doors closed and is not functioning.  190 FM-0054040 Los Angeles Dustice Center 19-K1 1 3rd floor with the doors closed and is not functioning.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  190 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.  200 FM-0054040 Los Angeles Dustice Center 19-K1 2 best.				Carata Nassiss			, , , , , , , , , , , , , , , , , , , ,					
HVAC - Rebuild failed CW Pump #22, replace CW Pump motor, remediate ACM pipe insulation and replace. #22 Chilled water pump motor has bad bearings and pump does not provide and replace. #22 Chilled water pump motor has bad bearings and pump does not provide proper discharge pressure. \$ 27,382 \$ 26,632 97.2	106	<b>5.</b> 4. 00 <b>5</b> 00 40			40.454	•		_	6.004		5 422	70.40
Stanley Mosk 187 FM-0054037 Los Angeles Courthouse 19-K1 1 and replace. #22 Chilled water pump motor has bad bearings and pump does not provide proper discharge pressure.  Grounds and Parking Lot - Motor Failure - Remove and replace damaged Sally Port Door with new Custom Built Door (The door is not of typical size). Install new tubing, hardware and re-wire controls/push button/card reader and assured door work for proper operation. Sally Port door inglewood Los Angeles Los Angeles Los Angeles Courthouse 19-F1 1 3rd floor with the doors dosed and is not functioning. Roof - A minor roof renovation will be done to the following areas Pitch Pan Repairs, Roof Drain Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at Courthouse 19-AY1 2 best.  Clara Shortridge Foltz Criminal Justice Center 19-L1 1 under and around the building, creating contamination risks on the east side of the building.  Exterior - Install and secure metal grills so the homeless will not enter areas beneath the facility. The homeless have accessed an area under the building leaving hazardous materials and trash, under and around the building, creating contamination risks on the east side of the building.  Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC-Restore Chiller operations; Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps	186	FM-0053949	Los Angeles	Courthouse	19-AP1			\$	6,921	\$	5,432	78.49
187 FM-0054037 Los Angeles Courthouse 19-K1 1 proper discharge pressure. \$ 27,382 \$ 26,632 97.2   Grounds and Parking Lot - Motor Failure - Remove and replace damaged Sally Port Door with new Custom Built Door (The door is not of typical size). Install new tubing, hardware and re-wire controls/push button/card reader and assured door work for proper operation. Sally Port door motor failed and the door dropped and was damaged beyond repair. \$ 106,109 \$ 72,992 68.7   Inglewood los Angeles Courthouse 19-F1 1 3rd floor with the doors closed and is not functioning. \$ 10,000 \$ 7,456 74.5   Inglewood los Angeles Courthouse 19-F1 1 3rd floor with the doors closed and is not functioning. \$ 10,000 \$ 7,456 74.5   Inglewood los Angeles Courthouse 19-F1 2 best. \$ 23,482 \$ 19,678 83.8   Inglewood los Angeles Courthouse 19-F1 2 best. \$ 23,482 \$ 19,678 83.8   Inglewood los Angeles Courthouse 19-F1 1 Install and secure metal grills so the homeless will not enter areas beneath the facility. The homeless have accessed an area under the building leaving hazardous materials and trash, under and around the building, creating contamination risks on the east side of the building. \$ 23,794 \$ 16,368 68.7   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair. \$ 10,000 \$ 7,456 74.5   Independent of the door dropped and was damaged beyond repair.												
Grounds and Parking Lot - Motor Failure - Remove and replace damaged Sally Port Door with new Custom Built Door (The door is not of typical size). Install new tubing, hardware and re-wire controls/push button/card reader and assured door work for proper operation. Sally Port door motor failed and the door dropped and was damaged beyond repair.    188 FM-0054038				•								
Clara Shortridge Foltz Criminal 188 FM-0054038 Los Angeles Inglewood 189 FM-0054039 Los Angeles 19-E1 1 Tard floor with the doors closed and is not functioning. 190 FM-0054042 Los Angeles 190 FM-0054047 Los Ang	187	FM-0054037	Los Angeles	Courthouse	19-K1	1	proper discharge pressure.	\$	27,382	\$	26,632	97.26
Clara Shortridge Foltz Criminal 188 FM-0054038 Los Angeles Justice Center 19-L1 1 motor failed and the door dropped and was damaged beyond repair.  189 FM-0054039 Los Angeles Courthouse 19-F1 1 3rd floor with the doors closed and is not functioning.  190 FM-0054042 Los Angeles Courthouse 19-Ay1 2 best.  190 FM-0054047 Los Angeles Justice Center 19-L1 1 motor failed and the door dropped and was damaged beyond repair.  190 FM-0054047 Los Angeles Dourthouse 19-F1 1 std door with the doors closed and is not functioning.  190 FM-0054047 Los Angeles Dourthouse 19-Ay1 2 best.  20 Exterior - Install and secure metal grills so the homeless will not enter areas beneath the facility.  The homeless have accessed an area under the building leaving hazardous materials and trash,  under and around the building, creating contamination risks on the east side of the building.  190 FM-0054047 Los Angeles Dourthouse 19-Ay1 2 best.  20 FM-0054047 Los Angeles Dourthouse 21 FM-0054047 Los Angeles Dourthouse 22 Jay4 \$ 16,368 68.70												
Foltz Criminal Justice Center 19-L1 1 controls/push button/card reader and assured door work for proper operation. Sally Port door Justice Center 19-L1 1 motor failed and the door dropped and was damaged beyond repair.    189 FM-0054039   Los Angeles   L												
188 FM-0054038 Los Angeles Justice Center 19-L1 1 motor failed and the door dropped and was damaged beyond repair. \$ 106,109 \$ 72,992 68.7    189 FM-0054039 Los Angeles Courthouse 19-F1 1 37d floor with the doors closed and is not functioning.    190 FM-0054042 Los Angeles Courthouse 19-AY1 2 best.    191 FM-0054047 Los Angeles Courthouse 19-L1 1 motor failed and the door dropped and was damaged beyond repair. \$ 106,109 \$ 72,992 68.7    190 FM-0054039 Los Angeles Courthouse 19-AY1 2 best.    190 FM-0054042 Los Angeles Courthouse 19-AY1 2 best.    190 FM-0054042 Los Angeles Courthouse 19-AY1 2 best.    190 FM-0054047 Los Angeles Courthouse 19-L1 1 under and around the building, creating contamination risks on the east side of the building. \$ 23,794 \$ 16,368 68.7    191 FM-0054047 Los Angeles Pomona Pomona    190 FM-0054047 Los Angeles Pomona Pomona Pomona Incident and the door dropped and was damaged beyond repair. \$ 106,109 \$ 72,992 68.7    191 FM-0054039 Los Angeles Courthouse 19-F1 1 1 motor failed and the door dropped and was damaged beyond repair.    190 FM-0054039 Los Angeles Courthouse 19-F1 1 1 The doors closed and is not functioning.    190 FM-0054042 Los Angeles Courthouse 19-AY1 2 best.    190 FM-0054042 Los Angeles Courthouse 19-AY1 2 best.    190 FM-0054044 Los Angeles Courthouse 19-AY1 2 best.    190 FM-0054047 Los Angeles Control Tansformer prediction, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations; Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps to the building drainage system that the current cooling tower drains into. As a resu												
Inglewood Los Angeles Courthouse 19-F1 1 3rd floor with the doors closed and is not functioning.  Roof - A minor roof renovation will be done to the following areas Pitch Pan Repairs, Roof Drain Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at Sex												
199 FM-0054039 Los Angeles Courthouse 19-F1 1 3rd floor with the doors closed and is not functioning. \$ 10,000 \$ 7,456 74.5   Roof - A minor roof renovation will be done to the following areas Pitch Pan Repairs, Roof Drain Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at \$ 23,482 \$ 19,678 83.8    Clara Shortridge Foltz Criminal Justice Center 19-L1 1 under and around the building, creating contamination risks on the east side of the building. \$ 23,794 \$ 16,368 68.7    Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations; Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps	188	FM-0054038	Los Angeles	Justice Center	19-L1	1		\$	106,109	\$	72,992	68.79
Roof - A minor roof renovation will be done to the following areas Pitch Pan Repairs, Roof Drain Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at best.  Clara Shortridge Foltz Criminal Justice Center  19-L1  FM-0054047  Los Angeles  Clara Shortridge Foltz Criminal FM-0054047  Los Angeles  Foltz Criminal Justice Center  19-L1  FM-0054047  FElectrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC -Restore Chiller operations; Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps				Inglewood			Elevator / Replace selector tape and sheave on elevator #1. Currently Elevator #1 is stuck on the					
Clara Shortridge Foltz Criminal 191 FM-0054047 Los Angeles Foltz Criminal 19-L1 FM-0054047 Los Angeles Foltz Criminal Pomona FM-0054047 Los Angeles Foltz Criminal Pomona FM-0054047 Los Angeles Foltz Criminal Pomona FM-0054047 Los Angeles Foltz Criminal FM-0054047 Los Angeles FM-0054047 Los Angeles Foltz Criminal FM-0054047 Los Angeles	189	FM-0054039	Los Angeles	Courthouse	19-F1	1		\$	10,000	\$	7,456	74.56
FM-0054042   Los Angeles   Courthouse   19-AY1   2   best.   \$ 23,482   \$ 19,678   83.88							Roof - A minor roof renovation will be done to the following areas Pitch Pan Repairs, Roof Drain					
Clara Shortridge Foltz Criminal  191 FM-0054047 Los Angeles  Los Angel				Chatsworth			Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at					
Foltz Criminal  FM-0054047 Los Angeles  Foltz Criminal  The homeless have accessed an area under the building leaving hazardous materials and trash,  under and around the building, creating contamination risks on the east side of the building.  Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the  affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations;  Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical  transformer short circuited causing power failure to the injector pumps to the building drainage  system that the current cooling tower drains into. As a result of loss of power the injector pumps	190	FM-0054042	Los Angeles	Courthouse	19-AY1	2	best.	\$	23,482	\$	19,678	83.80
Foltz Criminal 191 FM-0054047 Los Angeles 192 Los Angeles 194 Los Angeles 195 Los Angeles 196 Los Angeles 196 Los Angeles 197 Los Angeles 197 Los Angeles 198 Los Angeles 199												
191 FM-0054047 Los Angeles Justice Center 19-L1 1 under and around the building, creating contamination risks on the east side of the building. \$ 23,794 \$ 16,368 68.7  Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations; Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps				Clara Shortridge			Exterior - Install and secure metal grills so the homeless will not enter areas beneath the facility.					
Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations; Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps				Foltz Criminal			The homeless have accessed an area under the building leaving hazardous materials and trash,					
affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations;  Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps	191	FM-0054047	Los Angeles	Justice Center	19-L1	1	under and around the building, creating contamination risks on the east side of the building.	\$	23,794	\$	16,368	68.79
Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps							Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the					
transformer short circuited causing power failure to the injector pumps to the building drainage  Pomona system that the current cooling tower drains into. As a result of loss of power the injector pumps							affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations;					
Pomona system that the current cooling tower drains into. As a result of loss of power the injector pumps							Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical					
							transformer short circuited causing power failure to the injector pumps to the building drainage					
192   FM-0054048   Los Angeles   Courthouse South   19-W1   1   were not online.   \$ 46,931   \$ 42,773   91.1				Pomona			system that the current cooling tower drains into. As a result of loss of power the injector pumps	5				
	192	FM-0054048	Los Angeles	Courthouse South	19-W1	1	were not online.	\$	46,931	\$	42,773	91.14
			_									1
Beverly Hills Plumbing / Set-up containment, Conduct Environmental Testing, and replace fittings for the 2				Beverly Hills			Plumbing / Set-up containment, Conduct Environmental Testing, and replace fittings for the 2					
193 FM-0054051 Los Angeles Courthouse 19-AQ1 1 1/2" domestic cold water supply line that is leaking. Water leak has been isolated and contained. \$ 10,000 \$ 7,952 79.5	193	FM-0054051	Los Angeles	Courthouse	19-AQ1	1	1/2" domestic cold water supply line that is leaking. Water leak has been isolated and contained.	\$	10,000	\$	7,952	79.52

		1	Ī			Dlumbing / Set up Containment drying equipment champes carnet clean uphelstory &					1
			Albambra			Plumbing / Set-up Containment, drying equipment, shampoo carpet, clean upholstery, &					
104			Alhambra	10.11	4	replace ceiling tiles. Currently there is water dripping from the snack bar into the basement call	۸ ا	10.000	۸ ا	0.600	0.0
194	FM-0054054	Los Angeles	Courtnouse	19-I1		Center.	<b>\$</b>	10,000	\$	8,600	86
			la el acce a el			Plumbing / Set-up containment, conduct environmental testing, and replace cracked 4" main					
405			Inglewood		_	cast iron drain pipe in ceiling. Water dripping from the ceiling into the self help center on the 1st		10 500	_	0.000	
195	FM-0054055	Los Angeles	Courthouse	19-F1	1	floor. Currently the leak from the ceiling has been contained.	\$	12,500	\$	9,320	74.56
			.,			Electrical - Trace electrical wires to assure there are not shorts in system. Currently the lights in					
			Van Nuys			Rooms 233, 237, & 238 will not function even though there is electrical power going to the					
196	FM-0054057	Los Angeles		19-AX2	1	space.	\$	7,500	\$	7,500	100
			Clara Shortridge			Plumbing / Set-up Containment, disinfect area, set-up Drying equipment, and conduct					
			Foltz Criminal			environmental testing. Currently water is dripping into the 15th floor, public hallway from the					
197	FM-0054058	Los Angeles	Justice Center	19-L1	1	employee's Men's restroom on the 16th floor.	\$	10,000	\$	6,879	68.79
						Plumbing - Water remediation, set up containments, contain leaking, and dried leak affected					
			Pasadena			areas. Water leaking from 4th floor through to the ceiling on 3rd floor, Room 319 Public					
198	FM-0054059	Los Angeles	Courthouse	19-J1	1	Defender's Office.	\$	10,000	\$	10,000	100
			Clara Shortridge			Grounds / Replace burnt out motor, bottom guide rail, and bent/broken rods. The gate came					
			Foltz Criminal			down on top of the bus transporting the in-custodies creating a safety situation since the gate					
199	FM-0054060	Los Angeles	Justice Center	19-L1	1	no longer opens correctly.	\$	10,000	\$	10,000	100
						Plumbing / Replace broken toilet, replace telephone, and repair holes in wall. Currently an					
			Torrance			inmate has torn out the phone for the holding cell, broken the toilet, and punched holes in the					
200	FM-0054061	Los Angeles	Courthouse	19-C1	1	wall creating a safety situation for all deputies.	\$	10,000	\$	10,000	100
						Roof - Replace Missing Vent Caps. Approx. 200 SQ/FT of repairs. / Roof is in poor condition.					
			Alhambra			Immediate removal & replacement is recommended. IF removal & replacement is not done,					
201	FM-0054068	Los Angeles	Courthouse	19-I1	2	immediate maintenance is strongly recommended.	\$	2,247	\$	1,932	86.00
						Roof - Perform a minor renovation to the buildings roof which will include repairing the		<u> </u>		,	
						following components. Re-Caulk Lead Flashings, Clear Loose Granules From Roof Surface, Repair					
			Airport			Expansion-Joint Hole & Re-Tighten Roof Drains. Approx. 1,500 SQ/FT of repairs / Roof system is					
202	FM-0054069	Los Angeles	'	19-AU1	2	in poor to fair condition at best.	\$	10,011	\$	7,725	77.17
		8	Michael D.				'	- , -	•	, -	
			Antonovich			HVAC - Replaced vane actuator shaft control pre-rotation device, vane actuator and associated					
			Antelope Valley			linkages. Installed (3) new gaskets and (3) new 0-ring seals, and recharged Chiller. Compressor					
203	FM-0054076	Los Angeles	· · · · · · · · · · · · · · · · · · ·	19-AZ1	1	on the chiller not functioning due to a failed vane actuator to the vane linkage arm.	Ś	36,461	Ś	26,802	73.51
200	1111 003 1070	2007.1186.60	Courtificate	13 / 121		Elevators, Escalators, & Hoists - Replace bearings, motor shaft and Exciter Armature, restore	7	30,101	7	20,002	73.31
			Metropolitan			elevator to normal operations. Judge's elevator #12 bearings over heated. Elevator was on the					
204	FM-0054077	Los Angeles	1	19-T1	1	8th floor and out of service.	¢	40,730	¢	40,730	100
204	1101 0034077	Los / trigeres	Courtifouse	13 11		Plumbing - Excavate concrete around meter vaults and planter in front of the courthouse to	7	+0,730	7	40,730	100
						expose water line. Sidewalk removed. Installed new copper piping, valves, and regulators. New					
						sidewalk poured, dirt removed is replaced. Water Main Leak under sidewalk and into planter,					
			Burbank			vault containing the water meters was flooded. Additional leak located in the planter area					
205	EN4 00E4079	Los Angolos		10.61	1	coming from a clay-valve and gate valve.	خ	12 221	۲	20.221	00.76
203	FM-0054078	Los Angeles	Courtilouse	19-G1		Corning from a clay-valve and gate valve.	Ş	43,324	Ş	39,321	90.76
						Interior Finishes - Water remediation, set up containments, dehumidifiers and fans were placed					
						· · · · · · · · · · · · · · · · · · ·					
			Clara Chartridge			to remove moisture in the leak affected areas. ACM & Bacterial testing & clearance. Install new					
			Clara Shortridge			Cast iron pipe with fittings and install support hangers for pipes to meet current building codes.					
200	EN 4 005 4050		Foltz Criminal	40.14	_	Major drain line water leak on the 7th floor; areas affected due to this water leak include	_ ا	46.000	_	22.406	60 70
206	FM-0054079	Los Angeles	Justice Center	19-L1	1	secured hallways, court rooms, judge's chambers, restrooms, and clerk's areas.	>	46,803	<b>\</b>	32,196	68.79

			1			Interior Finishes - Water remediation, set up containments, restroom wall opened up to make					
						repairs, wall repaired to match existing. Replaced failed valve with copper pipe and fittings.					
			Motropolitan			Replace damaged ceiling tiles and install access panel. Water leak in Judges rest room on the 6th					
007	EN4 00E4090	Los Angolos	Metropolitan	10 T1	1	floor, water leak also affected Dept. #66 on the 5th floor.	۲	20 052	۲	20 222	94.54
107	FM-0054080	Los Angeles	Courthouse	19-T1	Т	HVAC - Water remediation, set up containment, contain leaking, and dried leak affected area.	<u>ې</u>	29,852	Ş	28,222	94.54
						Replace floor drain and pipe in ceiling. Replace 2 custom Chilled Water Coils including copper					
						piping. Build back of Snack Bar area including drywall and paint to match existing paint. 2nd					
			Noncelle			floor Mechanical Room floor drain is cracked and leaking into the ceiling below. Also the coils on					
200	EN 4 00E 4004		Norwalk	40 414	4	AHU-2 have deteriorated and are leaking on the floor of the Mechanical Room and seeping		75 240		62.054	05.03
.08	FM-0054081	Los Angeles	Courtnouse	19-AK1		through to the ceiling below.	\ <del>\</del>	75,210	\$	63,951	85.03
			Clandala			Plumbing - Set-up containment, conduct environmental testing, and replace leaking portion of					
300	EN 4 00E 400 4		Glendale	10.114	4	domestic hot water pipe. Currently water is dripping from the ceiling of the traffic clerk's area	۲ ا	12 500	_ ا	44 240	00.54
209	FM-0054084	Los Angeles	Courtnouse	19-H1		creating a safety hazard.	\ <del>\</del>	12,500	\$	11,318	90.54
			Matropoliton			Plumbing - Set-up containment, conduct environmental testing, and replace cracked drain pipe.					
110	EN 4 00E 4000		Metropolitan	10 T1	1	Currently water is dripping from the ceiling into the 8th floor Jury office room causing a safety	۲ ا	10.000	۲	0.454	04.54
110	FM-0054088	Los Angeles	Courtnouse	19-T1	1	hazard.  Parking Let Posters bent grill and rods on main roll up gate. The gate was hit by a sar and is not	, <del>)</del>	10,000	\$	9,454	94.54
			Cometon			Parking Lot - Restore bent grill and rods on main roll-up gate. The gate was hit by a car and is not					
244	EN 4 00E 4000		Compton	10 101	4	operational which is a safety hazard for the employees and staff of the courthouse. The vehicle		40.000	_	6.642	66.42
211	FM-0054089	Los Angeles	Courtnouse	19-AG1	1	has not been identified at this time.	\$	10,000	\$	6,613	66.13
			Nama Nivers			HVAC - Repair (3) non-functioning domestic hot water boilers. Currently there is no hot water					
4.2	EN 4 00E 4004		Van Nuys	10 472	2	supply throughout the entire building. This includes showers and faucets, not allowing judges	۸ ا	4.000	_ ا	4.022	00.40
12	FM-0054091	Los Angeles	Courthouse West	19-AX2		and employees to shower.	\ <del>\</del>	4,999	\$	4,023	80.48
112	EN 4 00E 400 4		Torrance	10.61	1	Elevator / Replace malfunctioning door edge sensor. Door edge sensor not sensing when	۲ ا	2 474	۲	2.100	05 14
.13	FM-0054094	Los Angeles		19-C1		someone was in the door way and closing which was causing a safety situation.	\ <del>\</del>	2,474	\$	2,106	85.14
111	EN 4 00E 400E		Van Nuys	10 414	4	Electrical - Replaced failed generator 3/8" fuel line and placed generator back into service. Fuel	۸ ا	2.000	_ ا	2 220	00.74
.14	FM-0054095	Los Angeles	Courthouse East	19-AX1		line broke while generator was running (outage due to DWP power issues).	\ <del>\</del>	2,606	<b>&gt;</b>	2,339	89.74
)1F	EN4 00E400C	Los Angolos	Bellflower	10 11	1	Elevator - Replace buffer circuit boards on top of the elevator car. Currently the elevator is not	لم ا	10.000	۲	7 704	77.04
12	FM-0054096	Los Angeles	Courtnouse	19-AL1		stopping on the designated floors which is causing a safety situation.	\ <del>\</del>	10,000	\$	7,794	77.94
						Plumbing - Water Leak - Set-up containment, conduct environmental testing, and located the					,
			Matropoliton			source of leak, removed and replaced a 15' section of 4" cast iron that had cracked. Removed					
1.0	ENA 00E 4007	Los Angolos	Metropolitan	10 T1	1	and replaced approximately 10 wet ceiling in storage room 3 and where water dripped through	لم ا	10.000	۲	0.454	04.54
10	FM-0054097	Los Angeles		19-T1		the ceiling tiles in storage room 4.  Exterior Finishes / Benlace panis hardware on ADA front entrance doors. Currently the doors are	\ <del>\</del>	10,000	<b>&gt;</b>	9,454	94.54
117	EN 4 00E 4000		Airport	10 4111	1	Exterior Finishes / Replace panic hardware on ADA front entrance doors. Currently the doors are	۲ ا	г 000	۲	2.050	77 17
1/	FM-0054098	Los Angeles	Courtnouse	19-AU1		not securing at night making the courthouse unsafe.	<u> </u>	5,000	\$	3,859	77.17
			Томмою оо			Diverbing / Deplete modify potioning toilet in 5th floor look up area. Invests alonged the toilet and					
110	EN4 00E4000	Los Angolos	Torrance	10.61	2	Plumbing / Replace malfunctioning toilet in 5th floor lock up area. Inmate clogged the toilet and		2 225	۲ ح	2 225	100.00
218	FM-0054099	Los Angeles	Courthouse	19-C1		flooded the lock up area on the 5th floor and water ran down to the 4th floor Dept P courtroom.	\ <del>\</del>	2,325	<b>&gt;</b>	2,325	100.00
			Van Nuvs			HVAC - Replace (3) Variable Frequency Drives to the cold deck, hot deck and return fan. This					
110	ENA 00E 4100	Los Angolos	Van Nuys	10 472	1	work was completed as a P1 emergency due to the 9th floor not having any heating which made	لم ا	0.646	۲	7.762	00.40
219	FM-0054100	Los Angeles	Courthouse West	19-AX2		it uncomfortable for the visitors and employees.	\ <del>\</del>	9,646	\$	7,763	80.48
						Plumbing - Set-up containment, conduct environmental testing and drying equipment, replace					
						angle stops from the 5th floor Jury restroom. This work was completed as a P1 emergency due					
			Nama Nivers			to water leaking from the 5th floor Depart 420, Jury Restroom into the 4th floor lawyer's					
120	ENA 005 4402		Van Nuys	10 414	4	interview room, the audience seating adjacent to the lawyer's interview room, and the jury	۲ ا	45 054	۲	45.054	400
<u> </u>	FIVI-UU541U2	Los Angeles	Courthouse East	19-AX1	1	room.	\$	15,851	<b>\</b>	15,851	100

			Airport			Plumbing - Replace leaking cap for the 4" domestic cold water supply pipe. Water leaking into					
221	FM-0054104	Los Angeles	'	19-AU1	1	the pump room which could become a flood if the work is not completed immediately.	\$	2,466	\$	1,903	77.17
								·			
						Plumbing / Set-up containment, conduct environmental testing, replace 3" cracked pipe leaking					
						from ceiling into the secure hallway adjacent from the DA's office, replace damaged drywall, and					
			Van Nuys			ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and					
222	FM-0054105	Los Angeles	Courthouse West	19-AX2	1	leaking water into the secure hallway creating a slip and safety hazard.	\$	12,800	\$	10,301	80.48
			Santa Clarita			Plumbing - Replace faulty control valve to toilet in the men's lock-up area. Water leaking from					
223	FM-0054107	Los Angeles	Courthouse	19-AD1	1	the base of the toilet and sink creating a slip hazard.	\$	2,320	\$	2,320	100
						Interior Finishes / Replace broken and loose floor tiles in the 1st floor snack bar. Currently the		<u> </u>			
			Compton			floor tiles are beginning to break and loosen up from the floor creating a trip hazard to the staff					
224	FM-0054112	Los Angeles	Courthouse	19-AG1	2	and the public.	\$	4,844	\$	3,203	66.13
						HVAC - Water remediation, set up containments, contain leaking, disinfect and dried leak	<u> </u>	•	·	,	
						affected area. ACM testing. 8 sq. ft. of ceiling tiles were removed and replaced. Installed new					
						custom manufactured hot water and chilled water coils along with new piping, and a new					
						custom manufactured stainless steel drain pan and pipe. Replace 4 gate valves and replace					
			Pomona			insulation from piping. Water leak from 2nd floor air handler room, is going into 1st floor lobby					
225	FM-0054115	Los Angeles	Courthouse South	19-W1	1	affecting employee entrance.	Ś	72,689	Ś	66,249	91.14
						HVAC - Replace Pneumatic control valves and actuators AHU-1 & AHU-2. Control valves are	Т	,	7	33,213	
						broken and non-operational. There is no way of controlling the cooling at these units because of					
			Compton			this issue. Also the chilled water isolation valves and bypass valves are non-operational at this					
226	FM-0054116	Los Angeles	•	19-AG1	1	unit and will have to be replaced.	Ś	44,313	\$	29,304	66.13
						Exterior Shell - Replace sally port door. The gate was struck by a vehicle and found on the	т	,	7		
			Pasadena			ground off of the track which causes a security concern due it being where they drop off the in					
227	FM-0054118	Los Angeles		19-J1	1	custody visitors.	Ś	10,000	Ś	6,935	69.35
							Т		7	3,222	
						Plumbing - Water Leak - Set-up containment, drying equipment, and conduct environmental					
						testing. Removed and replaced one broken hose bib, remove and replace approximately 35 sf of					
			San Fernando			damaged plaster ceiling and 100sf of plaster walls. Water from the janitorial sink ran down from					
228	FM-0054119	Los Angeles		19-AC1	1	the 4th floor to the 2nd floor effecting rooms 4046, 4045, 3096, 3095, 2102, & 2104.	Ś	10,000	Ś	8,341	83.41
	666 1226					Plumbing / Construct containment, set-up drying equipment, conduct environmental testing,	T		7	2,0 :=	301.12
						and replace fallen ceiling tiles. Initial work will be conducted under hot conditions until testing					
			Compton			results are received. Water leaked from the janitorial hose from the 11th floor down to the 8th					
229	FM-0054120	Los Angeles	-	19-AG1	1	floor.	Ś	12,500	\$	8,266	66.13
			Norwalk			Exterior Shell / Replace closing mechanism on exit doors. Currently the doors are not retracting	7		7	5,255	30:20
230	FM-0054121	Los Angeles		19-AK1	1	and locking automatically which is causing a security concern.	Ś	5,000	\$	4,252	85.03
						Plumbing - Flood Water Mitigation - Construct containment, conduct environmental testing, and	Т		, ,	.,===	
						replaced a 5 foot section of 2 inch cracked drain line and replaced one 2x2 ceiling tile in room					
			Stanley Mosk			106 which has a 14 foot ceiling.					
231	FM-0054122	Los Angeles	<u> </u>	19-K1	1		Ś	10,000	\$	9,726	97.26
	333 1222						T		T	3,. =0	37.20
						Plumbing / Set-up containment, drying equipment, conduct environmental testing, and replace					
			Norwalk			ceiling tiles. Water leaked from an overflowing toilet in the 3rd floor men's public restroom					
232	FM-0054123	Los Angeles		19-AK1	1	through the ceiling into the 2nd floor room 206R which created a safety situation.	\$	10,000	Ś	8,503	85.03
	1 500	1	1				т		т —	-,	23.03



						HVAC - Set Up Containment, heppa Vacuum, change out filters, and abate loose fire proofing.					
			Pasadena			Loose fire proofing was found in the air filters of AHU #2 which could have caused a health and					
233	FM-0054124	Los Angeles	Courthouse	19-J1	1	safety issue.	\$	10,000	\$	6,935	69.35
						Elevator - Install (1) emergency battery back-up power supply unit for the 110 volt elevator cab	'	,	'	,	
						lighting circuit on each elevator. The installation will entail the mounting of the power supply					
						unit on the elevator car top, piping and wiring between the power supply unit and the					
						emergency light fixture mounted in the ceiling area of the elevator cab, and piping and wiring to					
			Alhambra			the car top alarm bell. This unit will activate during loss of supply power to the emergency light					
234	FM-0054128	Los Angeles		19-I1	2	and emergency alarm bell.	ς	15,819	ς	13,604	86.00
254	1101 0054120	Los / mgeres	Courtificase	13 11		and emergency diarm ben.	7	13,013	7	13,004	00.00
						Plumbing - Water remediation, set up containments, secure water supply and disassemble Sloan					
			Clara Shortridge			assembly, re-build removed all calcium, installed new 3.5 master re-build kit with master					
			Foltz Criminal			vacuum break re-build kit. 4th floor Cell #1 Sloan assembly has calcium build up causing leak					
225	FM-0054130	Los Angeles	Justice Center	19-L1	1	when flushed in pipe chase. causing flood to 3rd floor in front Dept.32.	¢	11,400	رخ	7,842	68.79
233	1101-0034130	LOS Aligeles	Justice Center	19-61		when hashed in pipe chase, causing nood to 3rd hoor in front Dept.32.	٦	11,400	٦	7,042	08.73
						Elevators, Escalators, & Hoists - Build containment and enclose basement elevator door area,					
			Pasadena			wiped clean and set up negative air machine. Replace brake coil Judge's elevator #5. Brake coil					
226	FM-0054131	Los Angolos		19-J1	1	in Judge's elevator has failed. Elevator was shut down for safety reasons and locked out.	ځ	7,679	ے ا	E 22E	69.35
230	FIVI-0054151	Los Angeles	Courtilouse	19-11		HVAC - Water remediation, set up containments, vacuumed carpets to remove water and dried	Ş	7,079	Ş	5,325	09.55
						leak affected rooms. Replace ceiling tiles. Water leaked on the floor of the central plant from					
			Fact Los Angolos			1					
227	ENA 005 4122		East Los Angeles	10.1/1	4	chiller. The water seeped thru the concrete floor and leaked into the 3rd floor offices 301S and	ے ا	F C2F	ے ا	4 200	77 73
237	FM-0054132	Los Angeles		19-V1		301T. The water damaged ceiling tiles in both offices.	\$	5,635	\$	4,380	77.72
220	ENA 005 4422		Inglewood	10.51	4	HVAC - Remove defective 15HP motor. Installed new 15HP motor, drive pulley, bushing and 3	_ ا	2 402	_ ا	2.604	74.56
238	FM-0054133	Los Angeles	Courtnouse	19-F1	1	new B79 belts. Cooling tower fan motor not operational.	\$	3,493	\$	2,604	74.56
			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			Plumbing - Water remediation, set up containment, and remove existing failed copper water					
200			Van Nuys	40 41/4	4	supply line and replace it. Water leaking from pipe within space between floors above women's	_	10 100		10.006	00 74
239	FM-0054134	Los Angeles	Courthouse East	19-AX1	1	restroom.	\$	12,186	\$	10,936	89.74
						LIVAC Penlace compressors condensor for motor, and evaporator soil Penair leak in the 1st					
						HVAC - Replace compressors, condenser fan motor, and evaporator coil. Repair leak in the 1st					
						stage and charge with refrigerant. This work was completed as a P1 emergency due to Package					
						Unit #1 had a grounded compressor, the other had bad valves, and a faulty condenser fan					
2.40			Norwalk		4	motor. The first stage refrigerant was also flat. The evaporator coil had an internal restriction	_	15.640		40.070	0= 00
240	FM-0054135	Los Angeles	Courthouse	19-AK1	1	inside the metering devise. The unit was not supplying cooling to the elevator mechanical room.	\$	15,610	\$	13,273	85.03
			_								
			Torrance	10.01	_	Plumbing - Replace cracked 3 bolt toilet with 4 bolt toilet. The toilet was cracked and was about	_	4.004		4.405	0= 4.4
241	FM-0054138	Los Angeles		19-C1		to break off the wall and needed to be replaced for the safety of the visitors to the restroom.	\$	4,821	\$	4,105	85.14
242	<b>514 005 44 70</b>		Inglewood	40.54		Plumbing - Replace failed domestic hot water heater, no hot water to all public restrooms. Need	_	4.000	_ ا	2.570	74.56
242	FM-0054179	Los Angeles		19-F1	1	to restore hot water.	\$	4,800	\$	3,579	74.56
2.40			Downey		_	Elevators, Escalators, & Hoists - Dismantle generator, remove, rebuild, and reassemble. Elevator	_	27.042		24.004	00.70
243	FM-0054180	Los Angeles	Courthouse	19-AM1	2	#3, generator #2 failed and needs to be rebuilt.	\$	37,042	\$	31,004	83.70
						HVAC / Replace motor for cooling tower #2 and diagnose VFDs for Cooling Towers 1 & 2.					
			East Los Angeles			Currently the motor has failed and could affect the cooling for the courthouse. The VFDs have	١.				
244	FM-0054181	Los Angeles	Courthouse	19-V1	1	been placed out of auto due to the trouble that must be diagnosed.	\$	10,000	\$	7,772	77.72
						Roof - Install guardian roof railing system including (30) ground plates, (15) 10 safety rails, (11) 6					
			Monrovia Training		_	safety rails & painted safety striping to comply with Cal-OSHA fall protection / Current roof is	]				
245	FM-0054183	Los Angeles	Center	19-N1	2	missing guard rails for fall protection.	\$	24,539	<b>Ş</b>	17,248	70.29



			Danadana			HVAC - Abate ACM Fireproofing and restore valve to allow water flow into the cooling towers.					
2.46	5.4.005.44.00		Pasadena	40.14		Chiller #2 when off line due to high head pressure. The cause of the high head pressure was low	,	0.262	_	6 424	60.25
246	FM-0054188	Los Angeles	Courthouse	19-J1	1	water level in the cooling towers.	\$	9,263	\$	6,424	69.35
						Elevator - Elevator Renovation - Complete renovation of two (2) traction and one (1) hydraulic					
						elevators. Work will include but not be limited to, car frames and platforms, buffers and					
						safeties, hoist way entrance frames, doors and pit equipt., new AC gearless machines, micro-					
						processor control systems, regenerative VVVF AC drives, fly ball governors, current code					
			Edmund D.			required wiring, interior and lobby control panels, car and hall door panels with new doors,					
			Edelman			counterweights and roller guides, hoist and governor ropes, cab ceilings with LED down lights,					
	SWO-		Children's Court -			rope compensation, new submersible pump units and underground cylinders encased in PVC for					
247	1368822	Los Angeles	Parking Structure	19-Q2	2	hydraulic elevators, and seismic provisions. Install new machine room air conditioning.	ر	934,670	ڔ	747,736	80.00
247	1308822	LOS Aligeles	raiking Structure	19-Q2		Inyuraulic elevators, and seismic provisions. Install new machine room all conditioning.	ې ا	934,070	٦	747,730	80.00
						HVAC - Remove the two defective fire tubes and install two new tubes in their place. Once the					
						new tubes are in place they will be rolled to create the seal. After the tubes have been rolled					
						and the seal created; a Hydro-static test will be performed to insure that the new tubes and the					
			Madera County			remaining tubes will hold pressure and the boiler has no further leaks. The price will include the					
248	FM-0054129	Madera	Superior Court	20-A1	1	ASME documentation and the installation of a new fire gasket on the main access panel.	ς	4,075	ς	2,934	72
240	1101 003 +123	Widacia	County	20 711		HVAC - Replace failed blower motor on boiler #2 and replace pump #2 on the vacuum	7	4,073	7	2,334	72
249	FM-0053032	Mendocino	Courthouse	23-A1	2	condensate return.	Ś	7,078	Ś	4,786	67.62
	1111 0033032	- Wienia de inid	o ar thouse	23 7 12			Υ	7,070	Y	1,700	37.02
						Electrical - Change Lighting - change 6 recessed 8"x8" lights to new single tube 4' florescent					
			County			fixture in ground floor Hallways, fixture to be security type as this hallway is used for					
250	FM-0053570	Mendocino	Courthouse	23-A1	2	transportation of in-custody individuals. Current lighting not compliant with holding standards.	\$	5,365	Ś	3,628	67.62
				13712		Safety - Prep and patch any areas of spalled concrete under building eves, prime and finish paint	<u> </u>	3,333	T	3,020	07.02
						the entire area under the soffits and the fascia/front face of the roof overhangs - The underside					
						of the existing eaves have several areas that are showing signs of the concrete spalling that					
251	FM-0051815	Merced	Old Court	24-A1	2	could fall onto passers-by below.	\$	42,611	\$	42,611	100.00
						Security - Replace the Hirsch Velocity computer, update software, provide new PC server, flash	'	, -		, -	
			New Downtown			memory to all control panels - The control access computer Hirsch velocity is outdated,					
			Merced			damaged and needs to be replaced. Computer has been damaged throughout the years and					
252	FM-0052867	Merced	Courthouse	24-A8	2	software is not working correctly.	\$	16,193	\$	16,193	100.00
			New Downtown					<u> </u>		·	
			Merced			Exterior Shell - Saw cut and jack hammer concrete, replace failed pipe and fittings There is a					
253	FM-0052916	Merced	Courthouse	24-A8	1	very large water leak on the system.	\$	2,405	\$	2,405	100.00
						Exterior Shell - Remove existing entryway storefront doors size 9-51/2 w x 9-2 H with a single					
						emergency exit storefront door size 76 W x 86 H. The New door will be equipped with					
						emergency exit hardware. The existing door has a long history of sticking open when exiting					
						and causing a security breach to the courthouse. Work would include build side and top area					
254	FM-0053019	Merced	Old Court	24-A1	2	with CMU block to replace the existing glass size 9-51/2 w X 9-2 T.	\$	21,437	\$	21,437	100.00
			Salinas			Electrical - Install (3) 2 X 4, T-8 3-LAMP 18CELL FIXTURES in judges chamber. Judge is					
			Courthouse-			experiencing headaches from eye strain - doctors note and light readings indicate inadequate					
255	FM-0053429	Monterey	North Wing	27-A1	2	lighting in room.	\$	3,191	\$	3,191	100.00
						Roof - Replace failed built up roof (8500 sq ft), steep slope shingled roof (7500 sq ft), and					
			Marina			rotted gutters (600 sq ft) - due to deterioration and blisters, there is evidence of water intrusion					
256	FM-0053433	Monterey	Courthouse	27-B1	2	into the building.	\$	533,940	\$	533,940	100.00

			Salinas								
			Courthouse-			Fire Protection - Replace failed NAC 4 unit on Fire Annunciator Panel. Program and perform					
257	FM-0053944	Monterey	North Wing	27-A1	2	operational testing of new NAC.	\$	3,565	\$	3,565	100.00
			Criminal Court			HVAC - AC Unit/Compressor #1 - Remove and replace the failed discharge gasket and O-ring on					
258	FM-0052913	Napa	Building	28-A1	2	Compressor #1.	\$	4,074	\$	4,074	100.00
						Earthquake Remediation - Work includes; Lead and mold remediation, restoring operating					
						systems to their original condition, document restoration, perimeter fencing, fire watch, fire					
						alarm and fire sprinkler assessments, domestic water restoration and isolation valves installed					
						between buildings 28-B1 and 28-A1, replace failed fire alarm panel and sentry-one (71) devices,					
						utilities restoration; install isolation valve on the natural gas line to separate buildings 28-A1 and					
						28-B1, restoration of the buildings plumbing infrastructure, re-secure the existing water heater,					
			Nama Historia			verify the operating systems of the mechanical units, replace or provide new damaged light					
250	ENA 0052462	None	Napa Historic	20.04	1	fixtures, damaged switch gear and replace the hydraulic jack packing on the hydraulic	ے ا	1 000 000	۲	020.000	02.00
259	FM-0053463	Napa	Courthouse	28-B1	1	passenger elevator.  Earthquake Remediation - Work includes; Isolate and remediate three water leaks within the	>	1,000,000	\$	939,900	93.99
						building, replace multiple damaged light fixtures, secure loose wiring, relocate court equipment,					
			Criminal Court			fixtures and materials to new location for Court Operations and restore elevators to proper					
260	FM-0053464	Napa	Building	28-A1	1	operation.	¢	500,000	¢	500,000	100.00
200	1101-0055404	Ναρα	Dullullig	20-A1	<b>T</b>	Earthquake Restoration - Interior Finishes - Replace damaged fire sprinkler heads, carpet and	7	300,000	<del>ب</del>	300,000	100.00
						ceiling tile. Patch, paint and seal cracked wall, ceiling and baseboard surfaces throughout					
261	FM-0054065	Napa	Juvenile Court	28-C1	1	building.	Ś	50,000	Ś	50,000	100
201	553 1553	Trapa	Javenne Godie	20 01		Fire Protection - Annual PM of stand pipe and sprinklers did not pass due to failed equipment	Υ	30,000	Υ	30,000	
						elements. The project requires replacement of 19 missing escutcheons, inspector butterfly					
			Central Justice			valve with chain lock (space 80), 90 fire hoses, and tamper switch at inspector butterfly valve					
262	FM-0052810	Orange	Center	30-A1	2	(space 62/63).	\$	9,097	\$	8,294	91.17
			North Justice			HVAC - Remove and replace failed AHU-2 motor with new 40 HP 1730 RPM 324 Frame 460V		<u> </u>			
263	FM-0052845	Orange	Center	30-C1	2	Motor.	\$	7,434	\$	6,714	90.31
			North Justice			HVAC - Remove and replace failed AHU-1 motor with new 40 HP 1730 RPM 324 Frame 460V					
264	FM-0052846	Orange	Center	30-C1	2	Motor.	\$	7,434	\$	6,714	90.31
						HVAC - Cooling Tower on roof does not have a Variable Frequency Drive (VFD). It has a manual					
						Mag Starter. Replace the Mag Starter with a 20 HP ABB 3R VFD. New VFD to be installed in a					
			North Justice			weather-tight enclosure. The VFD will be more efficient and will save energy as it can be					
265	FM-0052847	Orange	Center	30-C1	2	programmed to the BAS system.	\$	10,141	\$	9,158	90.31
						Electrical - Replace 5 failed high-pressure sodium wall-pak lighting fixtures in the secured judicial					
266			North Justice	22.21		parking lots with 64W LED Wall-Pak lighting fixtures. The LED lighting will give more hours of		4 =0=		4 000	22.24
266	FM-0052848	Orange	Center	30-C1	2	light than the standard bulb currently used.	\$	4,787	\$	4,323	90.31
267	ENA 0053840	0	North Justice	20.61	,	HVAC - Remove and replace failed AHU-6 motor with a new 25 HP 1775 RPM 284 T Frame	,	Г 01 Г	۲	4.520	00.21
267	FM-0052849	Orange	Center Harbor Justice	30-C1		motor.	>	5,015	<b>\$</b>	4,529	90.31
						Fire Protection - Fire Alarm Panel - Replace power supply resulting from over 20 recorded					
268	FM-0052853	Orango	Center-Newport Beach Facility	30-E1	2	trouble instances, perform follow-up system inspection, and return to service.	خ	10,799	خ	9,106	84.32
200	1 14120022022	Orange	Deach Facility	JU-LI		Remove eroded soil from drainage field along the South side of the building (approximately	۲	10,/33	۲	5,100	04.32
			West Justice			1009 sq. ft.) and replace with 1" gravel, Two inches thick, to prevent ground and surface water					
269	FM-0052879	Orange	Center	30-D1	2	from penetrating and damaging the building.	Ś	6,120	Ś	5,550	90.68
203	0002073	0.0.00	Betty Lou			HVAC - Air Handler #8 - Remove and replace failed 60hp supply fan motor that services all floors		0,120		3,330	30.00
			Lamoreaux Justice			of the South West section of the building. There was loss of cooling in this area that required					
270	FM-0052929	Orange	Center	30-B1	2	immediate replacement.	\$	4,920	\$	3,934	79.95
	1 2223	10-	1	1		1	_ T	.,. = 5	_ т	-,	, , , , ,

						Fire Protection - Fire Hoses - Replace 10 each of 11/2" by 75' fire hoses, during annual					
			Central Justice			inspection fire hoses failed hydro test and need to be replaced before annual and 5 year					
271	FM-0052930	Orange	Center	30-A1	2	certification can be completed.	\$	4,100	\$	3,738	91.17
						Conveyances - Remove and replace non-functioning detention chairlift; replacement parts are					
						no longer available for the current lift. The project will include a new inclined wheelchair lift to					
			West Justice			be installed in place of the existing lift along with a new battery backup and hydraulic drive. This					
272	FM-0052944	Orange	Center	30-D1	2	is a noted safety and ADA deficiency; specifications and proposals are attached.	\$	43,155	\$	43,155	100.00
						Conveyances - Elevator #1 hydraulic feed line is leaking. Work will include shutting off oil line					
			North Justice			and replacing damaged sections of pipe and pipe joint, reopen oil line, and testing operation of					
273	FM-0052994	Orange	Center	30-C1	2	elevator before placing back in service.	\$	6,323	\$	5,710	90.31
			North Justice			Fire/Life/Safety - "Knox" Key - Install code required "Knox" key override into gate system for					
274	FM-0053009	Orange	Center	30-C1	2	secured parking areas per State Fire Marshals inspection.	\$	3,900	\$	3,522	90.31
						HVAC - replace two near failure roof mounted economizer fans with new Domex belt driven					
			West Justice			centrifugal units. Both are prone to frequent failure requiring excessive maintenance to retain					
275	FM-0053419	Orange	Center	30-D1	2	operational condition.	\$	9,384	\$	8,509	90.68
						Grounds & Parking Lot - Remediate and treat the metal gates to the Secure Parking Lot to					
			West Justice			prevent further deterioration and failure due to rust. Evidence of invasive rust is present					
276	FM-0053420	Orange	Center	30-D1	2	throughout.	\$	8,429	\$	8,429	100.00
						Grounds - Raised Concrete - Saw cut and remove approximately 105 sq. ft. of concrete sidewalk					
						that became uneven as a result of tree roots. Remove tree roots as necessary, construct new					
			West Justice			sidewalk and apply broom finish. Trip hazard/safety risk to employees and court tenants who					
277	FM-0053449	Orange	Center	30-D1	2	use sidewalk to gain access to courthouse.	\$	3,007	\$	2,727	90.68
						LINAC Variable Francisco Drive (VED). Bendana the eviation 20 LID Betwee Fam VED with a recov-					
						HVAC - Variable Frequency Drive (VFD) - Replace the existing 20 HP Return Fan VFD with a new					
			B			ABB 20 HP VFD. The existing VFD has three blown fuses and has ceased to function properly in					
			Betty Lou			automatic mode. The VFD is currently in bypass mode to run at 100% capacity all the time. The					
2=0			Lamoreaux Justice			VFD controls the Return Fan for AHU #8 and needs to be replaced to avoid disruption to	_			10	
2/8	FM-0053517	Orange	Center	30-B1	2	operations and prolong the life of the equipment. Related JO 1361775.	\$	6,933	\$	5,543	79.95
270	514 0050545		North Justice	20.01		HVAC - Replace failing cooling tower manual Mag Starter with 40 HP ABB 3R VFD in a weather-	,	42.046	_ ا	42 505	00.24
2/9	FM-0053545	Orange	Center	30-C1	2	proof enclose.	\$	13,946	\$	12,595	90.31
						Vandalism - Remove existing window film where necessary, clean interior glass surface, and					
						install high performance window film to 433 panels of glass on south, east, and west facing					
			Nie while it setting			exterior windows. The window tinting throughout the building is faded, torn in places, has					
200	ENA 0052546	0	North Justice	20.61	2	etched graffiti in places, and is in generally poor shape. Installation of new window tint is an	۲ .	F2 FC2	_ ا	47.470	00.24
280	FM-0053546	Orange	Center	30-C1	2	energy-cost saving project.	\$	52,563	\$	47,470	90.31
			Mast Lustins			HVAC - Replace the failing A/C Package Unit that serves the Sheriffs locker room and basement					
201		0,42,42,23	West Justice	20.01	2	areas. Deterioration of the coils and indoor fan motor/compressor makes system unable to	ے ا	C C20	ے ا	C 010	00.60
281	FM-0053564	Orange	Center	30-D1	2	maintain space temperature.  HVAC- Replace the failed Variable Frequency Drive (VFD) for Air Handler Unit #5 with a new 20	<b>\$</b>	6,628	<b>&gt;</b>	6,010	90.68
			North Justice								
202	[	Orango		20.01	2	HP ABB VFD with Johnson NE, Siemens FLN, MODBUS RTU, and BACNET Controls embedded in	خ	6 222	ے	E 610	00.21
282	FM-0054067	Orange	Center	30-C1	2	drive.  Holding Cells - Rehabilitate a large section of wall in the detention hallway that exhibits large	٦	6,222	<del>ا</del>	5,619	90.31
			West Justice								
202	ENA 0054127	Orango		20 D1	2	cracks. There are approximately 32LF of large random cracks that need to be filled with Slka 31 Epoxy Grout. This work is to be completed during non-working hours.	ر	2 500	ر	2 500	100.00
203	FM-0054127	Orange	Center	30-D1		LPONY GIOUL THIS WOLK IS to be completed during non-working hours.	\$	3,500	γ	3,500	100.00

		1	1	1			1		I		1
						Grounds and Parking Lot - Remove approximately 1,620 SF of existing 6 inch concrete, re-grade for bus clearance and water flow, pour new 6 inch thick concrete with No. 4 rebar at 18 inch on					
						center in both directions at 4,000 PSI. Existing Driveway is steep and uneven. The Sheriff bus					
			North Justice			scrapes along the driveway every day as it drives into/out of the bus bay. Water run-off from the					
284	FM-0054185	Orange	Center	30-C1	2	street pools along the bottom of the driveway contributing to the deficiency.	\$	33,818	\$	30,541	90.31
						Exterior Shell - Replace 54 wood windows - 80% of the windows in the historic courthouse have					
						failed due to dry rot and wear, and are beyond repair. The balance of the windows are showing					
						signs of wear and will soon be in disrepair. Window replacement will prevent further damage to					
			Historic			the interior finishes and the courthouse structure related to water and pest intrusion.					
285	FM-0002953	Placer	Courthouse	31-A1	2	Replacement windows will reduce impact to courts operations.	\$	1,025,200	\$	789,404	77.00
			South Placer			HVAC - Install new 3 ton Split HVAC system for Electrical room E0034 - Reduce run time on 27					
286	FM-0053448	Placer	Justice Center	31-H1	2	ton chiller by 108 hours per week.	\$	11,708	\$	11,708	100.00
						Fire Protection - Correct deficiencies identified during 5 year system inspection and Fire Marshal					
						inspection - Remove and replace three (3) 300psi gauges, five (5) non compliant sprinkler heads,					
			South Placer			five escutcheons, fire caulk two (2) areas of wall penetration and install a hydraulic placard at					
287	FM-0053470	Placer	Justice Center	31-H1	2	the fire riser. Current installation does not meet code requirements.	\$	14,451	\$	14,451	100.00
						HVAC - Burnt Compressor - Remove and replace Air Handler #1 compressor, the existing					
			South Placer			compressor grounded out and was smoking causing the system to go into alarm and shutting					
288	FM-0054063	Placer	Justice Center	31-H1	1	down.	\$	28,932	\$	28,932	100
			Portola/Loyalton			Grounds and Parking lot- Irrigation system is leaking and flooding grounds in several areas.					
289	FM-0052983	Plumas	Court	32-B2	2	Replace failed valves and piping. Add valves if required.	\$	8,147	\$	8,147	100.00
						HVAC - Cooling Tower - Remove and replace drift eliminators of the building's cooling tower in					
						cells 1 & 2. The existing eliminators are beyond their lifecycle and if not replaced will result in					
						failure of the HVAC system. Due to the failed eliminators water coming from the condensers is					
						getting to the chillers at a higher temperature than needed, resulting in the chillers working					
						harder and tripping off on high condenser temperature. Install new CTPC150 Counter Flow					
290	FM-0052822	Riverside	Hall of Justice	33-A3	1	Eliminators, 20 new NK-23.	\$	27,473	\$	27,473	100.00
						Lighting - Main Lobby - Arch Ceiling - Remove and retrofit 18 canned 400w mercury vapor bulbs					
						and ballasts with new 100w LED, 5500k cluster. Currently nearly half of the bulbs are dead and					
						in need of replacement. The lights are housed in the second floor arched ceiling and require a lift	-				
						to replace the mercury vapor bulbs. LED replacement would allow change out from above lights					
						via a catwalk. Mercury bulbs and ballasts last approx. 20k hours, while LED will increase the life					
291	FM-0053421	Riverside	Hall of Justice	33-A3	2	to 50k.	\$	7,369	\$	7,369	100.00
			Carol Miller			HVAC - Replace pillow block bearings for cooling tower fan - Chillers cannot run without cooling					
292	FM-0054044	Sacramento	Justice Center	34-D1	2	tower fan, chillers trip out on high head.	\$	3,583	\$	3,502	97.75
						HVAC - Removed damaged Variable Frequency drive for cooling tower #1 50 HP fan motor.					
			Juvenile			Replace with new Drive ABB Model # ACH550-UH-072A-4 - Variable Frequency drive controls					
293	FM-0054090	Sacramento	Courthouse	34-C2	2	fan speed which regulates the water temperature required for chillers to function correctly.	\$	8,211	\$	8,211	100.00
			Needles			COUNTY MANAGED- Parking Lot - Demo approximately 56,265 SF of existing asphalt paving that					
		San	Courthouse-Dept.			is beyond repair, re-grade demo area, and resurface with new asphalt paving. The parking lot is					
294	FM-0052402	Bernardino	N-1	36-K2	2	severely cracked and with several pot holes creating a trip hazard to the public.	\$	100,431	\$	100,431	100.00

to each power receptacle. Power and data receptacles are ended to accommodate new kinsks and monotors that are due to be installed by the Court. New Set flows and monotors will a reduction.  The proper of the pro		Ī	1	T	T		Electrical Install newer recentacles in 14 locations with additional empty data recentacles next	<del></del>		I		
And monitors that are due to be installed by the Court. New Set Price   New Stand Countries   San							Electrical - Install power receptacles in 14 locations with additional empty data receptacles next					
San   Courthouse-Opt   San   San   Courthouse-Opt   San				\								
295   Mr. 0052895   Nemardino   N-1   3-11   2   reduced staff   Same place the failed selector switch in public elevator #1 as well as the selector switch in public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 which is problematic and near failure. This work is necessary to return public elevator #2 work in work and replace approximately \$26,000 \$7 of \$8,000												
Blawaturs, Escalaturs, & Holists - Replace the failed selector switch in public elevator of 2 as well as the selector switch in public elevator of 2 which is profehenated and the failed. This work is necessary to return public elevator of 2 which is profehenated and the failed. This work is necessary to return public elevator of 2 which is profehenated and the failed and the failed of the failed and the fa	205	514 0052000		•				_	2.060	,	2.050	400.00
the selector switch in public elevator #2 which is problematic and near failure. This work is no processed in the selector switch in public elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed in the elevator #2 which is problematic and near failure. This work is no processed and near the elevator is not provided and part the elevator is not near the elevator failure. The elevator is not near the elevator is not near the elevator failure. The elevator is not near the elevator failure is not near the elevator failure. This work is not near the elevator failure is not near failure. This work is not near the elevator failure. This work is not near the elevator failure. This work is not near the elevator failure is not near failure. This work is not near the elevator failure failure is not near the elevator failure. This work is not near the elevator failure. This work is not near the elevator failure is near failure. This work is not near the elevator failure is near failure. This work is not near failure. This work is near failure. The wind such as a failure failure failure failure. The elevator failure f	295	FM-0052883	Bernardino	N-1	36-L1	2		\$	3,868	\$	3,868	100.00
san San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San Burstow San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San Burstow San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San Burstow San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 2 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino Courrhouse 36-A1 1 prevent possible fluture entranments.  San San Bernardino C												
296   PM-0052949   Bernardino   Courthouse   36-A1   2   prevent possible future entrappments.   S   8,863   \$ 8,477   95.64							·					
San Barstow San			San	San Bernardino								
san Barctow Courthouse 36-11 2 continues 36-12 2 continues 36-13 2 continues 36-14 2 continues 36-15 2 continues 36-15 2 continues 36-16 2 continues 36-17 2 continues 36-17 2 continues 36-18 2	296	FM-0052890	Bernardino	Courthouse	36-A1	2	· · ·	\$	8,863	\$	8,477	95.64
San Barstow Bernardino Courthouse 36-J1 2 locations. Electrical - Install power receptacles in 14 locations with additional empty data receptacles. Power and data are needed to accommodate self-help kicks and monitors. Equipment will all advised as a processed backleg caused by increase of traffic stemming from court distance of the court of the self-power and data are needed to accommodate self-help kicks and monitors. Equipment will all advised as a processed backleg caused by increase of traffic stemming from court distance of the power and data are needed to accommodate self-help kicks and monitors. Equipment will all advised as a processed backleg caused by increase of traffic stemming from court distance of the power and data are needed to accommodate self-help kicks and monitors. Equipment will all advised by increase of traffic stemming from court distance of the power and staff reductions.  San San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San San Bernardino Courthouse 36-A1 1 closures and staff reductions.  San Joshua Tree Court MANAGED. Parking Lot. Saw cut, demo and replace approximately 90,000 SF, 4 inch.  San Joshua Tree San Courthouse 36-E1 2 holes, and uneven areas that pose a tripping hazard.  COUNTY MANAGED. Parking Lot. Saw cut, demo and replace approximately 90,000 SF, 4 inch.  San Courthouse Dept.  San Courthouse Dept.  San Courthouse Dept.  San Courthouse Dept.  San San Bernardino Courthouse 36-E1 2 holes, and uneven areas that pose a tripping hazard.  COUNTY MANAGED. Exterior Shell Respond to proper regression of the building approximately 30,000 SF, 4 inch.  15,400S- Existing paint is dull, cracking and exposing the block. Work is necessary to prevent additional roof the building approximately 30,000 SF, 4 inch.  San San Bernardino Courthouse 36-A1 1 Replace and seal failed roofing material which occurred during recent rains affecting Department 50. Replace damaged celling tiles and extract water from carpets in affected area. Bernardino Courthouse 36-A1 1 Replace and							Roof - Remove and Replace Roof - Remove and replace approximately 26,000 SF of existing ACM					
297   FM-0052909   Bernardino   Courthouse   36-11   Z							roof material. Scope includes a 3rd party Hygienist to monitor the abatement, removing					
Rancho San Guermonga San Bernardino Courthouse San San Bernardino San San San San Bernardino San			San	Barstow			damaged seal around building, replacing counter flashing and pipe / vent flashing at various					
Rancho   San   Rancho   San   Power and data are needed to accommodate self-help klosks and monitors. Equipment will alleviate significant check-in processes backlog caused by increased traffic stemming from court   \$9,940   \$9,940   \$100.00	297	FM-0052909	Bernardino	Courthouse	36-J1	2	locations.	\$	580,000	\$	451,994	77.93
San Courthouse 36-F1 2 closures and staff reductions.  San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San Bernardino Courthouse 36-F1 2 closures and staff reductions.  San Joshua Tree  San Gourthouse 36-F1 2 closures that pose a tripping hazard.  COUNTY MANAGED - Exterior Shell Reseal & repaint the exterior of the building approx- 15,4005f. Extisting paint is dull, cracking and exposing the block. Work is necessary to prevent water intrusion in the rainy season. Scope includes clean & pressure wash walls, seal & repair  San San Bernardino  San Bernardino  San	ĺ						Electrical - Install power receptacles in 14 locations with additional empty data receptacles.					
298 FM-0052945 Bernardino Courthouse 36-F1 2 closures and staff reductions.  San San Bernardino San San Bernardino Courthouse 36-A1 2 hazard. Staffolding required.  San Johua Tree COUNTY MANAGED Parking Lot- Saw cut, demo and replace approximately 30,000 SF, 4 inch depth, of a sphalt, slurry seal and re-stripe. Construct concrete sidewalks, curbs and drainage for proper agrees and rain run-off. Currently happend exposing the block. Work is necessary to prevent user intrivision in the rainy season. Scope includes clean & pressure wash walls, seal & repair 300 FM-0053011 Bernardino N-1 36-K2 2 tracks, and paint.  San San Bernardino San Bernardino San San San Bernardino San				Rancho			Power and data are needed to accommodate self-help kiosks and monitors. Equipment will					
San Bernardino   San Bernardino   Courthouse   36-A1   2   hazard   Saffolding required   San Bernardino   Courthouse   36-A1   2   hazard   Saffolding required   San Joshua Tree   Courthouse   36-A1   2   hazard   Saffolding required   San Joshua Tree   Courthouse   36-A1   2   hazard   Saffolding required   San Joshua Tree   Courthouse   36-A1   2   hazard   Saffolding required   San Joshua Tree   Courthouse   36-A1   2   hazard   Saffolding required   San Joshua Tree   Courthouse   36-A1   2   hazard   Saffolding required   San Joshua Tree   Courthouse   San			San	Cucamonga			alleviate significant check-in processes backlog caused by increased traffic stemming from court					
San San Bernardino Courthouse 36-1 2 horizontally suspended stained glass window. The grand stairvell is dimly lit creating a safety 5,669 \$ 5,422 95.64    Proposator San Joshua Tree Jos	298	FM-0052945	Bernardino	Courthouse	36-F1	2	closures and staff reductions.	\$	9,940	\$	9,940	100.00
San							Interior Finishes - Replace failed lights. Remediate lead dust containing debris from the back of a					
San			San	San Bernardino			horizontally suspended stained glass window. The grand stairwell is dimly lit creating a safety					
COUNTY MANAGED - Parking Lot- Saw cut, demo and replace approximately 30,000 SF, 4 inch depth, of asphalt, slurry seal and re-stripe. Construct concrete sidewalks, curbs and drainage for proper egress and rain run-off. Currently the asphalt in the parking lot has numerous cracks, pot solon. San Courthouse 36-E1 2 holes, and uneven areas that pose a tripping hazard. COUNTY MANAGED - Exterior Shell. Reseal & repaint the exterior of the building approx-15,400SF. Existing paint is dull, cracking and exposing the block. Work is necessary to prevent water intrusion in the rainy season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair season. Scope includes clean & pressure wash walls, seal & repair seal & repair season. Scope includes clean & pressure wash walls, seal & repair seal & repair seal & repair the exterior of the building approximately and seal & repair the exterior of the building approximately seal & repair seal & repair seal & repair the exterior of the building approximately seal & repair seal & repair seal & repair the exterior of the building approximately seal & repair seal & repair the exterior of the building approximately seal & repair seal & repair the exterior of the building approximately seal & repair seal & repair the exterior of the building approximately seal & repai	299	FM-0052946	Bernardino	Courthouse	36-A1	2		\$	5,669	\$	5,422	95.64
depth, of asphalt, slurry seal and re-stripe. Construct concrete sidewalks, curbs and drainage for proper egress and rain run-off. Currently the asphalt in the parking lot has numerous cracks, pot San Bernardino  Needles San Courthouse Dept. San Courthouse Dept. San San Bernardino San							<u> </u>	†	,		,	
San Joshua Tree Growthouse 36-E1 2 proper egress and rain run-off. Currently the asphalt in the parking lot has numerous cracks, pot 5 120,000 100.00												
FM-0053005 Bernardino Courthouse 36-E1 2 holes, and uneven areas that pose a tripping hazard. \$ 120,000 \$ 120,000 100.00  COUNTY MANAGED- Exterior Shell- Reseal & repaint the exterior of the building approx- San Courthouse-Dept. Courthouse-Dept. San Courthouse-Dept. San San Bernardino N-1 36-K2 2 cracks, and paint. San San Bernardino San San San Bernardino San San San Bernardino San			San	Joshua Tree			, , , , , , , , , , , , , , , , , , , ,					
Needles Needles San Courthouse-Dept. San Courthouse-Dept. San Courthouse-Dept. San Courthouse-Dept. San	300	FM-0053005			36-F1	2		Ś	120 000	Ś	120 000	100 00
San	300	1101 0033003	Dernaranio	Courtifouse	30 21		, , , , , , , , , , , , , , , , , , , ,	+	120,000	7	120,000	100.00
San Courthouse-Dept. N-1 36-K2 2 cracks, and paint. \$ 12,100 \$ 12,100 \$ 100.00 \$ 100				Needles								
San   San Bernardino   N-1   36-K2   2   cracks, and paint.   San   San Bernardino   San   San Bernardino   San Cucamonga   San Bernardino			San									
Exterior Shell - Replace and seal failed roofing material which occurred during recent rains affecting Department 50. Replace damaged ceiling tiles and extract water from carpets in affected areas.  San Bernardino Courthouse 36-A1 1 affected areas.  San Bernardino Courthouse 36-A1 1 affected areas.  San Bernardino San Bernardino San San Bernardino Courthouse 36-A1 2 observed during recent torrential rains.  San San Bernardino Courthouse 36-A1 2 observed during recent torrential rains.  Rancho San	201	EN4-0053007		•		2		خ	12 100	ر	12 100	100.00
San San Bernardino Courthouse 36-A1 1 affected areas. \$ 4,682 \$ 4,478 95.64 Roof - Seal under interior counter flashing of (3) existing roof drain sumps, seal the outside of the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing. 3 existing roof drains are leaking, work is needed to prevent additional roof leaks which where observed during recent torrential rains. \$ 5,169 \$ 4,944 95.64 Interior Finishes - Restore damaged concrete sub floor - Perform initial ACM testing, remove a 6 X 9' area. Level concrete sub floor and install approximately 54SF of new carpet. All work to be performed after-hours. The damaged floor patch beneath the carpet is near the attorney's San Courthouse 36-A1 2 table and is a trip hazard. \$ 5,817 \$ 5,817 \$ 100.00 San Bernardino Courthouse - Annex 36-A2 2 future roof leaks. San Fontana HVAC - Install a new 1.5 ton split system that serves the 2nd floor A/V room. The current split	301	1 101-0033007	Bernarumo	IN-T	30-KZ		· · ·	- ا	12,100	٦	12,100	100.00
302 FM-0053011 Bernardino Courthouse 36-A1 1 affected areas. \$ 4,682 \$ 4,478 95.64 Roof - Seal under interior counter flashing of (3) existing roof drain sumps, seal the outside of the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing. 3 existing roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is needed to prevent additional roof leaks which where some sexisting roof drains are leaking, work is necessary in order to prevent after the sexisting roof drain sumps, seal the outside of the scuppers, install new down spouts, and install sor of vent caps and tighten 5 existing. 3  FM-0053418 Bernardino Courthouse 36-A1 2 observed during recent torrential rains. \$ 5,169 \$ 4,944 \$ 95.64 \$ 1.00 \$			San	San Bornardino								
Roof - Seal under interior counter flashing of (3) existing roof drain sumps, seal the outside of the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing. 3 existing roof drains are leaking, work is needed to prevent additional roof leaks which where  303 FM-0053418 Bernardino Courthouse 36-A1 2 observed during recent torrential rains. \$ 5,169 \$ 4,944 95.64  304 FM-0053422 Bernardino Courthouse 36-F1 2 table and is a trip hazard. \$ 5,817 \$ 5,817 \$ 100.00  305 FM-0053447 Bernardino Annex 36-A2 2 future roof leaks. \$ 3,558 \$ 3,401 95.58  306 FM-0053447 Bernardino Annex 36-A2 2 future roof leaks. \$ 3,558 \$ 3,401 95.58	202	FN4 00E2011			26 11	1		۲	4 602	۲	4 470	OF 64
the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing. 3 existing roof drains are leaking, work is needed to prevent additional roof leaks which where observed during recent torrential rains.  5,169 \$ 4,944 95.64    San   San   San Bernardino   San   San Bernardino   San   Courthouse   San Bernardino   San Bernardino   San   San Bernardino   San Bernardin	302	FIVI-0053011	Bernardino	Courthouse	30-A1	<u> </u>		<del>                                     </del>	4,082	) 	4,478	95.04
San San Bernardino Courthouse 36-A1 2 observed during recent torrential rains. \$ 5,169 \$ 4,944 95.64      FM-0053418   Bernardino   Bernardino   Bernardino   Courthouse   36-A1   2 observed during recent torrential rains. \$ 5,169 \$ 4,944 95.64												
303 FM-0053418 Bernardino Courthouse 36-A1 2 observed during recent torrential rains. \$ 5,169 \$ 4,944 95.64  Interior Finishes - Restore damaged concrete sub floor - Perform initial ACM testing, remove a 6' X 9' section of carpet over the affected area. Remove the failing concrete section of sub floor in the 6' X 9' area. Level concrete sub floor and install approximately 54SF of new carpet. All work  San Cucamonga  304 FM-0053422 Bernardino Courthouse 36-F1 2 table and is a trip hazard. \$ 5,817 \$ 5,817 \$ 5,817 \$ 100.00  Roof - Cut and reseal roof blisters. Seal multiple roof penetrations, fabricate and install (3) drain baskets, and install vent covers on 11 roof vents. This work is necessary in order to prevent  San Fontana HVAC - Install a new 1.5 ton split system that serves the 2nd floor A/V room. The current split			C	Cara Danas adlina								
Interior Finishes - Restore damaged concrete sub floor - Perform initial ACM testing, remove a 6'							, ·		- 400			a= a.
X 9' section of carpet over the affected area. Remove the failing concrete section of sub floor in the 6' X 9' area. Level concrete sub floor and install approximately 54SF of new carpet. All work to be performed after-hours. The damaged floor patch beneath the carpet is near the attorney's    San   Cucamonga   San Bernardino   San Bernardino   San Bernardino   Courthouse   San	303	FM-0053418	Bernardino	Courthouse	36-A1	2		\$	5,169	Ş	4,944	95.64
Rancho San Cucamonga Son Cucamonga Son Cucamonga Son Cucamonga Son Son Cucamonga Son												
San Cucamonga   to be performed after-hours. The damaged floor patch beneath the carpet is near the attorney's   5,817   5,817   100.00      FM-0053422   Bernardino   San Bernardino   San Bernardino   San Courthouse -   Bernardino   San Courthouse -   Bernardino   San Courthouse -   San Bernardino   Bernardino   San Courthouse -   San Bernardino   Bernardino   San Courthouse -   San Bernardino   San Courthouse -   San Bernardino   Bernardino   San Courthouse -   San San San Courthouse -   San												
304FM-0053422BernardinoCourthouse36-F12table and is a trip hazard.\$ 5,817\$ 5,817\$ 5,8178San Bernardino SanSanCourthouse - BernardinoCourthouse - AnnexRoof - Cut and reseal roof blisters. Seal multiple roof penetrations, fabricate and install (3) drain 				Rancho								
San Bernardino Courthouse - Bernardino Annex 36-A2 2 future roof leaks.  San Fontana Roof - Cut and reseal roof blisters. Seal multiple roof penetrations, fabricate and install (3) drain baskets, and install vent covers on 11 roof vents. This work is necessary in order to prevent \$ 3,558 \$ 3,401 95.58			San	Cucamonga			to be performed after-hours. The damaged floor patch beneath the carpet is near the attorney's					
San Courthouse - Bernardino Annex 36-A2 2 baskets, and install vent covers on 11 roof vents. This work is necessary in order to prevent \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	304	FM-0053422	Bernardino	Courthouse	36-F1	2	table and is a trip hazard.	\$	5,817	\$	5,817	100.00
305 FM-0053447BernardinoAnnex36-A22future roof leaks.SanFontanaHVAC - Install a new 1.5 ton split system that serves the 2nd floor A/V room. The current split43,558\$ 3,40195.58				San Bernardino			Roof - Cut and reseal roof blisters. Seal multiple roof penetrations, fabricate and install (3) drain					
San Fontana HVAC - Install a new 1.5 ton split system that serves the 2nd floor A/V room. The current split			San	Courthouse -			baskets, and install vent covers on 11 roof vents. This work is necessary in order to prevent					
	305	FM-0053447	Bernardino	Annex	36-A2	2	future roof leaks.	\$	3,558	\$	3,401	95.58
306 FM-0053452 Bernardino Courthouse 36-C1 2 system has failed, has a bad compressor as well as an un-repairable leak on the evaporator coil. \$ 7,241 \$ 7,241 100.00	1		San	Fontana			HVAC - Install a new 1.5 ton split system that serves the 2nd floor A/V room. The current split					
	306	FM-0053452	Bernardino	Courthouse	36-C1	2	system has failed, has a bad compressor as well as an un-repairable leak on the evaporator coil.	\$	7,241	\$	7,241	100.00

						COUNTY MANAGED - Grounds- Remove dead grass, trees, plants, and old landscape materials,	T				
						level mounds & holes in dirt area, and replace with gravel / dryscape to meet current city water					
			San Bernardino			restrictions. Existing area is currently a trip hazard due to the unevenness of the dirt & debris					
		San	Courthouse -			and also a fire hazard due to the dead landscape and dryness of the area as a result of missing					
307	FM-0053482	Bernardino	Annex	36-A2	2	irrigation.	\$	16,375	\$	16,375	100.00
						Roof - Leak remediation. Replace pipe seals, fabricate and install 12 drain screens, seal and coat					
						white (2) splits, install 360LF of walk pads around mechanical equipment, vents, and drains.					
		San	Fontana			Replace old asphalt repairs/coat with white coating at N&S wall tie-in, 80' tie-in, (3) vent					
308	FM-0053518	Bernardino	Courthouse	36-C1	2	flashings, and 3 pipe flashings.	\$	11,934	\$	9,921	83.13
						HVAC - Correct inadequate airflow resulting from additional heat load (staff and IT equipment)					
						following court reductions and realignment of resources. Tie into ductwork after existing VAV.					
						Install 35' of rigid 12" ductwork, 80' of flexible 12" ductwork, 25' of 10" flexible duct work, (1)					
						balancing damper, (1) new VAV box with Belimo actuator, and (1) thermostat. Provide and					
		San	San Bernardino			install power from existing 120V junction box and connect to transformer. Insulate all ductwork					
309	FM-0053558	Bernardino	Courthouse	36-A1	2	and support all rigid duct.	\$	16,634	\$	15,909	95.64
						Grounds and Parking Lot - Relocate (3) irrigation controllers (currently without power). Install (1)					
						new 24 zone controller to serve all zones and tie to JCC controlled electrical circuit. The existing					
						controllers are located in County managed areas and are powered by County circuits. Power has					
		San	Fontana			been disrupted for almost 4 weeks as a result of County work. The landscaping is currently dying					
310	FM-0054056	Bernardino	Courthouse	36-C1	2	and will result in significant replacement costs if the irrigation system is not restored soon.	\$	4,475	\$	3,720	83.13
						Flourator Flourator Domovetion Complete removetion of Nine (0) goodless traction alovators					
						Elevator - Elevator Renovation - Complete renovation of Nine (9) gearless traction elevators.					
						Work will include but not be limited to, car frames and platforms, buffers and safeties, hoist way					
						entrance frames, doors and pit equip., new AC gearless machines, micro-processor control					
						systems, regenerative VVVF AC drives, governors (elevators 1,2&3 only), closed loop heavy duty					
			Foot County			high speed operators, current code required wiring, interior and lobby control panels,					
211	FN4 0011033	Can Diago	East County	27.11	_	counterweights and roller guides (Elevators 7&9 only), hoist and governor ropes, cab ceilings	_ ا	2 404 200	ے ا	2 017 422	90 C2
311	FM-0011923	San Diego	Courthouse	37-I1	2	with LED down lights, rope compensation and seismic provisions.	+	3,494,260	<b>\</b>	2,817,422	80.63
1			County			Elevators, Escalators, & Hoists - Check encoder, Hoist motor brushes, tighten all I/O, Drive 23					
312	FM-0052821	San Diego	Courthouse	37-A1	1	faults. Change out card rack. Operational problems with elevator responding to service calls.	Ś	4,963	Ś	3,842	77.42
	000_0		North County	07.7.2		radicer ename each care radio experience problems must energe respension, green ename	+	.,555	+	3,6 .2	,,,,_
			Regional Center -			HVAC - Replace chilled water valve, and back flush evaporator coil. AHU S-11 is not producing					
313	FM-0052840	San Diego	Vista Center	37-F2	2	cool air. Court staff feels uncomfortable at times.	Ś	3,977	\$	2,674	67.24
						Elevators, Escalators, & Hoists - Elevator technician to adjust controller, drive and door	†	- 7 -	†	,-	
			County			operating equipment. This work will enhance the overall operation of both elevators. On going					
314	FM-0052850	San Diego	Courthouse	37-A1	2	issues with the operation of number seven and eight Judge's elevators.	\$	5,178	\$	5,178	100.00
			County			Elevators, Escalators, & Hoists - Refurbish escalators 1-2 and 2-1 to bring back into service by					
315	FM-0052858	San Diego	Courthouse	37-A1	2	replacing the worn step rollers.	\$	7,766	\$	6,012	77.42
			East County			Elevators, Escalators, & Hoists - Remove and replace the existing elevator hoist, the hoist is					
316	FM-0052872	San Diego	Regional Center	37-I1	2	worn and the elevator could become disabled due to current condition.	\$	14,791	\$	10,015	67.71
			South County			Interior Finishes - Repair and replace various area of carpet. Carpets are worn, torn, have snags					
317	FM-0052878	San Diego	Regional Center	37-H1	2	and is separating from concrete flooring. This is a trip hazard. (Jury Lounge, Public waiting)	\$	4,937	\$	1,769	35.84

						HVAC - Replace number one and two condensate return pumps. Waste make up water and					
			County			chemicals, cause excessive make up water for the boiler feed system. Condensate leaking all					
210	FM-0052951	San Diego	Courthouse	37-A1	1	over the floor, Safety hazard.	رخ	5,350	¢	4,142	77.42
310	1101-0032931	San Diego	Courtifouse	37-A1		over the hoor, safety hazard.	7	3,330	٦	4,142	77.42
						COUNTY MANAGED - Grounds - A condition assessment has shown that the underground					
210	FM-0052957	San Diego	Hall of Justice	37-A2	2	parking garage is in need of restriping. There are approximately 478 parking spaces to restripe.	ر	4,520	خ	1,819	40.24
319	1 101-0032937	San Diego	Trail Or Justice	37-AZ		COUNTY MANAGED - Fire Protection - The existing fire suppression system's post indicator valve	٦	4,320	٦	1,019	40.24
			South County			(PIV) is badly deteriorated and needs to be replaced along with the addition of a tamper switch					
220	FM-0052959	San Diego	Regional Center	37-H1	2	and replacement of fire main shut off valve and check valve.	ر	26,377	خ	26,377	100.00
320	1 101-0032333	San Diego	County	37-111		HVAC - Replace complete pump end. Boiler two feed pump is leaking from both ends, wasting	<del>ا</del> ک	20,377	٦	20,377	100.00
321	FM-0052965	San Diego	Courthouse	37-A1	2	chemicals. Number two boiler is the main boiler. and no back up feed pump.	رخ	4,944	¢	3,828	77.42
321	1 101-0032303	San Diego	Courtifouse	37-A1		Fire Protection - Fire Alarm System-system has code required upgrades based on State Fire	٧	4,344	٦	3,828	77.42
						Marshal Correction Notice. Install four (4) pull station installations; tie-in two (2) existing tamper					
						switches to Notifier panel; install two (2) enunciators (1 each) for Sheriff and Engineering office;					
			County			install two (2) new smoke detectors in lobby of North tower and two (2) horns / strobes in	'				
222	FM-0052995	San Diego	Courthouse	37-A1	2	holding areas.	رخ	29,049	¢	22,490	77.42
322	1 101-0032333	San Diego	North County	37-A1		Holding areas.	٦	23,043	٦	22,490	77.42
			Regional Center -			COUNTY MANAGED - Grounds - Gate Failure - Restore the failing motorized gate back to normal					
222	FM-0052996	San Diego	South	37-F1	2	operating standards.	ر	3,599	خ	3,599	100.00
323	FIVI-0032990	San Diego	East County	37-г1		HVAC - Replace Chiller #1 600 amp main breaker. Breaker supporting Chiller #1 is worn out and	٦	3,333	Ş	3,333	100.00
224	FM-0053012	San Diego	Regional Center	37-I1	1	not operational.	رخ	13,735	¢	9,300	67.71
324	1101-0033012	San Diego	East County	37-11		Elevators, Escalators, & Hoists - Removed worn out sheave bearings and installed new sheave	٧	13,733	٦	9,300	07.71
225	FM-0053021	San Diego	Regional Center	37-I1	1	bearings in place. Elevator is making too much noise and disrupting court.	رخ	14,748	¢	9,986	67.71
323	1101-0033021	Jan Diego	Regional Center	37-11		HVAC - Removed and replaced 15 HP Variable Frequency Drive and Variable Frequency Drive	7	14,740	7	3,380	07.71
326	FM-0053033	San Diego	Juvenile Court	37-E1	1	enclosure fan. AHU #1 not working and affecting depts. 6, 7 and 8.	رخ	5,428	¢	4,050	74.62
320	1 101-0033033	Jan Diego	Juvernie Court	37-L1		Plumbing - Replace failed Sloan Flushometer. Water remediation, set up containments, Extract	7	3,420	7	4,030	74.02
						water from carpets throughout affected area. Disinfect/deodorize area. Set multiple					
						dehumidifiers throughout chambers until dry. Test carpet/walls before final clean up and					
			County			returned furniture back in place. Flooding occurred throughout Judges' chambers 51 and 50 and					
327	FM-0053425	San Diego	Courthouse	37-A1	2	entering chambers' 38 restroom ceiling.	Ġ	12,164	¢	12,164	100.00
327	1101 0033423	Jan Diego	East County	37 AI		Elevators, Escalators, & Hoists - Remove existing generator, rewire and rebuild, install back into	7	12,104	7	12,104	100.00
328	FM-0053438	San Diego	Regional Center	37-I1	2	place. Elevator #3 generator needs to be rebuilt, stopped working.	ς .	13,131	ς	8,891	67.71
320	1101 0033 130	Jan Diego	Regional Center	37 11		place. Elevator no generator necas to be result, stopped working.	-	13,131	7	0,031	07.71
						Elevators, Escalators, & Hoists - Failing Motor Starter - Install new Solid State Starter, reducing					
329	FM-0053441	San Diego	Juvenile Court	37-E1	2	potential damaging high inrush current and starting torque. Motor starter is worn and failing.	ς .	4,337	\$	3,236	74.62
323	1101 0033441	San Diego	North County	37 LI		potential damaging right in astrono and starting torque. Wotor starter is worn and raining.	<del>                                     </del>	7,557	7	3,230	74.02
			Regional Center -								
			Department 34			Roof - Install fall protection/guardrail system in areas of fall risk. The rooftop air conditioners are					
330	FM-0053455	San Diego	Trailer	37-F4	2	too close to the edge of the roof. Roof requires fall protection rails.	Ġ	4,489	¢	4,489	100.00
330	1101 0033433	Jan Diego	North County	37 14		too close to the edge of the root. Noor requires fail protection rulis.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	7,703	7	7,703	100.00
			Regional Center -								
			Department 35			Roof - Install fall protection/guardrail system in areas of fall risk. The rooftop air conditioners are					
331	FM-0053457	San Diego	Trailer	37-F5	2	too close to the edge of the roof. Roof requires fall protection rails.	5	4,489	\$	4,489	100.00
771	111 0033437	Jan Diego	County	3, 13		Plumbing - Replace 20 section of failed cast iron pipe and a 10 section of copper pipe, fittings	+	7,703	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	7,703	100.00
337	FM-0053497	San Diego	Courthouse	37-A1	2	and bands.	\$	4,173	\$	3,231	77.42
332	111 0033437	Juli Diego	County	3, AI		HVAC - Replace Power Modular Equipment Controller (MEC). Units will not operate in	-	7,173	-	3,231	,,,,,
222	FM-0053503	San Diego	Courthouse	37-A1	1	automatic. Departments 4 and 5 temperature was too warm.	ج	8,753	ς .	6,777	77.42
223	INI -0022202	Jan Diego	Courtifouse	] J / -WI	1	Tautomane. Departments - and 5 temperature was too warm.	۲	0,733	۲ ا	0,111	11.42

						Electrical - Lights and Ballast - Remove and properly dispose of 15 burnt out lights and failed					
			County			ballast, and replace with new T-8 lights and ballast. Various lights are burned out in Department					
334	FM-0053525	San Diego	Courthouse	37-A1	2	28, Safety and trip hazard.	\$	6,232	\$	6,232	100.00
			North County			Holding Cell - Replace touch screen "in custody" door control monitor - The touch screen					
			Regional Center -			operation of the door monitoring system is not functioning/freezes. This prevents automatic					
335	FM-0053528	San Diego	Vista Center	37-F2	2	opening and closing of certain holding cell doors.	\$	10,349	\$	10,349	100.00
			Fact Carrets			LIVAC Bereit and realize a construction of the					
226	FN4 0052520	Can Diago	East County	27.14	_	HVAC - Remove and replace evaporator and condenser with new. Split unit in Civil Business	۲	F C12	۲	2 000	C7 71
336	FM-0053529	San Diego	Regional Center	37-I1	2	Office IT room non-functional. IT equipment could be damaged due to excessive heat in room.  Exterior Shell - Repair the exterior damaged grout of 4 existing carrot wood brick planters.	\$	5,612	\$	3,800	67.71
						Damaged or loose bricks on planters need to be repaired to prevent bodily injury, this is an					
337	FM-0053540	San Diego	Juvenile Court	37-E1	2	immediate safety risk.	\$	2,262	ς	1,688	74.62
337	1111 00333 10	Jan Diego	North County	3, 21		Fire Protection - Refurbish 5 Fire Doors, re-wire and re-string, tighten all loose mountings and	Υ	2,202	Υ	1,000	7 1.02
			Regional Center -			fasteners, lube all points of friction, balance and align doors. The fire curtains are not operating.					
338	FM-0053568	San Diego	Traffic Annex	37-F3	2	Curtains will not drop in a fire alarm event.	\$	4,699	\$	4,699	100.00
						HVAC - Secure HVAC vent with additional ceiling hangers and replace broken ceiling tiles in grid.					
						The ceiling air vent outside of D-5 in public corridor are loose and at risk of falling, this is a safety					
339	FM-0054049	San Diego	Juvenile Court	37-E1	2	concern.	\$	2,682	\$	2,001	74.62
			County			Exterior Shell - Elevator 4B replaced Power Supply Board, ran car and verified, tested okay.					
340	FM-0054050	San Diego	Courthouse	37-A1	1	Elevator not responding to call, stuck on 2nd floor, getting stuck on random floors.	\$	2,965	\$	2,296	77.42
			County			HVAC - Replace failing blower motor and place system back in service. Motor is failing and needs		2 42 4	_	2 424	100.00
341	FM-0054071	San Diego	Courthouse	37-A1	2	to be replaced before it fails. This units supplies D-24 and D-25.	Ş	3,434	\$	3,434	100.00
						Interior Finishes - Set up containment, ACM testing/clearance, replace drywall, and remount the					
			Koarny Mosa			light fixture. Suspended ceiling light fixture fell in northwest end of basement. A portion of the					
2/12	FM-0054092	San Diego	Kearny Mesa Traffic Court	37-C1	1	plaster from ceiling's hard lid broke loose, due to potential ACM disturbance a containment was set-up and environmental testing performed.	ċ	4,498	خ	4,498	100
342	1101-0034032	Jan Diego	Tranic Court	37-01		Elevators, Escalators, & Hoists - Replaced step roller wheels and tightened up guide plates.	٧	4,430	7	4,430	100
			County			Escalator 2-3 is thumping in operation, step roller wheels need replacement. Loose guide plates					
343	FM-0054117	San Diego	Courthouse	37-A1	2	are tearing up step rollers.	\$	2,252	\$	1,743	77.42
						HVAC - Replace condenser fan motors and blades, also installed new wires to motors for AHU	·	,		,	
			Kearny Mesa			#2. Tested and placed unit back in operation. HVAC #2 not providing cool air. Two condenser					
344	FM-0054198	San Diego	Traffic Court	37-C1	1	fans went out at the same time, need to replace.	\$	3,413	\$	3,413	100
						HVAC - Replace the upper section of the heating hot water (HHW) and chilled water (CHW) coils					
		San	Civic Center			on AHU #4, balance the supply fan (SF) on air handler (AHU) #3, increase the max CFM from 75%					
345	FM-0053948	Francisco	Courthouse	38-A1	2	to 100%, achieve duct static pressure from 1.13" to 1.5", and provide vibration analysis report.	\$	57,707	\$	57,707	100.00
						Cafaty, Install handrails along main ontry handisan ramp. Court systemore are surrently					
			Manteca Branch			Safety- Install handrails along main entry handicap ramp. Court customers are currently					
3/16	FM-0052936	San Joaquin		39-C1	2	stepping off high points at middle and end of upper ramp into flower beds. (this is a safety issue). Drop at mid-point is >24", Drop at end of upper ramp into flower bed is >12".	ċ	4,242	خ	4,242	100.00
340	1101-0032930	San Joaquin	Manteca Branch	33-01		Plumbing - Cut out all old solder fittings and failed fittings and replace with pro press fittings -	۲	4,242	٦	4,242	100.00
347	FM-0053462	San Joaquin		39-C1	2	Old fittings are failed and causing leaks throughout older section of courthouse.	Ś	10,706	Ś	10,706	100.00
	111 0000 102	23 23444111			_		T	_0,, 00	7		
						COUNTY MANAGED - Roofing - Remove existing multilayer roofing, including ACM substrate,					
						under Cooling Tower and Pumps; install 3 layer, urethane/glass mat fabric roofing system,					
						approx 900 Sq/Ft and apply masonry damp-proofing to existing stucco walls - Continuing roofing					
348	FM-0052815	San Mateo	Hall of Justice	41-A1	2	patches have failed to correct multiple location leaks resulting in Court operation disruptions.	\$	65,875	\$	65,875	100.00

			Municipal Court			HVAC - Replace Ten (10) failed hot water reheat coils, associated valves and piping at New Wing	T			
			Building -			side - Active and temporarily remediated leaks at (7) coils; (3) additional coils clogged and				
349	FM-0054074	San Mateo	Northern Branch	41-C1	2	inactive.	\$	88,703	\$ 73,810	83.21
						Roof - Installation of roof rail system for lower section (North) of Building G - safety concern for				
		Santa	Santa Maria			roof access to skylight and exhaust fans (1, 15 & 16). Parapet walls do not comply with OSHA				
350	FM-0052824	Barbara	Courts Building G	42-F5	2	requirements for safe access to the work space.	\$	9,775	\$ 9,432	96.49
			J			Exterior Shell - Reapply Water Sealant is required to maintain non-slip texture of footpath:				
						Clean, pressure wash, and tape off stain concrete areas. Re-stain and coat exterior stained				
		Santa	Santa Maria Clerks	;		concrete. Outside new construction warranty period. Heavy foot traffic causes concrete's water				
351	FM-0052832	Barbara	Building	42-F7	2	sealant to wear and create slipping hazard.	\$	8,326	\$ 8,326	100.00
1										
I						Plumbing - Water Intrusion and Microbial Remediation of Secured stairwell, men's and women's				
						public restroom and water membrane correction of North exterior wall - 3000 square feet of				
		Santa	Santa Maria			drywall replacement in secured stairwell, men's and women's public rest room damaged as a				
352	FM-0052984	Barbara	Courts Building G	42-F5	2	result of Water Intrusion caused by faulty water membrane on exterior of facility.	\$	16,171	\$ 15,603	96.49
			Santa Maria							
		Santa	Courts Building C			Plumbing - Replace ceiling in lobby of Building C due to Water Intrusion - SB County condenser				
353	FM-0053017	Barbara	+ D	42-F1	1	leak caused damage to 925 sq. ft. of ceiling in lobby adjacent to Dept. 4 entrance.	\$	14,128	\$ 7,728	54.70
						Plumbing - Replace failed main water line, pinhole leak capped, wall tile removed and replaced;				
		Santa	Lompoc Municipal			Restroom restored to pre-water intrusion conditions. Water leaking in wall between Men's and				
354	FM-0053036	Barbara	Court	42-D1	1	Women's public restroom.	\$	6,110	\$ 2,155	35.27
						Roof - Installation of copper angle to existing gutter, current system allows water to run off from				
		Santa	Santa Barbara			roof (open skylight design) onto the screening area. Gutters are unable to contain all run-off				
355	FM-0053038	Barbara	Figueroa Division	42-B1	2	causing water to leak onto Security Screening equipment.	\$	12,792	\$ 12,792	100.00
		Santa	Santa Maria			HVAC - Replace failing 8.5 Ton HVAC unit (PKU 11) - PKU servicing Department 7 Courtroom is				
356	FM-0053519	Barbara	Courts Building G	42-F5	2	failing and no longer functioning as designed.	\$	16,207	\$ 16,207	100.00
						Elevator - Restore elevator, replace seal and install to hydraulic system casing for elevator to				
		Santa	Santa Barbara Jury	<b>'</b>		function properly. Elevator has a seal that broke and detached from the casing of the hydraulic				
357	FM-0053523	Barbara	Assembly Bldg.	42-G1	2	system.	\$	2,636	\$ 2,636	100.00
						Plumbing - Remove material surrounding elbow joint in contained environment and area to be				
			Santa Maria			cleared per JCC/ABM protocol. Once cleared, replace leaking section of hot water pipe and				
		Santa	Courts Building C			restore area to pre-leak conditions. Leaking pipe in Depart. 2 Courtroom above jurors box to be				
358	FM-0053567	Barbara	+ D	42-F1	2	replaced. Questionable material wrapping elbow joint.	\$	10,946	\$ 10,946	100.00
			New Santa							
		Santa	Barbara Criminal			Grounds and Parking Lot - Parking Lots A, B & C - Install Safety Lighting - Safety/Security for				
359	FM-0054125	Barbara	Courthouse	42-M1	2	Court Staff in JCC-managed Parking Lots.	\$	4,000	\$ 4,000	100.00
						Exterior Shell - Replace 87 wood windows - Remove and replace 87 wood windows in the				
						historic courthouse. 50% of the windows have failed due to wear, termite damage and dry rot.				
						The remaining balance of the windows are starting to fail. The cost delta between 100%				
			Historic			replacement and 50% replacement is \$200k. Recommend 100% replacement as most cost				
360	FM-0020267	Santa Clara	Courthouse	43-B2	2	effective - long term solution.	\$	1,634,710	\$ 1,634,710	100.00
						Exterior Shell - Exterior windows at stairwells (120 ea) - Remove and replace the existing				
						interior and exterior failing window gasket seals. The existing vinyl seals will be replaced with a				
			Palo Alto			silicone based liquid sealant. Water is leaking into the building under heavy rains, Work will				
361	FM-0049249	Santa Clara	Courthouse	43-D1	2	require the use of high reach equipment, aerial lift and scaffolding.	\$	84,427	\$ 55,756	66.04

						HVAC - Restore Air Handler Unit 4 and nine (9) coils to manufacturers specifications - The					
						cooling to the building has not been sufficient and is affecting operations. Cutting through					
			Sunnyvale			existing ductwork is needed to gain access to the coils. Replace and Patch ductwork sheet metal.					
362	FM-0052835	Santa Clara		43-F1	2	HVAC will be shut down during the work over the weekend.	\$	14,239	\$	14,239	100.00
			Morgan Hill			Holding Cell - Replace (1) door window 25 1/4 x 7 1/2 x 1/2 Tempered laminate. Repair lock					
363	FM-0052869	Santa Clara	Courthouse	43-N1	2	operation to avoid lock outs.	\$	4,411	\$	4,411	100.00
			Morgan Hill		_	HVAC - Replace failed pump seal and bearing assembly to the leaking heating hot water pump					
364	FM-0052870	Santa Clara	Courthouse	43-N1	2	#1.	\$	3,136	\$	3,136	100.00
			Hall of Justice			Elevators, Escalators, & Hoists - Rebuild failed generator motor for elevator #2 - This is the only				20 - 20	
365	FM-0052938	Santa Clara	(West)	43-A2	1	public elevator in building and is not operational at this time.	\$	28,599	\$	28,599	100.00
266	EN 4 0052066	Carata Clara	Downtown	42 D4		Plumbing - Replace (1) Failed check valve and (1) failed cleanout in 4 inch sewer line in	_	7 740	_	7 742	400.00
366	FM-0052966	Santa Clara	Superior Court	43-B1	2	basement file room to eliminate leak.  Fire Protection - Code Compliance Issue - Replace failed internal parts (bolts and gaskets to (2)	\$	7,713	\$	7,713	100.00
			Hall of Justice			FDC 8" check valve - check valve deficiencies were found during the 5 year inspection located in					
267	FM-0052975	Santa Clara		12 11	2	the valve box - removal of the internal check parts are required to bring the fire system to code	خ	1 122	خ	4 422	100.00
307	FIVI-0032973	Santa Clara	(East)	43-A1		compliance.  Fire Protection - Replace failed 6" Fire main grooved coupling - Shutdown fire system and drain -	Ş	4,423	Ş	4,423	100.00
						remove steel ceiling panels in in-custody transfer tunnel to access failed fire main coupling -					
						disassemble and remove failed coupling and piping - install approx. 8' of new 6" piping with 2					
			Hall of Justice			new 6" Victaulic couplings - re-charge fire system and leak test - re-install steel ceiling panels -					
368	FM-0053026	Santa Clara	(East)	43-A1	2	clean and remove debris from site.	¢	8,659	¢	8,659	100.00
300	1101-0033020	Janta Ciara	Downtown	43-VI		clean and remove debris from site.	7	8,033	7	0,033	100.00
369	FM-0053428	Santa Clara	Superior Court	43-B1	2	Vandalism - Replace 7x 3 shattered safety laminated glass at public entry.	\$	1,571	ς	1,571	100.00
303	1111 0033 120		Downtown	13 51		Plumbing - Replace (1) failed ejector pump motor and check valves. Pump is overflowing and	7	1,371	<b>Υ</b>	1,371	100.00
370	FM-0053440	Santa Clara	Superior Court	43-B1	2	flooding the basement area.	Ś	8,106	Ś	8,106	100.00
			Ca.po. : Ca.   C		_	Roof - Replace 22,000 sq. ft of deteriorated roof, coping metal (1000 sq ft), Gravel stops (250 sq	T		T	5,255	
			Palo Alto			ft), Surface mount (450 sq ft) and deteriorated over flow drains. The roof is showing signs of					
371	FM-0053442	Santa Clara	Courthouse	43-D1		cracking and ponding. Roof leaks are evident in the building.	\$	824,415	\$	544,444	66.04
						HVAC - Replace failed re-heat coils (13), valve train from isolation valve to VAV's including pipe,		<u> </u>		,	
						strainers, belimo valve, temp sensors and thermostats - Re-heat coils failing due to corrosion					
						from service without dialectic pipe connections; issue discovered during isolation valve					
372	FM-0052863	Santa Cruz	Main Courthouse	44-A1	2	replacement modification.	\$	60,503	\$	59,965	99.11
			Jury Assembly			Pest Control - Full building termite fumigation, tenting required - termites found in several					
373	FM-0053417	Santa Cruz	Room	44-A3	2	locations causing structural damage.	\$	7,105	\$	7,105	100.00
						Electrical - Storm water and sewage discharge pumps - Replace four (4) 480 volt 7.5 horsepower					
						pumps with four (4) 200 volt 7.5 pumps and two (2) 480 volt 5 horsepower pumps with two (2)					
						200 volt 5 horsepower pumps, so their motor voltage matches the emergency generator output					
						voltage - connect the new pumps to the emergency power panel so they function during a					
374	FM-0051922	Solano	Hall of Justice	48-A1	2	power outage.	\$	258,000	\$	187,876	72.82
			Solano Justice			Interior finishes - Replace failed fire shutter at transaction window number seven in the criminal					
375	FM-0052814	Solano	Building	48-B1	2	division. Code Required.	\$	13,505	\$	13,505	100.00
						Fire Alarm System - Correct deficiencies found while performing a level IV PM - Replace failed					
376	FM-0052862	Solano	Hall of Justice	48-A1	2	duct detector, LED enunciator, and horn strobe.	\$	3,054	\$	2,224	72.82
377	EN 4 0052072	Calar	Hall at the second	40.44		Electrical - Sump pump - Install electrical feed from emergency panel so the pump functions	_	4 4 2 2	_ ا	2 202	72.00
3//	FM-0052873	Solano	Hall of Justice	48-A1	2	during a power outage.	\$	4,123	<b>&gt;</b>	3,002	72.82
270	ENA 0052420	Colons	Solano Justice	40 D4	_	HVAC - Replace failed two ton split air-conditioning unit that cools Court IT (MDF) room 118 -	۲	14050	۲	14.050	100.00
3/8	FM-0053439	Solano	Building	48-B1	2	Work to be performed afterhours.	\$	14,950	<b>\</b>	14,950	100.00

					Electrical - Replace failed secure door lock control relay - Remove and replace control panel for			
					the secure door lock entering the secured stairwell, the relay has failed and cannot be replaced			
					without replacing the control panel all together. The door is currently in the "Fail Open"			
379 FM-0053950	Solano	Hall of Justice	48-A1	2	position. Work to be performed after hours with escort.	\$ 6,729	\$ 6,729	100.00
					COUNTY MANAGED - Elevators Renovation - Renovate South Common Area - Single elevator in			
380 FM-0046916	Sonoma	Hall of Justice	49-A1	2	south lobby is beyond useful life.	\$ 156,741	\$ 156,741	100.00
		Modesto Main						
381 FM-0053435	Stanislaus	Courthouse	50-A1	1	HVAC - Replace supply and return fan VFD and Chiller #1 upgrades to Circuit A.	\$ 50,000	\$ 38,910	77.82
					HVAC - Replace Failed Mini-split unit for Tech Print Room. Existing condenser unit has failed			
					beyond repair. Replacement parts not feasible and replacement condensing unit not available			
382 FM-0053456	Stanislaus	Hall of Records	50-A2	2	with R-22 refrigerant (replacement is required).	\$ 8,154	\$ 8,154	100.00
		Modesto Main			Plumbing - Replace failed hot water heater for main courthouse. Main tank is cracked and			
383 FM-0053458	Stanislaus	Courthouse	50-A1	2	unable to be repaired.	\$ 5,310	\$ 4,132	77.82
					Safety - Carpet: Remove knock down strips - re-stretch carpeting in courtrooms 1 and 2 and			
		Modesto Main			replace knockdown with rubber molding - The carpet is bunching up causing a potential trip			
384 FM-0054075	Stanislaus	Courthouse	50-A1	2	hazard.	\$ 3,276	\$ 3,276	100.00
					Fire Protection - Replace four fire sprinkler heads (two corroded fire sprinkler heads, two			
					painted fire sprinkler heads), replace the drain valve with an approved valve, and relocation of			
385 FM-0053548	Tehama	Annex No. 2	52-A3	2	the gauges on the riser to an approved location - Annual FMS PM failed.	\$ 3,152	\$ 3,152	100.00
					Fire Protection - Remove and replace fire alarm panel with failing communicator. The failing			
386 FM-0053013	Yolo	Traffic Court	57-A3	2	communicator is causing a loss of communication with fire alarm monitoring company.	\$ 3,055	\$ 3,055	100.00

\$ 27,066,997 \$ 23,396,856

ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	ESTIMATED CURRENT YEAR COSTS (Includes existing costs prior to CFR term)	ESTIMATED BUDGET YEAR COSTS	TOTAL ESTIMATED CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
1	11-CFR003	Glenn	11-C1	Resource Center	Lease	One- Time	(Utility costs are court funded) Lease extension from 5/1/2015-12/31/2016. The leased space houses the Family Court Facilitator, FCS Mediator, Self Help Center and court records storage. This request is considered urgent because this space is needed until the new courthouse is completed, estimated completion date is 10/31/16.  Electrical upgrades at El Monte Courthouse and Stanley Mosk	7 Months	CCF for Lease Costs, Operating Budget for Utility Costs	\$ 74,666	\$ 77,105	\$ 129,533	No Concerns
2	19-CFR024	Los Angeles	Multiple	Multiple	FM	One- Time	Courthouse. These upgrades are deemed urgent because they are needed to support the new case management system.	NA	Operating Budget	\$ 225,000	\$ -	\$ 225,000	No Concerns
3		San Joaquin	39-C1	Manteca Branch Court	FM	One- Time	The existing T1 & DSL line is not sufficient for the new Court's case management system that is currently in the implementation stage. This project will increase bandwidth capactiy from 1.5 MBS to 20 MBS, significantly improving computing capacity and faster computing response times. This request is deemed urgent because the new case management system requires this additional bandwidth. This project will also reduce the Court's monthly services cost from \$940 per month to \$250 per month.	NA	Operating Budget	\$ 9,156	\$ -	\$ 9,156	No Concerns